



Aviation Investigation Final Report

Location: Mint Hill, North Carolina Accident Number: GAA18CA306

Date & Time: May 27, 2018, 13:30 Local Registration: N582DF

Aircraft: LITE FLIGHT DRAGONFLY Aircraft Damage: Substantial

Defining Event: Aerodynamic stall/spin **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, while maneuvering about 1,300 ft mean sea level (about 600 ft above the ground), he initiated a 180° right turn, and about halfway through the turn, the airplane began to descend rapidly and would not respond to flight controls. The airplane struck a tree, spun to the right, and came to rest on a residential house.

Postaccident examination conducted by the pilot revealed that all controls were intact and operational.

The airplane sustained substantial damage to the fuselage, empennage, and both wings.

In a written statement provided to the local police department, the pilot reported that he lost control of the airplane, and it "spiraled down" and then struck a tree and a house.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Given the pilot's statement, it is likely that the airplane entered an aerodynamic stall/spin when the pilot exceeded the airplane's critical angle of attack during a turn.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's exceedance of the airplane's critical angle of attack during a turn, which resulted in an aerodynamic stall/spin.

Findings

Aircraft Angle of attack - Capability exceeded

Personnel issues Aircraft control - Pilot

Environmental issues Tree(s) - Contributed to outcome

Page 2 of 5 GAA18CA306

Factual Information

History of Flight

Maneuvering	Aerodynamic stall/spin (Defining event)
Maneuvering	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Sport Pilot	Age:	60,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Sport pilot Unknown	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	LITE FLIGHT	Registration:	N582DF
Model/Series:	DRAGONFLY NO SERIES	Aircraft Category:	Airplane
Year of Manufacture:	2006	Amateur Built:	
Airworthiness Certificate:	Experimental (Special)	Serial Number:	82
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	September 15, 2017 Condition	Certified Max Gross Wt.:	992 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	730 Hrs at time of accident	Engine Manufacturer:	ROTAX
ELT:	C91A installed, not activated	Engine Model/Series:	582UL
Registered Owner:		Rated Power:	65 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA306

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KEQY,679 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	16:53 Local	Direction from Accident Site:	184°
Lowest Cloud Condition:	Scattered / 3300 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.01 inches Hg	Temperature/Dew Point:	27°C / 20°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Indian Trail, NC (28A)	Type of Flight Plan Filed:	None
Destination:	Indian Trail, NC (28A)	Type of Clearance:	None
Departure Time:	13:00 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	35.184722,-80.606941(est)

Administrative Information

Investigator In Charge (IIC):	Benhoff, Kathryn
Additional Participating Persons:	Paul Meyer; FAA; Charlotte, NC
Original Publish Date:	November 5, 2018
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=97345

Page 4 of 5 GAA18CA306

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA306