



# **Aviation Investigation Final Report**

Location: Borger, Texas Accident Number: GAA17CA144

Date & Time: February 17, 2017, 18:00 Local Registration: N591P

Aircraft: PITTS SPECIAL S 1C Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that, during the takeoff as the tailwheel lifted, the biplane veered "hard right" and exited the runway. He added that he "felt" he had enough speed to fly and attempted to lift off. Subsequently, the biplane struck a tree.

The biplane sustained substantial damage to the fuselage and both wings.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the biplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control of the biplane during takeoff.

#### **Findings**

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Tree(s) - Contributed to outcome

Page 2 of 5 GAA17CA144

## **Factual Information**

## History of Flight

Takeoff	Loss of control on ground (Defining event)
Takeoff	Runway excursion
Takeoff	Collision with terr/obj (non-CFIT)
Takeoff	Nose over/nose down

### **Pilot Information**

Certificate:	Private	Age:	53,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Single
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	July 1, 2015
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 4, 2016
Flight Time:	(Estimated) 967.4 hours (Total, all aircraft), 30 hours (Total, this make and model), 877.7 hours (Pilot In Command, all aircraft), 4.4 hours (Last 90 days, all aircraft), 3.4 hours (Last 30 days, all aircraft), 0.5 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA17CA144

## Aircraft and Owner/Operator Information

PITTS SPECIAL	Registration:	N591P
S 1C NO SERIES	Aircraft Category:	Airplane
1967	Amateur Built:	
Unknown	Serial Number:	CP-1
Tailwheel	Seats:	1
Unknown	Certified Max Gross Wt.:	
	Engines:	1 Reciprocating
	Engine Manufacturer:	Lycoming
Not installed	Engine Model/Series:	0-360
	Rated Power:	180
On file	Operating Certificate(s) Held:	None
	S 1C NO SERIES  1967  Unknown  Tailwheel  Unknown  Not installed	S 1C NO SERIES  Aircraft Category:  1967  Amateur Built:  Unknown  Serial Number:  Tailwheel  Seats:  Unknown  Certified Max Gross Wt.:  Engines:  Engine Manufacturer:  Not installed  Engine Model/Series:  Rated Power:  On file  Operating Certificate(s)

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KBGD,3054 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	23:51 Local	Direction from Accident Site:	188°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.63 inches Hg	Temperature/Dew Point:	19°C / 0°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Borger, TX (BGD )	Type of Flight Plan Filed:	None
Destination:	Borger, TX (BGD )	Type of Clearance:	None
Departure Time:	18:00 Local	Type of Airspace:	Class G

Page 4 of 5 GAA17CA144

#### **Airport Information**

Airport:	HUTCHINSON COUNTY BGD	Runway Surface Type:	Asphalt
Airport Elevation:	3055 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	6299 ft / 100 ft	VFR Approach/Landing:	None

#### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	35.7,-101.394165(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Albert Hilliard; FAA; Lubbock, TX
Original Publish Date:	April 10, 2017
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=94732

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA17CA144