



Aviation Investigation Final Report

Location: Ontario, Oregon Accident Number: GAA18CA176

Date & Time: March 18, 2018, 14:30 Local Registration: N234RA

Aircraft: AMERICAN CHAMPION AIRCRAFT 7GCBC Aircraft Damage: Substantial

Defining Event: Abnormal runway contact **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor reported that, during the last landing of the day, which he performed in crosswind conditions, the tailwheel-equipped airplane bounced. He added that during the bounce, the airplane rolled right, and the right main landing gear touched down. Subsequently, once both main landing gear were on the runway the airplane veered sharply to the right and he lost directional control. The airplane exited the right side of the runway, the right main landing gear spindle and tire separated from the airplane, and the airplane came to rest.

The airplane sustained substantial damage to the front spar.

The flight instructor reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The automated weather observation system located at the accident airport reported, about the time of the accident, the wind was from 210° at 8 knots. The flight instructor landed on runway 33.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The flight instructor's failure to maintain directional control during landing, in cross wind conditions.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Instructor/check pilot

Environmental issues Crosswind - Effect on operation

Page 2 of 5 GAA18CA176

Factual Information

History of Flight

Landing-flare/touchdown	Abnormal runway contact (Defining event)	
Landing-landing roll	Loss of control on ground	
Landing-landing roll	Runway excursion	
Landing-landing roll	Part(s) separation from AC	

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	75,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	BasicMed	Last FAA Medical Exam:	August 7, 2017
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 8, 2017
Flight Time:	(Estimated) 3532 hours (Total, all aircraft), 18 hours (Total, this make and model), 3378 hours (Pilot In Command, all aircraft), 20 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Student pilot Information

Certificate:	Student	Age:	46,Female
Airplane Rating(s):	None	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	February 20, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 22 hours (Total, all aircraft), 9 hours (Total, this make and model), 9 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA18CA176

Aircraft and Owner/Operator Information

Aircraft Make:	AMERICAN CHAMPION AIRCRAFT	Registration:	N234RA
Model/Series:	7GCBC NO SERIES	Aircraft Category:	Airplane
Year of Manufacture:	2003	Amateur Built:	
Airworthiness Certificate:	Aerobatic; Normal	Serial Number:	1351-2003
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	November 30, 2017 Annual	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	680 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C91A installed, not activated	Engine Model/Series:	O-320-B2B
Registered Owner:		Rated Power:	160 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KONO,2193 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	20:53 Local	Direction from Accident Site:	140°
Lowest Cloud Condition:	Scattered / 5500 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.11 inches Hg	Temperature/Dew Point:	11°C / -3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Ontario, OR (ONO)	Type of Flight Plan Filed:	None
Destination:	Ontario, OR (ONO)	Type of Clearance:	VFR
Departure Time:	13:30 Local	Type of Airspace:	Class G

Page 4 of 5 GAA18CA176

Airport Information

Airport:	ONTARIO MUNI ONO	Runway Surface Type:	Asphalt
Airport Elevation:	2193 ft msl	Runway Surface Condition:	Dry
Runway Used:	33	IFR Approach:	None
Runway Length/Width:	5006 ft / 100 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	44.022499,-117.014724(est)

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Gregory Horrell; FAA; Boise, ID
Original Publish Date:	July 5, 2018
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=96922

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA176