



# **Aviation Investigation Final Report**

Location: Harrisonville, Missouri Accident Number: CEN17LA217

Date & Time: June 8, 2017, 09:00 Local Registration: N3082T

Aircraft: Piper PA 28-235 Aircraft Damage: Minor

**Defining Event:** AC/prop/rotor contact w person **Injuries:** 1 Serious, 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

When the private pilot taxied the airplane to park, he was taxiing past his friend, who was using a camera to record the airplane. The pilot felt a thump and could not see his friend, so he turned the airplane around and saw his friend lying on the ground. The friend sustained serious injuries. The airplane sustained damage to the left wingtip. Weather at the time of the accident was a clear sky with no restrictions to visibility.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain a safe distance between the airplane and a person on the ground, which resulted in serious injuries to the person.

### **Findings**

 Personnel issues
 Decision making/judgment - Other

 Personnel issues
 Monitoring other person - Pilot

 Environmental issues
 Person - Awareness of condition

#### **Factual Information**

#### **History of Flight**

**Taxi** AC/prop/rotor contact w person (Defining event)

On June 8, 2017, about 0900 central daylight time, a Piper PA-28-235 airplane, N3082T, struck a person while taxiing at a private airstrip near Harrisonville, Missouri. The private pilot was not injured, and a pilot-rated pedestrian was seriously injured. The airplane was registered to and operated by a private individual under the provisions of 14 Code of Federal Regulations Part 91 as a personal flight. Visual meteorological conditions prevailed for the flight, which operated without a flight plan. The flight originated from the Lawrence Smith Memorial Airport (KLRY), Harrisonville, Missouri, and the airplane landed on a private airstrip about 4 miles southwest of KLRY.

According to information obtained by the responding Federal Aviation Administration inspector and sheriff's deputy, when the pilot taxied the airplane to park, he was taxiing past his friend (the pilot-rated pedestrian) who was using a camera to record the airplane. He felt a thump and could not see his friend, so he turned the airplane around and saw his friend laying on the ground. The friend was transported to the hospital. The airplane had damage to the left wingtip.

An automated weather reporting facility near the accident site reported a clear sky with no restrictions to visibility.

An NTSB Form 6120 was not submitted by the pilot.

#### **Pilot Information**

Certificate:	Private	Age:	55,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	July 1, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Page 2 of 4 CEN17LA217

# Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N3082T
Model/Series:	PA 28-235 235	Aircraft Category:	Airplane
Year of Manufacture:	1972	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	28-7310002
Landing Gear Type:	Tricycle	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:		Engine Model/Series:	0-540 SERIES
Registered Owner:		Rated Power:	250 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KLRY,915 ft msl	Distance from Accident Site:	5 Nautical Miles
Observation Time:	08:55 Local	Direction from Accident Site:	40°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.1 inches Hg	Temperature/Dew Point:	22°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	HARRISONVILLE, MO (LRY )	Type of Flight Plan Filed:	None
Destination:	Harrisonville, MO	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Page 3 of 4 CEN17LA217

#### **Airport Information**

Airport: Private Airstrip Priv Runway Surface Type:

Airport Elevation:915 ft mslRunway Surface Condition:UnknownRunway Used:IFR Approach:NoneRunway Length/Width:VFR Approach/Landing:Full stop

### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Minor
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	1 Serious	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 None	Latitude, Longitude:	38.550277,-94.406112(est)

#### **Administrative Information**

Investigator In Charge (IIC): Aguilera, Jason

Additional Participating Persons: David Wood; FAA; Kansas City, MO

Original Publish Date: June 5, 2018

**Note:** The NTSB did not travel to the scene of this accident.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=95330">https://data.ntsb.gov/Docket?ProjectID=95330</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 4 of 4 CEN17LA217