



Aviation Investigation Final Report

Location: Sedona, Arizona Accident Number: GAA16CA461

Date & Time: August 30, 2016, 11:02 Local Registration: N114LC

Aircraft: AMERICAN LEGEND AIRCRAFT CO AIrcraft Damage: Substantial

Defining Event: Abnormal runway contact **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

According to the pilot of the tailwheel-equipped airplane, during approach for landing the airplane encountered "slight" turbulence, but the wind was reported as calm. He further reported that there were building cumulus clouds in the area. The pilot reported that about 4 feet above the ground, the airplane encountered wind gusts from left to right, so he added power and right rudder. He reported that the airplane landed on the left main landing gear, immediately veered left, exited the left side of the runway and impacted a drainage culvert. The airplane sustained substantial damage to the fuselage frame and right wing ribs.

The pilot reported that there were no mechanical malfunctions or anomalies with any portion of the airplane during the flight that would have prevented normal flight operations.

As a recommendation the pilot reported that he should have gone around at the first indication of turbulence and tested the conditions further. He wrote that had the conditions worsened he would have departed the area for a suitable airport.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing in gusting wind conditions, which resulted in a runway excursion.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Gusts - Effect on equipment

Environmental issues Gusts - Ability to respond/compensate

Environmental issues (general) - Contributed to outcome

Page 2 of 5 GAA16CA461

Factual Information

History of Flight

Landing	Turbulence encounter
Landing-flare/touchdown	Abnormal runway contact (Defining event)
Landing-flare/touchdown	Loss of control on ground
Landing-landing roll	Runway excursion
Landing-landing roll	Landing gear collapse
Landing-landing roll	Collision with terr/obj (non-CFIT)

Pilot Information

Private	Age:	70,Male
Single-engine land	Seat Occupied:	Front
None	Restraint Used:	4-point
None	Second Pilot Present:	No
None	Toxicology Performed:	No
Class 3 With waivers/limitations	Last FAA Medical Exam:	August 29, 2016
No	Last Flight Review or Equivalent:	November 15, 2015
(Estimated) 407.7 hours (Total, all aircraft), 51 hours (Total, this make and model), 382.7 hours (Pilot In Command, all aircraft), 6.4 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		
	Single-engine land None None Class 3 With waivers/limitations No (Estimated) 407.7 hours (Total, all air (Pilot In Command, all aircraft), 6.4 hours	Single-engine land None Restraint Used: None Second Pilot Present: None Toxicology Performed: Class 3 With waivers/limitations Last FAA Medical Exam: No Last Flight Review or Equivalent: (Estimated) 407.7 hours (Total, all aircraft), 51 hours (Total, this make and a (Pilot In Command, all aircraft), 6.4 hours (Last 90 days, all aircraft), 3 hours

Page 3 of 5 GAA16CA461

Aircraft and Owner/Operator Information

Aircraft Make:	AMERICAN LEGEND AIRCRAFT CO	Registration:	N114LC
Model/Series:	AL3 UNDESIGNAT	Aircraft Category:	Airplane
Year of Manufacture:	2008	Amateur Built:	
Airworthiness Certificate:	Special light-sport (Special)	Serial Number:	AL-1140
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	December 12, 2015 Annual	Certified Max Gross Wt.:	1320 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	362.8 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-200/A48
Registered Owner:		Rated Power:	100 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSEZ,4827 ft msl	Distance from Accident Site:	74 Nautical Miles
Observation Time:	17:55 Local	Direction from Accident Site:	5°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.21 inches Hg	Temperature/Dew Point:	29°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Prescott, AZ (PRC)	Type of Flight Plan Filed:	None
Destination:	Sedona, AZ (SEZ)	Type of Clearance:	None
Departure Time:	10:15 Local	Type of Airspace:	Class G

Page 4 of 5 GAA16CA461

Airport Information

Airport:	SEDONA SEZ	Runway Surface Type:	Asphalt
Airport Elevation:	4830 ft msl	Runway Surface Condition:	Dry
Runway Used:	03	IFR Approach:	None
Runway Length/Width:	5132 ft / 100 ft	VFR Approach/Landing:	Full stop:Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.509166,-111.473052(est)

Administrative Information

Investigator In Charge (IIC):	Hicks, Michael
Additional Participating Persons:	Craig Tompkins; FAA; Scottsdale, AZ
Original Publish Date:	January 18, 2017
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=93936

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA16CA461