



# **Aviation Investigation Final Report**

Location: Little Rock, Arkansas Accident Number: GAA18CA252

Date & Time: April 30, 2018, 16:00 Local Registration: N550K

Aircraft: Beech 95B55 Aircraft Damage: Substantial

**Defining Event:** Abnormal runway contact **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot in the multi-engine airplane reported that, during landing, the right propeller struck the runway and that the cabin door came open. The pilot taxied the airplane to the ramp when he discovered the right propeller damage.

The airplane sustained substantial damage to the fuselage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper landing flare.

#### **Findings**

Aircraft Landing flare - Not attained/maintained

Personnel issues Aircraft control - Pilot

## **Factual Information**

## **History of Flight**

Landing	Abnormal runway contact (Defining event)	
Landing	Hard landing	

### **Pilot Information**

Certificate:	Private	Age:	69,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	December 12, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 3, 2016
Flight Time:			

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Beech	Registration:	N550K
Model/Series:	95B55 UNDESIGNAT	Aircraft Category:	Airplane
Year of Manufacture:	1978	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	TC-2180
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	May 8, 2017 Annual	Certified Max Gross Wt.:	5100 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	2677.1 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	C91 installed, not activated	Engine Model/Series:	IO-470L
Registered Owner:		Rated Power:	260 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 2 of 4 GAA18CA252

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KLIT,257 ft msl	Distance from Accident Site:	6 Nautical Miles
Observation Time:	20:53 Local	Direction from Accident Site:	172°
<b>Lowest Cloud Condition:</b>	Few / 5500 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	120°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.1 inches Hg	Temperature/Dew Point:	26°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Little Rock, AR (ORK )	Type of Flight Plan Filed:	None
Destination:	Little Rock, AR (ORK )	Type of Clearance:	None
Departure Time:	15:30 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	NORTH LITTLE ROCK MUNI ORK	Runway Surface Type:	Concrete
Airport Elevation:	545 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	05	IFR Approach:	None
Runway Length/Width:	5002 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.830276,-92.256111(est)

Page 3 of 4 GAA18CA252

#### **Administrative Information**

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: Shane Benedetto; FAA; Little Rock, AR

Original Publish Date: September 10, 2018

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=97168">https://data.ntsb.gov/Docket?ProjectID=97168</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 4 of 4 GAA18CA252