



Aviation Investigation Final Report

Location: IMMOKALEE, Florida Accident Number: GAA19CA092

Date & Time: November 5, 2018, 17:45 Local Registration: N9225G

Aircraft: Maule MX7 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The flight instructor reported that, while administering a flight review, he took the flight controls to demonstrate a full-stall landing. During the landing roll, the airplane exited the right side of the runway. He increased power to abort the landing, and the left horizontal stabilizer struck a runway sign. He continued the climb the airplane and flew one pattern and landed. The airplane sustained substantial damage to the left horizontal stabilizer and the rudder. The instructor reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The flight instructor's failure to maintain directional control during the landing roll, which resulted in a runway excursion and a collision with runway signage during the subsequent attempted aborted landing.

Findings

Personnel issues Aircraft control - Instructor/check pilot

Aircraft Directional control - Not attained/maintained

Environmental issues Sign/marker - Effect on operation

Page 2 of 5 GAA19CA092

Factual Information

History of Flight

Landing	Loss of control on ground (Defining event)	
Landing	Collision with terr/obj (non-CFIT)	

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	74,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Glider	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 3 None	Last FAA Medical Exam:	May 8, 2017
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	November 14, 2017
Flight Time:	(Estimated) 5039 hours (Total, all aircraft), 68 hours (Total, this make and model), 4976 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Airline transport; Commercial; Flight engineer; Flight instructor	Age:	70,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	April 20, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 3, 2016
Flight Time:	(Estimated) 8164 hours (Total, all aircraft), 32 hours (Total, this make and model), 2865 hours (Pilot In Command, all aircraft), 21 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA19CA092

Aircraft and Owner/Operator Information

N9225G
Airplane
20001C
4
.: 2400 lbs
1 Reciprocating
Lycoming
0-360-C4F
180 Horsepower
None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	IMM,37 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	22:15 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	30°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	IMMOKALEE, FL (IMM)	Type of Flight Plan Filed:	None
Destination:	IMMOKALEE, FL (IMM)	Type of Clearance:	None
Departure Time:	17:45 Local	Type of Airspace:	Class G

Page 4 of 5 GAA19CA092

Airport Information

Airport:	IMMOKALEE RGNL IMM	Runway Surface Type:	Asphalt
Airport Elevation:	37 ft msl	Runway Surface Condition:	Dry
Runway Used:	09	IFR Approach:	None
Runway Length/Width:	5000 ft / 100 ft	VFR Approach/Landing:	Touch and go;Traffic

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	26.43361,-81.400558(est)

Administrative Information

Investigator In Charge (IIC):	Hicks, Michael
Additional Participating Persons:	Roberto Rodriguez; FAA; Miramar, FL
Original Publish Date:	March 17, 2020
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98755

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA19CA092