



Aviation Investigation Final Report

Location: Van Nuys, California Accident Number: GAA17CA413

Date & Time: June 15, 2017, 11:00 Local Registration: N2537F

Aircraft: Champion 7ECA Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation

Analysis

The pilot of the tailwheel-equipped airplane reported that, during the landing roll, the airplane drifted to the right and he corrected with rudder but then the airplane "started to pull" to the left. He added that his "rudder input failed to stop the plane from continuing to the left," the airplane ground looped to the left, and the right wingtip hit the ground.

The airplane sustained substantial damage to the right wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing roll.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Page 2 of 5 GAA17CA413

Factual Information

History of Flight

| Landing-landing roll | Loss of control on ground (Defining event) | |
|----------------------|--|--|
|----------------------|--|--|

Pilot Information

| Certificate: | Commercial | Age: | 42,Male |
|---------------------------|--|-----------------------------------|-------------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Front |
| Other Aircraft Rating(s): | None | Restraint Used: | Unknown |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 2 With waivers/limitations | Last FAA Medical Exam: | February 27, 2017 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | January 27, 2017 |
| Flight Time: | (Estimated) 600 hours (Total, all aircraft), 14 hours (Total, this make and model), 540 hours (Pilot In Command, all aircraft), 70 hours (Last 90 days, all aircraft), 25 hours (Last 30 days, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | Champion | Registration: | N2537F |
|-------------------------------|----------------|-----------------------------------|-----------------|
| Model/Series: | 7ECA NO SERIES | Aircraft Category: | Airplane |
| Year of Manufacture: | 1965 | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 159 |
| Landing Gear Type: | Tailwheel | Seats: | 2 |
| Date/Type of Last Inspection: | Unknown | Certified Max Gross Wt.: | 1320 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | CONT MOTOR |
| ELT: | Installed | Engine Model/Series: | 0-200 SERIES |
| Registered Owner: | | Rated Power: | 100 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |
| | | | |

Page 3 of 5 GAA17CA413

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|-----------------------------|---|------------------|
| Observation Facility, Elevation: | KVNY,770 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 17:51 Local | Direction from Accident Site: | 147° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | / | Turbulence Type Forecast/Actual: | / None |
| Wind Direction: | | Turbulence Severity Forecast/Actual: | / N/A |
| Altimeter Setting: | 29.92 inches Hg | Temperature/Dew Point: | 29°C / 8°C |
| Precipitation and Obscuration: | No Obscuration; No Precipit | ation | |
| Departure Point: | CARLSBAD, CA (CRQ) | Type of Flight Plan Filed: | None |
| Destination: | Van Nuys, CA (VNY) | Type of Clearance: | Unknown |
| Departure Time: | 09:00 Local | Type of Airspace: | Class D |
| | | | |

Airport Information

| Airport: | VAN NUYS VNY | Runway Surface Type: | Asphalt |
|----------------------|------------------|----------------------------------|-----------|
| Airport Elevation: | 802 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 16R | IFR Approach: | None |
| Runway Length/Width: | 8001 ft / 150 ft | VFR Approach/Landing: | Full stop |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|---------------------|--------|-------------------------|----------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 34.211944,-118.490554(est) |

Page 4 of 5 GAA17CA413

Administrative Information

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: Ray Martin; FAA; Van Nuys, CA

Original Publish Date: October 17, 2017

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=95596

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA17CA413