



# **Aviation Investigation Final Report**

Location: Harrisonville, Missouri Accident Number: GAA17CA532

Date & Time: September 11, 2017, 20:03 Local Registration: N34413

Aircraft: Cessna 177 Aircraft Damage: Substantial

**Defining Event:** Wildlife encounter (non-bird) **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The pilot reported that, during takeoff, he heard a "bang," and "it felt as though the airplane hit a brick wall." He added that, during the climb, he examined the engine instruments, which appeared normal. About 800 ft above ground level, he looked out the left pilot window and observed that the fixed left main landing gear was "oddly positioned up next to [the] seat/door." The pilot reported that he contacted air traffic control, declared an emergency, and performed a "gear up" landing at the destination airport.

The airplane sustained substantial damage to the left stabilizer.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

After the accident, the following was added to the Airport Facility Directory: "Deer and other wildlife on and in vicinity of airport." It is likely the airplane hit a deer on the runway.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A collision with a deer on the runway during the takeoff roll.

## **Findings**

**Environmental issues** 

Animal(s)/bird(s) - Ability to respond/compensate

Page 2 of 5 GAA17CA532

## **Factual Information**

## **History of Flight**

Takeoff Wildlife encounter (non-bird) (Defining event)
--

#### **Pilot Information**

Certificate:	Private	Age:	58,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	November 23, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 24, 2017
Flight Time:	(Estimated) 1318.4 hours (Total, all aircraft), 189 hours (Total, this make and model), 954.5 hours (Pilot In Command, all aircraft), 36.7 hours (Last 90 days, all aircraft), 11.3 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N34413
Model/Series:	177 B	Aircraft Category:	Airplane
Year of Manufacture:	1972	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17701791
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	April 20, 2017 Annual	Certified Max Gross Wt.:	2500 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	4371.51 Hrs as of last inspection	Engine Manufacturer:	LYCOMING
ELT:	C91A installed, not activated	Engine Model/Series:	O-360-A1F6D
Registered Owner:		Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA17CA532

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night
Observation Facility, Elevation:	KLRY,915 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	12:55 Local	Direction from Accident Site:	82°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/ None
Wind Direction:		Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.23 inches Hg	Temperature/Dew Point:	13°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Harrisonville, MO (LRY )	Type of Flight Plan Filed:	None
Destination:	LEE'S SUMMIT, MO (LXT )	Type of Clearance:	None
Departure Time:	20:03 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	LAWRENCE SMITH MEMORIAL LRY	Runway Surface Type:	Asphalt
Airport Elevation:	915 ft msl	Runway Surface Condition:	Dry
Runway Used:	35	IFR Approach:	None
Runway Length/Width:	4000 ft / 75 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	38.610832,-94.343612(est)

Page 4 of 5 GAA17CA532

#### **Administrative Information**

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: David S Johnson; FAA; Kansas City, MO

Original Publish Date: December 15, 2017

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=95996">https://data.ntsb.gov/Docket?ProjectID=95996</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 GAA17CA532