



# **Aviation Investigation Final Report**

Location: Malone, New York Accident Number: GAA18CA416

Date & Time: June 30, 2018, 19:12 Local Registration: N712FP

Aircraft: Aeroprakt A-22 VALOR Aircraft Damage: Substantial

**Defining Event:** Hard landing **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

According to the pilot, he overflew the airport and assessed the winds for landing. During the landing flare, the airplane encountered a crosswind gust from the right. The right wing lifted, and the left wing struck the ground. The airplane pivoted about the left wing and landed hard.

The airplane sustained substantial damage to the left wing spar.

The pilot reported that there were no mechanical malfunctions or failures with the airplane that would have precluded normal operation.

The pilot reported that, about the time of the accident, the wind at the airport was from 240° and light and variable, gusting to 7 knots. The pilot landed on runway 23.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper crosswind correction during the landing flare in gusting wind conditions, which resulted in a hard landing.

## **Findings**

Aircraft Crosswind correction - Incorrect use/operation

Personnel issues Aircraft control - Pilot

**Environmental issues** Gusts - Effect on operation

**Environmental issues** Crosswind - Effect on operation

Page 2 of 5 GAA18CA416

## **Factual Information**

## **History of Flight**

Landing-flare/touchdown	Other weather encounter
Landing-flare/touchdown	Hard landing (Defining event)

#### **Pilot Information**

Certificate:	Private	Age:	69,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	May 1, 2017
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 15, 2017
Flight Time:	(Estimated) 200 hours (Total, all aircraft), 20 hours (Total, this make and model), 200 hours (Pilot In Command, all aircraft), 2.5 hours (Last 90 days, all aircraft), 1.1 hours (Last 30 days, all aircraft)		

## **Aircraft and Owner/Operator Information**

<u>.                                      </u>			
Aircraft Make:	Aeroprakt	Registration:	N712FP
Model/Series:	A-22 VALOR Undesignat	Aircraft Category:	Airplane
Year of Manufacture:	2008	Amateur Built:	
Airworthiness Certificate:	Special light-sport (Special)	Serial Number:	223
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	May 23, 2008 Annual	Certified Max Gross Wt.:	1320 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2900 Hrs	Engine Manufacturer:	Rotax
ELT:	Installed, not activated	Engine Model/Series:	912
Registered Owner:		Rated Power:	100 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA416

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSLK,1663 ft msl	Distance from Accident Site:	29 Nautical Miles
Observation Time:		Direction from Accident Site:	169°
<b>Lowest Cloud Condition:</b>	Scattered	Visibility	10 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/ 7 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	Malone, NY (MAL )	Type of Flight Plan Filed:	None
Destination:	Malone, NY (MAL )	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

## **Airport Information**

Airport:	Malone-Dufort MAL	Runway Surface Type:	Asphalt
Airport Elevation:	789 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	3994 ft / 100 ft	VFR Approach/Landing:	Full stop;Straight-in;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.85361,-74.328887(est)

Page 4 of 5 GAA18CA416

#### **Administrative Information**

Investigator In Charge (IIC): Hicks, Michael

Additional Participating Persons: Todd P Moses; FAA; Albany, NY

Original Publish Date: March 18, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=97749">https://data.ntsb.gov/Docket?ProjectID=97749</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 GAA18CA416