



Aviation Investigation Final Report

Location: Hutchinson, Kansas Accident Number: GAA19CA206

Date & Time: April 15, 2019, 13:35 Local Registration: N55275

Aircraft: Piper PA28R Aircraft Damage: Substantial

Defining Event: Landing gear not configured **Injuries:** 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot in the retractable landing gear-equipped airplane reported that, during a straight-in approach, the airplane's approach angle was too high. He recalled that he was distracted by an increase in aircraft operating in the area and that he forgot to extend the landing gear. The airplane landed with the landing gear retracted and slid off the right side of the runway before it came to rest.

The airplane sustained substantial damage to the lower fuselage.

The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to extend the landing gear before landing.

Findings

Personnel issues Lack of action - Pilot

Personnel issues Use of equip/system - Pilot

Aircraft Gear extension and retract sys - Not used/operated

Personnel issues Use of checklist - Pilot

Page 2 of 5 GAA19CA206

Factual Information

History of Flight

Landing-flare/touchdown	Landing gear not configured (Defining event)	
Landing-landing roll	Runway excursion	

Pilot Information

Certificate:	Private	Age:	52,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	April 24, 2019
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 11, 2018
Flight Time:	(Estimated) 160 hours (Total, all aircraft), 35 hours (Total, this make and model), 103 hours (Pilot In Command, all aircraft), 42 hours (Last 90 days, all aircraft), 16 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N55275
Model/Series:	PA28R 200	Aircraft Category:	Airplane
Year of Manufacture:	1973	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	28R-7335209
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	March 1, 2019 Annual	Certified Max Gross Wt.:	2600 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2324 Hrs	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	IO-360-C1C
Registered Owner:		Rated Power:	200 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA19CA206

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KHUT,1542 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:		Direction from Accident Site:	197°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.06 inches Hg	Temperature/Dew Point:	22°C
Precipitation and Obscuration:			
Departure Point:	Great Bend, KS (GBD)	Type of Flight Plan Filed:	None
Destination:	Hutchinson, KS (HUT)	Type of Clearance:	VFR flight following
Departure Time:	13:00 Local	Type of Airspace:	Class D

Airport Information

Airport:	Hutchinson Rgnl HUT	Runway Surface Type:	Asphalt
Airport Elevation:	1542 ft msl	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	4405 ft / 100 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	38.066112,-97.860557(est)

Page 4 of 5 GAA19CA206

Administrative Information

Investigator In Charge (IIC): Hicks, Michael

Additional Participating Persons: Webster McKinley; FAA; Wichita, KS

Original Publish Date: November 6, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=99268

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA19CA206