



Aviation Investigation Final Report

Location: Sebring, Florida Accident Number: GAA18CA364

Date & Time: June 17, 2018, 19:00 Local Registration: N6284X

Aircraft: Cessna 182T Aircraft Damage: Substantial

Defining Event: Runway excursion **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, after landing in crosswind conditions, the airplane veered right, exited the runway, and nosed over. The airplane came to rest upside down on the sandy grass adjacent to the runway.

The airplane sustained substantial damage to the left wing and empennage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The automated weather observation system at the airport reported that, about 6 minutes before the accident, the wind was from 080° at 6 knots. The pilot landed the airplane on runway 1 and reported that the wind speed was 21 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing with a crosswind.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Crosswind - Effect on operation

Page 2 of 5 GAA18CA364

Factual Information

History of Flight

| Landing-landing roll | Loss of control on ground |
|----------------------|-----------------------------------|
| Landing-landing roll | Runway excursion (Defining event) |
| Landing-landing roll | Nose over/nose down |

Pilot Information

| Certificate: | Private | Age: | 70,Male |
|---------------------------|--|-----------------------------------|------------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 3-point |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 With waivers/limitations | Last FAA Medical Exam: | April 25, 2018 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | October 27, 2017 |
| Flight Time: | (Estimated) 168 hours (Total, all aircraft), 16 hours (Total, this make and model), 70 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | Cessna | Registration: | N6284X |
|-------------------------------|--------------------------|-----------------------------------|-----------------|
| Model/Series: | 182T T | Aircraft Category: | Airplane |
| Year of Manufacture: | 2008 | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 18282105 |
| Landing Gear Type: | Tricycle | Seats: | 4 |
| Date/Type of Last Inspection: | Unknown | Certified Max Gross Wt.: | 2348 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | LYCOMING |
| ELT: | Installed, not activated | Engine Model/Series: | IO-540-AB1A5 |
| Registered Owner: | | Rated Power: | 290 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |

Page 3 of 5 GAA18CA364

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|--------------------------|
| Observation Facility, Elevation: | KSEF,63 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 23:15 Local | Direction from Accident Site: | 131° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 6 knots / | Turbulence Type Forecast/Actual: | None / None |
| Wind Direction: | 80° | Turbulence Severity Forecast/Actual: | N/A / N/A |
| Altimeter Setting: | 30.07 inches Hg | Temperature/Dew Point: | 29°C / 21°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Punta Gorda, FL (PGD) | Type of Flight Plan Filed: | VFR |
| Destination: | Sebring, FL (SEF) | Type of Clearance: | VFR;VFR flight following |
| Departure Time: | 18:19 Local | Type of Airspace: | Class G |
| | | | |

Airport Information

| Airport: | SEBRING RGNL SEF | Runway Surface Type: | Asphalt |
|----------------------|------------------|----------------------------------|-----------------------|
| Airport Elevation: | 61 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 01 | IFR Approach: | None |
| Runway Length/Width: | 5234 ft / 100 ft | VFR Approach/Landing: | Full stop;Straight-in |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|---------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 27.456388,-81.342498(est) |

Page 4 of 5 GAA18CA364

Administrative Information

Investigator In Charge (IIC): Nepomuceno, Eleazar

Additional Participating Persons: Cory Best; FAA; Orlando, FL

Original Publish Date: March 18, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=97538

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA18CA364