



Aviation Investigation Final Report

Location: Fullteron, California Accident Number: GAA19CA203

Date & Time: April 11, 2019, 11:30 Local Registration: N9964L

Aircraft: Cessna 172 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The student pilot reported that, during the landing roll, he applied brakes, but the airplane began to veer left. He corrected with right rudder, but the airplane exited the runway to the left and nosed over.

The airplane sustained substantial damage to the left wing and rudder.

The student reported that there were no preimpact mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's failure to maintain directional control during the landing roll, which resulted in a runway excursion and nose-over.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Use of equip/system - Student/instructed pilot

Factual Information

History of Flight

Loss of control on ground (Defining event)	
Attempted remediation/recovery	
Runway excursion	
Nose over/nose down	

Student pilot Information

Certificate:	Student	Age:	29,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	January 21, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 8, 2019
Flight Time:	(Estimated) 142 hours (Total, all aircraft), 60 hours (Total, this make and model), 11.5 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9964L
Model/Series:	172 P	Aircraft Category:	Airplane
Year of Manufacture:	1986	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17276652
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	100 hour	Certified Max Gross Wt.:	2400 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-320 SERIES
Registered Owner:		Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	None

Page 2 of 4 GAA19CA203

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KFUL,96 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	18:53 Local	Direction from Accident Site:	85°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	22°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Fullteron, CA (FUL)	Type of Flight Plan Filed:	None
Destination:	Fullteron, CA (FUL)	Type of Clearance:	VFR
Departure Time:	11:00 Local	Type of Airspace:	Class D

Airport Information

Airport:	Fullerton Muni FUL	Runway Surface Type:	Asphalt
Airport Elevation:	96 ft msl	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	3121 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.871944,-117.979721(est)

Page 3 of 4 GAA19CA203

Administrative Information

Investigator In Charge (IIC): Gutierrez, Eric

Additional Participating Persons: Kevin Doty; FAA; Long Beach, CA

Original Publish Date: November 6, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=99248

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 4 of 4 GAA19CA203