



Aviation Investigation Final Report

Location: Yakutat, Alaska Accident Number: GAA18CA363

Date & Time: June 19, 2018, 14:00 Local Registration: N9819D

Aircraft: Piper PA22 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, after touchdown, the airplane began oscillating and that it then exited the runway to the right. The airplane ground looped to the right, the left main landing gear collapsed, and the left wing impacted the ground.

The airplane sustained substantial damage to the left wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing.

Findings

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Factual Information

History of Flight

Landing	Miscellaneous/other
Landing	Loss of control on ground (Defining event)
Landing	Landing gear collapse

Pilot Information

Certificate:	Airline transport; Flight instructor	Age:	38,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	May 17, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 19, 2018
Flight Time:	(Estimated) 6575.8 hours (Total, all aircraft), 101 hours (Total, this make and model), 5145.5 hours (Pilot In Command, all aircraft), 103.1 hours (Last 90 days, all aircraft), 44.4 hours (Last 30 days, all aircraft), 0.3 hours (Last 24 hours, all aircraft)		

Page 2 of 4 GAA18CA363

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N9819D
Model/Series:	PA22 160	Aircraft Category:	Airplane
Year of Manufacture:	1959	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22-6706
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	April 14, 2018 Annual	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3604.2 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-320-A2B
Registered Owner:		Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument (IMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAYA,31 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	22:53 Local	Direction from Accident Site:	312°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Overcast / 800 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.13 inches Hg	Temperature/Dew Point:	13°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Yakutat, AK (A68)	Type of Flight Plan Filed:	None
Destination:	Yakutat, AK (YAK)	Type of Clearance:	Special VFR
Departure Time:		Type of Airspace:	Class E

Page 3 of 4 GAA18CA363

Airport Information

Airport:	YAKUTAT YAK	Runway Surface Type:	Asphalt
Airport Elevation:	32 ft msl	Runway Surface Condition:	Dry
Runway Used:	11	IFR Approach:	None
Runway Length/Width:	7732 ft / 150 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	59.508888,-139.664169(est)

Administrative Information

Investigator In Charge (IIC):	Benhoff, Kathryn
Additional Participating Persons:	Mathew Dahl; FAA; Juneau, AK
Original Publish Date:	March 18, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=97530

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 4 of 4 GAA18CA363