

Aviation Investigation Final Report

Location: Denver, Colorado

Date & Time: October 12, 2018, 09:16 Local

Aircraft: Airbus A319

Defining Event: Turbulence encounter

Flight Conducted Under: Part 121: Air carrier - Scheduled

Accident Number: DCA19CA010

Registration: N926FR

Aircraft Damage: None

Injuries: 1 Serious, 1 Minor, 22

None

Analysis

On October 12, 2018, about 0916 MDT, Frontier Airlines flight 190, an Airbus A319, N926FR, encountered turbulence while climbing through 24,000 feet after departure from Denver International Airport (DEN), Denver, Colorado. Of the 24 passengers and crew onboard, one flight attendant received serious injuries. The airplane was not damaged. The regularly scheduled passenger flight was operating under 14 *Code of Federal Regulations* Part 121 from DEN to Austin Bergstrom International Airport (AUS), Austin, Texas.

According to the flight crew, the flight encountered only intermittent light turbulence during the initial climb. However, as the airplane was climbing through flight level 240, they encountered continuous moderate turbulence. The airplane began to accelerate rapidly so the captain disconnected the autopilot and increased the climb. There was no convective activity in the area and no reports of any turbulence from other airplanes.

At the time of the turbulence encounter, two flight attendance in the aft gally were preparing for cabin service. Initially, the turbulence was light, however, when flight attendants felt the intensity increasing, they moved to get into their jump seats. Before they could get in their seats, they were both thrown into the air and then onto the floor. One flight attendant injured her ankle and the other injured her knee.

The captain called back to the cabin and was told that one of the flight attendants was seriously injured. He declared a medical emergency and requested paramedics meet the flight on arrival. After landing, one flight attendant was transported to a local hospital where she was diagnosed with a broken ankle.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

inadvertent encounter with clear air turbulence resulting in a flight attendant receiving serious injuries.

Findings

Environmental issues	nental issues Clear air turbulence - Effect on personnel		
Environmental issues	Clear air turbulence - Awareness of condition		
Environmental issues	Clear air turbulence - Ability to respond/compensate		

Page 2 of 5 DCA19CA010

Factual Information

History of Flight

Initial climb	Turbulence encounter (Defining event)	
---------------	---------------------------------------	--

Pilot Information

Certificate:	Airline transport; Commercial	Age:	48
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	July 16, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	June 3, 2018
Flight Time:	3368 hours (Total, all aircraft), 3368 hours (Total, this make and model)		

Co-pilot Information

Certificate:	Airline transport; Commercial	Age:	39,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	December 21, 2017
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	May 28, 2018
Flight Time:	625 hours (Total, all aircraft), 625 hours (Total, this make and model)		

Page 3 of 5 DCA19CA010

Aircraft and Owner/Operator Information

Aircraft Make:	Airbus	Registration:	N926FR
Model/Series:	A319 111	Aircraft Category:	Airplane
Year of Manufacture:	2004	Amateur Built:	
Airworthiness Certificate:	Transport	Serial Number:	2198
Landing Gear Type:	Retractable - Tricycle	Seats:	150
Date/Type of Last Inspection:	September 1, 2018 Continuous airworthiness	Certified Max Gross Wt.:	155200 lbs
Time Since Last Inspection:		Engines:	2 Turbo fan
Airframe Total Time:	697614 Hrs as of last inspection	Engine Manufacturer:	Cfm Intl.
ELT:	Installed, not activated	Engine Model/Series:	CFM56 SERIES
Registered Owner:		Rated Power:	
Operator:		Operating Certificate(s) Held:	Flag carrier (121)
Operator Does Business As:		Operator Designator Code:	F3LA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Unknown	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/ None
Wind Direction:		Turbulence Severity Forecast/Actual:	/ Moderate
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	Denver, CO (DEN)	Type of Flight Plan Filed:	
Destination:	Austin, TX (AUS)	Type of Clearance:	Unknown
Departure Time:		Type of Airspace:	

Page 4 of 5 DCA19CA010

Wreckage and Impact Information

Crew Injuries:	1 Serious, 1 Minor, 3 None	Aircraft Damage:	None
Passenger Injuries:	19 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 Minor, 22 None	Latitude, Longitude:	39.516944,-104.403892

Administrative Information

Investigator In Charge (IIC): Ward, Effie Lorenda

Additional Participating Persons:

Original Publish Date: January 6, 2022 Investigation Class: 4

Note: This accident report documents the factual circumstances of this accident as described to the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=98501

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 DCA19CA010