

Aviation Investigation Final Report

Location: Pella, Iowa **Accident Number**: GAA19CA193

Date & Time: March 26, 2019, 14:50 Local Registration: N7127G

Aircraft: Cessna 172 Aircraft Damage: Substantial

Defining Event: Nose over/nose down **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor reported that, during the landing with the student pilot on the flight controls, about 5 to 10 ft above the ground, a wind gust caused the airplane to drift right. The instructor assumed control of the airplane, attempted to correct, applied full power, and initiated a go-around. The instructor stated that the airplane was "low and slow," and the left main landing gear contacted the runway, and the airplane drifted left. Concerned the airplane would not gain significant altitude to clear the buildings in the flightpath, the instructor chose to land in the grass left of the runway. Subsequently, the airplane encountered soft terrain and nosed over.

The airplane sustained substantial damage to the aft fuselage and rudder.

The instructor reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

About the time of the accident, the airport's automated weather observation station reported that the wind was from 170° at 5 knots. The student was landing the airplane on runway 16.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's failure to maintain the runway heading and the flight instructor's delayed remedial action during landing, which resulted in the instructor landing the airplane in grass left of the runway and a subsequent nose-over.

Findings

Aircraft	Heading/course - Not attained/maintained	
Personnel issues	Aircraft control - Student/instructed pilot	
Personnel issues	Delayed action - Instructor/check pilot	
Environmental issues	Soft surface - Effect on operation	

Page 2 of 5 GAA19CA193

Factual Information

History of Flight

Landing	Loss of control in flight
Landing	Attempted remediation/recovery
Landing-aborted after touchdown	Abnormal runway contact
Landing	Nose over/nose down (Defining event)

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	41,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	October 22, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 16, 2018
Flight Time:	(Estimated) 562.2 hours (Total, all aircraft), 314.5 hours (Total, this make and model), 494.8 hours (Pilot In Command, all aircraft), 61.5 hours (Last 90 days, all aircraft), 14.8 hours (Last 30 days, all aircraft), 2.2 hours (Last 24 hours, all aircraft)		

Student pilot Information

Certificate:	Student	Age:	17,Female
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	September 28, 2017
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 51 hours (Total, all aircraft), 42.4 hours (Total, this make and model), 3 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 3.9 hours (Last 30 days, all aircraft), 2.2 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA19CA193

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N7127G
Model/Series:	172 K	Aircraft Category:	Airplane
Year of Manufacture:	1969	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	17258827
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	January 17, 2019 Annual	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	10600 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C126 installed, not activated	Engine Model/Series:	O-320-E2D
Registered Owner:		Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KPEA,885 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	21:55 Local	Direction from Accident Site:	186°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	170°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.31 inches Hg	Temperature/Dew Point:	14°C / -2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Pella, IA (PEA)	Type of Flight Plan Filed:	Unknown
Destination:	Pella, IA (PEA)	Type of Clearance:	Unknown
Departure Time:		Type of Airspace:	Class G

Page 4 of 5 GAA19CA193

Airport Information

Airport:	Pella Muni PEA	Runway Surface Type:	Concrete
Airport Elevation:	884 ft msl	Runway Surface Condition:	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	5403 ft / 75 ft	VFR Approach/Landing:	Full stop;Go around;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	41.401111,-92.945831(est)

Administrative Information

Investigator In Charge (IIC):	Gutierrez, Eric
Additional Participating Persons:	Kendall D Arkema; FAA; Des Moines , IA
Original Publish Date:	November 6, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=99213

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA19CA193