

Aviation Investigation Final Report

Location: Cahokia, Illinois Accident Number: CEN17CA140

Date & Time: February 23, 2017, Registration: N51827

Aircraft: Cessna 172R Aircraft Damage: Substantial

Defining Event: Unknown or undetermined **Injuries:** N/A

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The airplane was parked on the operator's ramp when Federal Aviation Administration inspector(s), during a routine ramp inspection, found that the airplane had substantial damage to the firewall and structure aft of the firewall. Airplane maintenance records showed an entry stating that the damage was due to a suspected hard landing. The operator stated that the damage must have occurred between the airplane's 100-hour inspection on September 27 and an oil change performed on October 24, 2016. The operator's mechanic stated that the damage was found when the engine cowl was removed for the oil change.

A review of airplane flight logs showed about 20 different people had flown the airplane over 48 flights between the time of the 100-hour inspection and the oil change. On October 8, 2016, a student pilot was performing touch and gos when the airplane bounced two or three times during the flight's final landing. The student pilot stated that, when she turned off the runway onto the taxiway, she noticed the airplane was not steering properly and reported to the air traffic control tower that she had some mechanical difficulty that required maintenance assistance. The student pilot's flight instructor and a company lineman responded and noticed that the airplane had a flat nosewheel tire. The lineman inflated the tire, and the student pilot and flight instructor taxied the airplane to the operator's maintenance facility. The flight instructor informed the operator's mechanic of the bounced landing and flat tire. The mechanic stated that he replaced the nose tire, performed a brief exterior walk-around visual inspection of the airplane, noting it appeared airworthy, and returned it to service. A hard landing inspection was not performed. Other than the bounced landing reported on October 8, 2016, no other concerns about the other flights were reported to the operator.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A hard landing for reasons that could not be determined based on the available evidence.

Findings

Not determined

(general) - Unknown/Not determined

Page 2 of 5 CEN17CA140

Factual Information

History of Flight

Information

Certificate:	Age:
Airplane Rating(s):	Seat Occupied:
Other Aircraft Rating(s):	Restraint Used:
Instrument Rating(s):	Second Pilot Present:
Instructor Rating(s):	Toxicology Performed:
Medical Certification:	Last FAA Medical Exam:
Occupational Pilot:	Last Flight Review or Equivalent:
Flight Time:	

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N51827
Model/Series:	172R	Aircraft Category:	Airplane
Year of Manufacture:	2002	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	17281108
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	September 27, 2016 100 hour	Certified Max Gross Wt.:	2457 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	IO-360-L2A
Registered Owner:		Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	None

Page 3 of 5 CEN17CA140

Meteorological Information and Flight Plan

Conditions at Accident Site:	Unknown	Condition of Light:	Not reported
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	Unknown
Destination:		Type of Clearance:	Unknown
Departure Time:		Type of Airspace:	Unknown

Airport Information

Airport:	St Louis Downtown Airport CPS	Runway Surface Type:	
Airport Elevation:	413 ft msl	Runway Surface Condition:	Unknown
Runway Used:		IFR Approach:	Unknown
Runway Length/Width:		VFR Approach/Landing:	Unknown

Wreckage and Impact Information

Crew Injuries:		Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	N/A	Latitude, Longitude:	38.570278,-90.154998(est)

Page 4 of 5 CEN17CA140

Administrative Information

Investigation Docket:

Investigator In Charge (IIC):Gallo, MitchellAdditional Participating Persons:Dennis Mueller; Federal Aviation Administration; STL FSDO; St. Ann, MOOriginal Publish Date:June 7, 2017Note:This accident report documents the factual circumstances of this accident as described to the NTSB.

https://data.ntsb.gov/Docket?ProjectID=94925

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 CEN17CA140