

Aviation Investigation Final Report

Location: Tacoma, Washington Accident Number: GAA19CA100

Date & Time: December 14, 2018, 09:00 Local Registration: N19EC

Aircraft: Cessna A185 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, during the landing roll, the airplane veered right. He applied left rudder, and the airplane straightened out, but it then began to veer right again. He stated that he then overcorrected with excessive left rudder control and that the right wingtip impacted the runway. The right-wing trailing edge spar was substantially damaged. The pilot reported that there were no preimpact mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of directional control during the landing roll and his subsequent overapplication of left rudder, which resulted in the right wing impacting the runway.

Findings

Personnel issues Aircraft control - Pilot

Personnel issues Use of equip/system - Pilot

Aircraft Directional control - Not attained/maintained

Aircraft Rudder control system - Incorrect use/operation

Aircraft Rudder control system - Incorrect use/operation

Page 2 of 5 GAA19CA100

Factual Information

History of Flight

| Landing-landing roll | Loss of control on ground (Defining event) | |
|----------------------|--|--|
| Landing-landing roll | Attempted remediation/recovery | |

Pilot Information

| Certificate: | Private | Age: | 68,Male |
|---------------------------|----------------------------------|-----------------------------------|------------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | Unknown |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 With waivers/limitations | Last FAA Medical Exam: | October 31, 2017 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | (Estimated) | | |
| | | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | Cessna | Registration: | N19EC |
|-------------------------------|-------------------------------|-----------------------------------|-----------------|
| Model/Series: | A185 E | Aircraft Category: | Airplane |
| Year of Manufacture: | 1967 | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 185-1306 |
| Landing Gear Type: | Tailwheel | Seats: | 4 |
| Date/Type of Last Inspection: | Annual | Certified Max Gross Wt.: | 3300 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | Continental |
| ELT: | C126 installed, not activated | Engine Model/Series: | IO-520-D |
| Registered Owner: | | Rated Power: | 300 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |
| | | | |

Page 3 of 5 GAA19CA100

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|-----------------------------|---|------------------|
| Observation Facility, Elevation: | KTIW,315 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 16:53 Local | Direction from Accident Site: | 92° |
| Lowest Cloud Condition: | | Visibility | 10 miles |
| Lowest Ceiling: | Broken / 12000 ft AGL | Visibility (RVR): | |
| Wind Speed/Gusts: | / | Turbulence Type Forecast/Actual: | None / None |
| Wind Direction: | | Turbulence Severity Forecast/Actual: | N/A / N/A |
| Altimeter Setting: | 29.6 inches Hg | Temperature/Dew Point: | 6°C / 4°C |
| Precipitation and Obscuration: | No Obscuration; No Precipit | ation | |
| Departure Point: | Tacoma, WA (TIW) | Type of Flight Plan Filed: | None |
| Destination: | Tacoma, WA (TIW) | Type of Clearance: | None |
| Departure Time: | | Type of Airspace: | Class D |
| | | | |

Airport Information

| Airport: | Tacoma Narrows TIW | Runway Surface Type: | Asphalt |
|----------------------|--------------------|----------------------------------|-----------------------|
| Airport Elevation: | 294 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 17 | IFR Approach: | None |
| Runway Length/Width: | 5002 ft / 100 ft | VFR Approach/Landing: | Full stop;Straight-in |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|---------------------|--------|-------------------------|----------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 47.268054,-122.578056(est) |

Page 4 of 5 GAA19CA100

Administrative Information

Investigator In Charge (IIC): Nepomuceno, Eleazar

Additional Participating Persons: Gaddie Orcullo; FAA; Des Moines, WA

Original Publish Date: August 27, 2020

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=98782

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA19CA100