



Aviation Investigation Final Report

Location: Punta Gorda, Florida Accident Number: GAA17CA136

Date & Time: February 11, 2017, 17:40 Local Registration: N289MN

Aircraft: NIELSEN MARTIN M CHALLENGER Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, during the landing flare, while on his second landing attempt, the airplane began to sink rapidly, and the right wing dropped. He applied right rudder and power in an attempt to maintain directional control but was unsuccessful. The airplane settled in the bushes to the left of the runway.

The airplane sustained substantial damage to the right wing.

The pilot reported no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Tree(s) - Contributed to outcome

Page 2 of 5 GAA17CA136

Factual Information

History of Flight

Landing	Loss of control in flight (Defining event)
Landing	Attempted remediation/recovery
Landing	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Airline transport	Age:	65,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	December 16, 2015
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	March 7, 2016
Flight Time:	(Estimated) 24687 hours (Total, all aircraft), 23 hours (Total, this make and model), 13000 hours (Pilot In Command, all aircraft), 25 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA17CA136

Aircraft and Owner/Operator Information

NIELSEN MARTIN M	Registration:	N289MN
CHALLENGER II	Aircraft Category:	Airplane
2015	Amateur Built:	Yes
Restricted (Special)	Serial Number:	2089
Tricycle	Seats:	2
November 6, 2016 Annual	Certified Max Gross Wt.:	960 lbs
	Engines:	1 Reciprocating
22.3 Hrs at time of accident	Engine Manufacturer:	Rotax
C126 installed, not activated	Engine Model/Series:	503 DCDI
	Rated Power:	53 Horsepower
On file	Operating Certificate(s) Held:	None
	CHALLENGER II 2015 Restricted (Special) Tricycle November 6, 2016 Annual 22.3 Hrs at time of accident C126 installed, not activated	CHALLENGER II Aircraft Category: 2015 Amateur Built: Restricted (Special) Serial Number: Tricycle Seats: November 6, 2016 Annual Certified Max Gross Wt.: Engines: 22.3 Hrs at time of accident C126 installed, not activated Engine Model/Series: Rated Power: On file Operating Certificate(s)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	VILK,410 ft msl	Distance from Accident Site:	40 Nautical Miles
Observation Time:	12:00 Local	Direction from Accident Site:	289°
Lowest Cloud Condition:	Unknown	Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	2 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:		Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:		Temperature/Dew Point:	22°C / 7°C
Precipitation and Obscuration:	Moderate - None - Haze		
Departure Point:	Punta Gorda, FL (PGD)	Type of Flight Plan Filed:	None
Destination:	Punta Gorda, FL (PGD)	Type of Clearance:	None
Departure Time:	16:00 Local	Type of Airspace:	Class D

Page 4 of 5 GAA17CA136

Airport Information

Airport:	PUNTA GORDA PGD	Runway Surface Type:	Asphalt
Airport Elevation:	25 ft msl	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	7193 ft / 150 ft	VFR Approach/Landing:	Go around;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	26.912776,-81.991943(est)

Administrative Information

Investigator In Charge (IIC):	Vanover, Jackie
Additional Participating Persons:	Rulon Vilcan; FAA; Tampa, FL
Original Publish Date:	July 20, 2017
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=94709

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA17CA136