



Aviation Investigation Final Report

Location: Ocklawaha, Florida **Accident Number:** GAA18CA517

Date & Time: August 25, 2018, 15:00 Local Registration: N7618S

Aircraft: Champion 7GCBC Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, during landing, a wind gust from the right caused the airplane to weathervane. The airplane veered right off the runway, ground looped to the right, and the left wing and elevator impacted the ground.

The airplane sustained substantial damage to the left wing and left elevator.

The pilot added that he was a "very experienced pilot, but very inexperienced with tailwheel operations."

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Personnel issues Total experience w/ equipment - Pilot

Page 2 of 5 GAA18CA517

Factual Information

History of Flight

Landing	Other weather encounter
Landing	Loss of control on ground (Defining event)
Landing	Runway excursion

Pilot Information

Certificate:	Airline transport; Flight engineer; Flight instructor; Private	Age:	52,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	April 4, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 22, 2018
Flight Time:	(Estimated) 11300 hours (Total, all aircraft), 25 hours (Total, this make and model), 11000 hours (Pilot In Command, all aircraft), 110 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA18CA517

Aircraft and Owner/Operator Information

Aircraft Make:	Champion	Registration:	N7618S
Model/Series:	7GCBC No Series	Aircraft Category:	Airplane
Year of Manufacture:	1976	Amateur Built:	
Airworthiness Certificate:	Aerobatic; Normal	Serial Number:	923-76
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 13, 2018 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1773 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	0-320-A2D
Registered Owner:		Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KVVG,89 ft msl	Distance from Accident Site:	11 Nautical Miles
Observation Time:	19:24 Local	Direction from Accident Site:	202°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Broken / 4200 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	11 knots / 20 knots	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	60°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.06 inches Hg	Temperature/Dew Point:	29°C / 23°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Ocklawaha, FL (FA38)	Type of Flight Plan Filed:	None
Destination:	Ocklawaha, FL (FA38)	Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Class G

Page 4 of 5 GAA18CA517

Airport Information

Airport:	WOODS AND LAKES AIRPARK FA38	Runway Surface Type:	Asphalt;Grass/turf
Airport Elevation:	100 ft msl	Runway Surface Condition:	Dry
Runway Used:	03	IFR Approach:	None
Runway Length/Width:	2900 ft / 97 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	29.123888,-81.887496(est)

Administrative Information

Investigator In Charge (IIC):	Benhoff, Kathryn
Additional Participating Persons:	Albert Gomez; FAA; Orlando, FL
Original Publish Date:	March 18, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98183

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA517