

VOLKSWAGEN AKTIENGESELLSCHAFT	Konzern - Richtlinie Produktaudit Leitungsstränge -- Berichtsvordruck, Gesamtübersicht --	Ausgabe : 07/2023 Anlage A Seite 1 von 3
 DRÄXLMAIER	Monatsbericht Produktaudit Leitungsstränge	Monat / Jahr Mai 2026

An:

Volkswagen AG, Wolfsburg

E-Mail : Produktaudit-Leitungsstrang@volkswagen.de

Von:

Firma:

Abteilung:

Koordinator:

Tel.-Nr.:

Email:

Dräxlmaier Group

OE5131

Y.Zouaoui

+216 58 25 58 41

Produktaudit-ES@draexlmaier.com

A - Fertigungsstätten B - ausgelagerte Prozesse C - verlängerte Werkbank			Aktueller Monat: Mai			Anzahl geprüfter Leistungs- stränge		Letzter Monat: April		
			QK	QK	QK	aktuell	Vor-	QK	QK	QK
			min.		max.		monat	min.		max.
1	A- DET Jemmal (Tunesien)		0.6	0.8	1.2	6	6	0.3	0.7	1.0
	DUNS-NR.: 36-286-5226									
2										
3										
4										
5										
6										
7										

Bemerkungen:

VOLKSWAGEN AKTIENGESELLSCHAFT		Konzern - Guideline Product Audit Wire Harnesses -- Report, Summary Overview --		Ausgabe: 07/2023 Anlage A Seite 3 von 3																					
		Monthly Report Product Audit Wire Harnesses		Monat / Jahr 05 / 2026																					
Part Discription : CSH Description : LL IR Vehicle Type : AU 416-2B Drawing / Kenn-N° : 2141772 TAB : TAB010619GF Drawing date : 10.10;2025		Auditor : Horrich Kawther OE-TM Departmer : Quality Compar : DET Location : Jemmal (Tunesien)		Lead-Auditor : Horric Kawther Telephone : +216 56729302 Date : 20/05/2026																					
		Target: QC ≤ 0,5 Threshold: QC > 1,0																							
		<table border="1"> <tr> <td>Weighted defect Points</td> <td>188</td> <td>Manufacturing Defects (F)</td> <td>4</td> <td colspan="2">Quality Class</td> </tr> <tr> <td>Calculation Factor</td> <td>0.5</td> <td>Damage Defects (S)</td> <td>0</td> <td colspan="2" rowspan="3"> QK 1.2 </td> </tr> <tr> <td>Number of defects</td> <td>4</td> <td>Design Defects (K)</td> <td>0</td> </tr> <tr> <td>100-Point-defects</td> <td>3</td> <td>Supplier Defects (L)</td> <td>0</td> </tr> </table>				Weighted defect Points	188	Manufacturing Defects (F)	4	Quality Class		Calculation Factor	0.5	Damage Defects (S)	0	QK 1.2		Number of defects	4	Design Defects (K)	0	100-Point-defects	3	Supplier Defects (L)	0
Weighted defect Points	188	Manufacturing Defects (F)	4	Quality Class																					
Calculation Factor	0.5	Damage Defects (S)	0	QK 1.2																					
Number of defects	4	Design Defects (K)	0																						
100-Point-defects	3	Supplier Defects (L)	0																						
defect Code	pos. cause	Defect Types / Defect Improvement Actions		Freq.	Points/ Defect																				
7.1G	F	Assembly- / form- / add on parts (clips / cable ties etc.) Dimension not acc. to specification Short measure between assmebly part - CL_1714 =>MPSB10_B - Koo: 1-16A Soll: SOLL:198mm +10mm Ist: IST:160mm		1	100																				
Improvement Action introduced:		Root cause: BB not optimal =>gabel not adequat Measure: ISSUE QUALITY ALERT Check the inventory :IO request to optimize layout , to change gabel CP22_5941																							
7.1G	F	Assembly- / form- / add on parts (clips / cable ties etc.) Dimension not acc. to specification Short measure between assmebly part - CL_2510 =>AUSSENSSG - Koo: 2-14G Soll: SOLL:302mm +10mm Ist: IST:285mm		1	100																				
Improvement Action introduced:		Root cause: The ACT orientation incorrect Measure: ISSUE QUALITY ALERT Check the inventory :IO 'Fix the ACT full heads according specification																							
7.1G	F	Assembly- / form- / add on parts (clips / cable ties etc.) Dimension not acc. to specification Short measure between assmebly part - CL_5122=>CL_5145 - Koo: 3-47G Soll: SOLL:182mm +5mm Ist: IST:170mm		1	100																				
Improvement Action introduced:		Root cause: Layout not optimal Bolzen installed is not adequate and generate a loss of mesurement Measure: ISSUE QUALITY ALERT Check the inventory :IO optimize layout LL=>'Add rod Kipteil																							
7.1L	F	Assembly- / form- / add on parts (clips / cable ties etc.) Assembly / latching n.o.k. Assembly clip not ok according to specification (tight nio)- CL_2015 - Koo: 1-42D		1	75																				
Improvement Action introduced:		Root cause: assmebly branche not adequat with the clip =>the branch is minor Measure: ISSUE QUALITY ALERT Check the inventory :IO Add 3 turns tesa under clips to secure the fastening																							
		Error points report:		375	Total on page: 4 375 375																				

VOLKSWAGEN AKTIENGESELLSCHAFT		Konzern - Guideline Product Audit Wire Harnesses -- Report, Summary Overview --		Ausgabe: 07/2023 Anlage A Seite 3 von 3	
		Monthly Report Product Audit Wire Harnesses		Monat / Jahr 05 / 2026	

Part Discription :	CSH	Auditor :	Horrich Kawther OE-TN	Lead-Auditor :	Horric Kawther
Description :	RL IR	Departmer :	Quality	Telephone :	+216 56729302
Vehicle Type :	AU 416-2B	Compar :	DET	Date :	20/05/2026
Drawing / Kenn-N° :	2221993	Location :	Jemmal (Tunesien)		
TAB :	TAB010619GH				
Drawing date :	10.10.2025				

Target: QC ≤ 0,5 Threshold: QC > 1,0

Weighted defect Points	125	Manufacturing Defects (F)	3	Quality Class QK 0.9
Calculation Factor	0.5	Damage Defects (S)	0	
Number of defects	3	Design Defects (K)	0	
100-Point-defects	2	Supplier Defects (L)	0	

defect Code	pos. cause	Defect Types / Defect Improvement Actions	Freq.	Points/ Defect	Defect points
7.1G	F	Assembly- / form- / add on parts (clips / cable ties etc.) Dimension not acc. to specification short measure between assembly part- POS:CL_1504=>MPS11_A - Koo: 1-39H Soll: SOLL:164mm +10mm Ist: IST:150mm	1	100	100
Improvement Action introduced:		Root cause: BB not optimal =>gabel not adequat Measure: ISSUE QUALITY ALERT Check the inventory :IO request to optimize layout and to change gable 3 fix not kipptail CP22_5940			
7.1G	F	Assembly- / form- / add on parts (clips / cable ties etc.) Dimension not acc. to specification short measure between assembly part- POS:CL_2507=>CL_2509 - Koo: 2-4C Soll: SOLL:168mm +5mm Ist: IST:160mm	1	100	100
Improvement Action introduced:		Root cause: the current force is insufficient to achieve proper tightening Measure: ISSUE QUALITY ALERT Check the inventory :IO request to change force tightening in assembly ligne CP22_5942			
7.1F	F	Assembly- / form- / add on parts (clips / cable ties etc.) taped not acc. to specification (Spiral- or spot tape, not taped / fixed) fixiting bteil not ok according to specification /WI not respected- POS:CL_1025 - Koo: 1-41C Soll: SOLL:2 round and halfToleranz / Tolerance* Ist: IST:1 round	1	50	50
Improvement Action introduced:		Root cause: Operator does not do the self contol Measure: ISSUE QUALITY ALERT Check the inventory :IO *training Reminder regarding on the B-teil fixing method			
Improvement Action introduced:					
		Error points report:	250	Total on page:	3 250 250

Part Description :

CSH

Auditor :

Horrich Kawther OE-TN

Lead-Auditor :

Horric Kawther

Description :

RL Cockpit

Departmer :

Quality

Telephone :

+216 56729302

Vehicle Type :

AU 416_2B

Compar :

DET

Date :

20/05/2026

Drawing / Kenn-N° :

2221614

Location :

Jemmal (Tunesien)

TAB :

TAB026068CL

Drawing date :

10.10.2025

Target: $QC \leq 0,5$

Threshold: QC > 1,0

Weighted defect Points	80	Manufacturing Defects (F)	1	Quality Class QK 0.6
Calculation Factor	0.8	Damage Defects (S)	0	
Number of defects	1	Design Defects (K)	0	
100-Point-defects	1	Supplier Defects (L)	0	

defect Code	pos. cause	Defect Types / Defect Improvement Actions	Freq.	Points/ Defect	Defect points
7.1G	F	Assembly- / form- / add on parts (clips / cable ties etc.) Dimension not acc. to specification Short measure between assembt part - CL_1012=>CL_1013 - Koo: 14J Soll: SOLL:187mm +5mm Ist: IST:174mm	1	100	100
Improvement Action introduced:		Root cause: layout not adequat , does not guarante the correct measure Measure: ISSUE QUALITY ALERT Check the inventory :!O Request to change fork G1 by Bolzen and move it 5mm CP22-5949			
Improvement Action introduced:					
Improvement Action introduced:					
Improvement Action introduced:					
Improvement Action introduced:					
Error points report:		100	Total on page:	1	100
				100	100

VOLKSWAGEN AKTIENGESELLSCHAFT		Konzern - Guideline Product Audit Wire Harnesses -- Report, Summary Overview --		Ausgabe: 07/2023 Anlage A Seite 3 von 3	
		Monthly Report Product Audit Wire Harnesses		Monat / Jahr 05 / 2026	

Part Discription :	CSH	Auditor :		Lead-Auditor :	Horric Kawther
Description :	RL IR	Departmer :	Quality	Telephone :	+216 56729302
Vehicle Type :	AU 416_2B	Compar :	DET	Date :	20/05/2026
Drawing / Kenn-N° :	2221614	Location :	Jemmal (Tunesien)		
TAB :	TAB010619GH				
Drawing date :	10.10.2025				

Target: QC ≤ 0,5
Threshold: QC > 1,0

Weighted defect Points	100	Manufacturing Defects (F)	2	Quality Class QK 0.7
Calculation Factor	0.5	Damage Defects (S)	0	
Number of defects	2	Design Defects (K)	0	
100-Point-defects	2	Supplier Defects (L)	0	

defect Code	pos. cause	Defect Types / Defect Improvement Actions	Freq.	Points/ Defect	Defect points
7.1G	F	Assembly- / form- / add on parts (clips / cable ties etc.) Dimension not acc. to specification Short measure between assembly pat - CL_2511=>CL_2512 - Koo: 2-10A Soll: SOLL:236mm +5mm Ist: IST:225mm	1	100	100
Improvement Action introduced:		Root cause: The ACT orientation incorrect Measure: ISSUE QUALITY ALERT Check the inventory :IO 'Fix the ACT full heads according specification			
7.1G	F	Assembly- / form- / add on parts (clips / cable ties etc.) Dimension not acc. to specification long measure of branche - HCP5_B - Koo: 2-18E Soll: SOLL:115mm +15mm Ist: IST:160mm	1	100	100
Improvement Action introduced:		Root cause: Missing of training regarding the importance of self control (respecting 1/1 drawing when lying) Measure: ISSUE QUALITY ALERT Check the inventory :IO 'Training regarding the importance of self control and respecting 1/1 drawing during laying out harness.			
Improvement Action introduced:					
Improvement Action introduced:					
Improvement Action introduced:					
		Error points report:	200	Total on page:	200
			2	200	200

VOLKSWAGEN AKTIENGESELLSCHAFT		Konzern - Richtlinie Produktaudit Leitungsstränge -- Berichtsvordruck, Gesamtübersicht --				Ausgabe : 07/2023 Anlage C					
		Jahresübersicht Qualitätsstatus Produktaudit Leitungsstränge				Jahr					
						2026					
Fertigungsstätte		Land		DUNS Nummer		Koordinator Lieferant					
DET / Jemmal		Tunesien		36-286-5226		Y.Zouaoui					
Projekte KSK (Werk / BTV)		AU416_2B (Ingolstadt / Hr. Ott Eric)									
Projekte Autarke (Werk / BTV)											
Zertifizierte Produktauditoren (gemäß VW Richtlinie)		validation of the reports by Y. Zouaoui, M. Vogel									
		Kawther Horrich, Shil Sirine									
		Produktaudit zerstörend				Produktaudit partiell					
Monat	Qualitätsklasse	Σ gepr. Ltg.	QK min.	QK Ø	QK max.	Σ gepr. Ltg.	QK min.	QK Ø	QK max.		
	Produktgruppe (PG) Leitungsstrang	KSK	Autarke	Batterie-/ Masse-/ Generatoritg.	HV	KSK	Autarke	Batterie-/ Masse-/ Generatoritg.	HV		
Januar	Firma	0	0.0	0.0	0.0	4	0.6	0.8	0.9		
	VW Konzern	-	-	-	-	-	-	-	-		
	Σ P-Audit	0	0	0	0	4	0.0	0.0	0.0		
Februar	Firma	0	0.0	0.0	0.0	6	0.6	0.8	1.0		
	VW Konzern	-	-	-	-	-	-	-	-		
	Σ P-Audit	0	0	0	0	6	0.0	0.0	0.0		
März	Firma	2	1.1	1.2	1.3	0	0.0	0.0	0.0		
	VW Konzern	-	-	-	-	-	-	-	-		
	Σ P-Audit	2	0	0	0	0	0	0	0		
April	Firma	0	0.0	0.0	0.0	6	0.3	0.7	1.0		
	VW Konzern	-	-	-	-	-	-	-	-		
	Σ P-Audit	0	0	0	0	6	0.0	0.0	0.0		
Mai	Firma	0	0.0	0.0	0.0	6	0.6	0.8	1.2		
	VW Konzern	-	-	-	-	-	-	-	-		
	Σ P-Audit	0	0	0	0	6	0.0	0.0	0.0		
Juni	Firma										
	VW Konzern										
	Σ P-Audit										
Juli	Firma										
	VW Konzern										
	Σ P-Audit										
August	Firma										
	VW Konzern										
	Σ P-Audit										
September	Firma										
	VW Konzern										
	Σ P-Audit										
Oktober	Firma										
	VW Konzern										
	Σ P-Audit										
November	Firma										
	VW Konzern										
	Σ P-Audit										
Dezember	Firma										
	VW Konzern										
	Σ P-Audit										

© All rights reserved. Distribution within the company, customer and partners