

MAINTENANCE REPORT

Report ID: MR-2024-014

Date: 15 January 2024

Facility: Visakhapatnam Industrial Complex, Unit 3

Equipment: Pump-101 (Centrifugal Feed Pump)

Performed by: Rajesh Kumar (Senior Maintenance Engineer)

Shift: Day Shift (08:00 - 16:00)

OBSERVATION:

During routine maintenance check, Pump-101 showed abnormal vibration levels exceeding 7.2 mm/s (threshold: 4.5 mm/s). Bearing temperature recorded at 78°C, above normal operating range of 55-65°C.

ACTIONS TAKEN:

- Vibration analysis performed using portable analyzer
- Bearing lubrication checked and topped up
- Recommended follow-up inspection within 7 days

REFERENCE DOCUMENTS:

- Safety Procedure SP-45 (Rotating Equipment Safety Protocol)
- Regulatory Guideline OISD-105
- Related to previous incident report INC-2023-089 (Boiler-3 bearing failure)

NOTES:

This is the second vibration anomaly recorded on feed pumps in this unit within the last quarter. Recommend cross-checking similar equipment (Pump-104) for early signs of the same failure pattern.

Status: Follow-up Required

Next Inspection Due: 22 January 2024