

MAINTENANCE REPORT

Report ID: MR-2024-022

Date: 3 March 2024

Facility: Visakhapatnam Industrial Complex, Unit 3

Equipment: Pump-104 (Centrifugal Feed Pump)

Performed by: Anita Sharma (Maintenance Engineer)

Shift: Day Shift (08:00 - 16:00)

OBSERVATION:

Routine check revealed vibration levels at 5.1 mm/s, within Warning threshold as defined by Safety Procedure SP-45. Bearing temperature recorded at 69°C, slightly elevated but within acceptable range.

ACTIONS TAKEN:

- Escalated to Maintenance Supervisor within 2 hours (in compliance with SP-45)
- Vibration analysis scheduled for detailed diagnostics
- Lubrication levels checked, found adequate

REFERENCE DOCUMENTS:

- Safety Procedure SP-45
- Similar pattern noted in Pump-101 (Maintenance Report MR-2024-014) and historical incident INC-2023-089 (Boiler-3)

NOTES:

Given that this is the third instance of elevated vibration in feed pump equipment within this unit over the past 5 months (Boiler-3, Pump-101, and now Pump-104), recommend a comprehensive fleet-wide vibration audit across all rotating equipment in Unit 3.

Status: Under Investigation

Next Inspection Due: 10 March 2024