

Koy to Accosement



LOW



MEDILIM



COMPANY NAME : BEAVER FLOORCARE

CLIENT: APPLE

SITE: APPLE R340 BRAEHEAD

ACTIVITY: STONE FLOOR MAINTENANCE & RE-FINISHING

DATE OF RISK ASSESSMENT: 19th December 2017

ПСП

AUTHOR: D.CAMPTON

Key to Assessment	LOW Minor Impact Damage quickly repaired	MEDIUM Moderate Impact Partial Loss of Operations	HIGH Disaster Very Serious Consequences				
						•	
				HAZARD	PERSONS/PROPERTY	CONTROLLED RISK	SUMMARY OF PROTECTIVE & PREVENTIVE
AT RISK		MEASURES					
Olina Trina and Falla	Decises Descend	1.011	- Mark spheridal autoida of trading times				
Slips , Trips and Falls	Beaver Personnel	LOW	Work scheduled outside of trading times. Future is a Staff Training in protection (place in a technique of the staff Training in protection).				
during restoration &	Site Personnel		Extensive Staff Training in restoration/ cleaning techniques Training in Site University and its actions.				
maintenance activities			Training in Site Housekeeping				
(No heights or ladder work undertaken)			Need for working in manageable areas				
			Avoidance of trailing cables etc				
			Use of Hazard Warning Signage at all times				
			Areas cordoned off as required - barriers, barrier tape, signs				
			Spill procedures established				
			Safety footwear worn by technicians				
Use of Cleaning	Beaver Personnel	LOW	Training provided in chemical use.				
Chemicals	Site Personnel		Use of non-hazardous chemicals whenever possible				
	Building Fabric		Special Training in use of Ardex R65P				
- skin problems			Dispenser pumps , gloves used to prevent skin contact				
- eye contamination			• PPE to be used - masks, glasses, gloves ,protective clothing				
- inhalation of chemical			Protective masking to areas wherever required				
vapours			Eye Wash in First Aid Kits carried on Site.				
rapouro							

Restoration and Maintenance of Carpet, Marble, Vinyl, Rubber and Wood

Reg. Office The Barn, Oldberrow Manor, Ullenhall Lane, Ullenhall, Warwickshire B95 5PF Tel: 01564 742095 Fax: 01564 742853

Beaver Floorcare Ltd.: Registered in England No. 6695922 info@beaverfloorcare.co.uk www.beaverfloorcare.co.uk









COMPANY NAME: BEAVER FLOORCARE

CLIENT: APPLE

SITE: APPLE R.340 BRAEHEAD

ACTIVITY: STONE FLOOR MAINTENANCE & RE-FINISHING

DATE OF RISK ASSESSMENT: 19th December 2018
AUTHOR: D.CAMPTON

Key to Assessment	LOW	MEDIUM	HIGH
	Minor Impact	Moderate Impact	Disaster
	Damage quickly repaired	Partial Loss of Operations	Very Serious Consequences
HAZARD	PERSONS/PROPERTY	CONTROLLED RISK	SUMMARY OF PROTECTIVE & PREVENTIVE

HAZARD	PERSONS/PROPERTY AT RISK	CONTROLLED RISK	SUMMARY OF PROTECTIVE & PREVENTIVE MEASURES
Musculoskeletal Disorders - Transporting cleaning equipment - Moving furniture at site - Using cleaning/reprocessing equpt - Working awkwardly e.g. on knees	Beaver Personnel	LOW	 Training in Manual Handling to ensure correct lifting of cleaning equipment, furniture etc. Use of provided wheels to assist with furniture moving. Training in correct use of cleaning machinery -e.g height etc adjustment of rotary machines to ensure no torque Regular checks to machines including vibration etc Try to avoid awkward working, if not, ensure adequate rest periods. Knee pads provided. Safety shoes worn by staff to prevent foot damage.
Electrical Hazards - shocks	Beaver Personnel Site Premises	LOW	 Machinery used with RCD's to prevent electrocution, shocks & any interruption to supply Staff trained in the safe use of electrical equipment Regular PAT Testing & checks in accordance with Provision & Use of Equipment at Work Regs. 1998 Masking to supply points and data ports.
Noise Damage to Site / Mall	Beaver Personnel Site Premises Fixtures & Fittings	LOW	 Noise levels monitored - ear plugs provided Filtration to sedimentation tanks to prevent suspended calcium deposits from blocking drains All due care and protective measures taken to ensure no
			 splashing or impact damage to fixtures & fittings Extra care and protective measures to be taken when working Mallside to ensure no splashing or damage to Mall floor Mallside area to be inspected & signed off by Supervisor when works completed.