


## FTSW SUPPLY UPDATE

- 1. Change 680/2W, R131, at 6-32 to 1K/2W.
- 2. Change 4704/16v cap at F-34, C9, to 33004/16v (glue on top of board)
- 3. Check R115 at F-35, 330 ohms.
- 4. Voltage at c9 should be 8-10 v DC, Rhythm mode, 3 v DC Lead



DROD OLD PARTS SUT MOUT