Sentinel Safety

See Risk. Prevent Harm.

Overview

An inspection identified a condition involving no fire extinguisher in the man lift.

Risk Evaluation

The condition presents a medium risk to personnel and site operations, requiring timely corrective action.

Standards

No specific regulatory standard was automatically identified. A compliance review is recommended.

Corrective Actions

Recommended corrective action should be implemented to address the identified hazard and restore compliance.

Compliance Note

Final compliance determination should be made by a qualified safety professional in accordance with MSHA/OSHA regulations.