

INSITE

Inspection Report

Field Safety Inspection Record

Multi-observation site 1787153191692

Full Inspection

Inspection date: August 19, 2026

Inspector: Multi Observation

Findings documented: 4

Report generated: August 19, 2026

Executive Summary

4

FINDINGS

2

CRITICAL / HIGH

4

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		1
High		1
Moderate		2
Low		0

INSPECTION RECORD

SITE / FACILITY

Multi-observation site 1787153191692

INSPECTION

Full Inspection

INSPECTION DATE

August 19, 2026

INSPECTOR

Multi Observation

REGULATORY CONTEXT

Not established

ASSESSMENT

This inspection documented 4 findings: 1 Critical, 1 High, 2 Moderate. 2 findings rated Critical or High require prioritized corrective action and should be assigned an owner and a closure date without delay. 4 corrective actions were logged for this inspection, of which 4 remain open.

BASIS AND LIMITATIONS

Regulatory context: Not established — HazLenz evaluated standards as conditional candidates unless the observation itself established the governing agency. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Egress	Moderate	Finalized	Open
2	Machine Guarding	Critical	Finalized	Open
3	Electrical	High	Finalized	Open
4	Hot Work	Moderate	Finalized	Open

Detailed Findings

Finding 1 — Egress

WHAT WAS OBSERVED

in the north warehouse aisle the emergency exit door is blocked by three stacked pallets

Risk: **Moderate**

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

29 CFR 1910.37(a)(3) — Candidate requirements related to emergency preparedness.

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Immediate hazard control required to prevent contact/exposure to Egress hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: High

Assigned To: Multi Observation

NOTES

Finding 2 — Machine Guarding

WHAT WAS OBSERVED

in the maintenance bay the belt guard on the air compressor drive is missing

Risk: **Critical**

Severity 4 · Likelihood 4 · Risk score 16

APPLICABLE STANDARD

30 CFR 56.14107(a)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ISO / ANSI Consensus Standards - ISO 13857 / ANSI B11.19)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

Finding 2 — Machine Guarding (continued)

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 1

Immediate: Keep the equipment out of service and restrict access to the point of operation.

Permanent: Install or restore guarding that prevents access to the moving hazard during operation and foreseeable tasks.

Verification: Test the guard and document that access to the moving hazard is prevented.

Status: Open · Priority: High

Assigned To: Multi Observation

NOTES

Finding 3 — Electrical

WHAT WAS OBSERVED

a portable extension cord powering a bench grinder has exposed copper conductors

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

A portable extension cord powering a bench grinder has exposed copper conductors and remains energized where employees are working.

Risk: **High**

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

29 CFR 1910.303 — OSHA General Industry live electrical parts

HazLenz standard summary: Candidate only, qualified review required: Candidate only; missing: general-industry jurisdiction.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 3

Immediate: Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.

Permanent: Repair or replace the electrical component with appropriately rated equipment and verify the installation.

Verification: Have a qualified person document the electrical inspection before returning the equipment to service.

Status: Open · Priority: High

Finding 3 — Electrical (continued)

Assigned To: Multi Observation

NOTES

Finding 4 — Hot Work

WHAT WAS OBSERVED

a portable extension cord powering a bench grinder has exposed copper conductors and remains energized where employees are working.

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

A portable extension cord powering a bench grinder has exposed copper conductors and remains energized where employees are working.

Risk: **Moderate**

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

30 CFR 56.12025 — MSHA electrical grounding and continuity

HazLenz standard summary: Candidate only, qualified review required: Candidate only; missing: MSHA jurisdiction, conductive contact pathway.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 4

Immediate: Pause hot work until fire-prevention controls, combustible separation, and fire watch are verified.

Permanent: Implement the applicable hot-work permit, fire prevention, and post-work monitoring controls.

Verification: Verify hot-work controls and fire-watch records before resuming the operation.

Status: Open · Priority: High

Assigned To: Multi Observation

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#2	Keep the equipment out of service and restrict access to the point of operation.	Multi Observation	—	Open
#1	Immediate hazard control required to prevent contact/exposure to Egress hazard.	Multi Observation	—	Open
#3	Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.	Multi Observation	—	Open
#4	Pause hot work until fire-prevention controls, combustible separation, and fire watch are verified.	Multi Observation	—	Open