

INSITE

Inspection Report

Field Safety Inspection Record

Riverside Bridge Deck Project

Full Inspection

Inspection date: August 18, 2026

Inspector: Riley Okafor

Findings documented: 3

Report generated: August 18, 2026

Executive Summary

METRIC	VALUE
Total findings	3
Critical / High risk findings	1
Open corrective actions	3
Inspection status	Completed

Risk Distribution

Critical		0
High		1
Moderate		2
Low		0

Summary

This inspection identified findings requiring prioritized corrective action. Critical and High findings should be assigned an owner and closure date without delay.

Inspection Information

FIELD	DETAIL
Site / facility	Riverside Bridge Deck Project
Inspection	Full Inspection
Inspection date	August 18, 2026
Inspector	Riley Okafor
Status	Completed
Regulatory context	OSHA - Construction (29 CFR 1926), set for this inspection

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Egress	Moderate	Finalized	Open
2	Electrical	High	Finalized	Open
3	Hazard Communication	Moderate	Finalized	Open

Detailed Findings

Finding 1 — Egress

WHAT WAS OBSERVED

the ground-floor exit door is chained shut

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the occupied building under renovation, the ground-floor exit door is chained shut while twelve workers are on shift. A 5-gallon container of solvent in the paint room has no label identifying its contents or hazards. Manual finding: the extension cord powering the chop saw has exposed copper conductors and remains energized where laborers are working.

RISK

MODERATE

Severity 2 · Likelihood 3 · Score 6

APPLICABLE STANDARD

29 CFR 1926.34(a) — Means of egress - General

HazLenz standard summary: In every building or structure on a construction site, exits must be so arranged and maintained as to provide free and unobstructed egress from all parts of the building or structure at all times when it is occupied (29 CFR 1926.34(a)); means of egress must be continually maintained free of all obstructions or impediments to full instant use in case of fire or other emergency (1926.34(c)). HazLenz basis: Supported by submitted evidence for OSHA Construction means of egress; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 1

Immediate: Immediate hazard control required to prevent contact/exposure to Egress hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: High

Finding 2 — Electrical

WHAT WAS OBSERVED

manual finding: the extension cord powering the chop saw has exposed copper conductors

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the occupied building under renovation, the ground-floor exit door is chained shut while twelve workers are on shift. A 5-gallon container of solvent in the paint room has no label identifying its contents or hazards. Manual finding: the extension cord powering the chop saw has exposed copper conductors and remains energized where laborers are working.

RISK

HIGH

Severity 4 · Likelihood 3 · Score 12

APPLICABLE STANDARD

29 CFR 1926.416(a)(1) — Electrical safety-related work practices - General requirements: protection of employees from contact with electric power circuits

HazLenz standard summary: No employer may permit an employee to work in such proximity to any part of an electric power circuit that the employee could contact the circuit in the course of work, unless the employee is protected against electric shock by deenergizing the circuit and grounding it, or by guarding it effectively by insulation or other means (29 CFR 1926.416(a)(1)). HazLenz basis: Supported by submitted evidence for OSHA Construction electric power circuit contact protection; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.

Permanent: Repair or replace the electrical component with appropriately rated equipment and verify the installation.

Verification: Have a qualified person document the electrical inspection before returning the equipment to service.

Status: Open · Priority: High

Finding 3 — Hazard Communication

WHAT WAS OBSERVED

a 5-gallon container of solvent in the paint room has no label identifying its contents or hazards.

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the occupied building under renovation, the ground-floor exit door is chained shut while twelve workers are on shift. A 5-gallon container of solvent in the paint room has no label identifying its contents or hazards. Manual finding: the extension cord powering the chop saw has exposed copper conductors and remains energized where laborers are working.

RISK

MODERATE

Severity 2 · Likelihood 3 · Score 6

APPLICABLE STANDARD

29 CFR 1926.59 — Hazard Communication

HazLenz standard summary: The hazard communication requirements applicable to construction work under 29 CFR 1926.59 are identical to those set forth at 29 CFR 1910.1200: containers of hazardous chemicals in the workplace must be labeled with the product identifier and hazard information, and employers must maintain the hazard communication program, safety data sheets, and training that 1910.1200 requires. HazLenz basis: Supported by submitted evidence for OSHA Construction hazard communication (identical to 1910.1200); qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 3

Immediate: Immediate hazard control required to prevent contact/exposure to Hazard Communication hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: High

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Immediate hazard control required to prevent contact/exposure to Egress hazard.	Unassigned	—	Open
#2	Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.	Unassigned	—	Open
#3	Immediate hazard control required to prevent contact/exposure to Hazard Communication hazard.	Unassigned	—	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.