

INSITE

Inspection Report

Field Safety Inspection Record

Riverside Bridge Deck Project

Full Inspection

Inspection date: August 18, 2026

Inspector: Riley Okafor

Findings documented: 2

Report generated: August 18, 2026

Executive Summary

METRIC	VALUE
Total findings	2
Critical / High risk findings	1
Open corrective actions	2
Inspection status	Completed

Risk Distribution

Critical	0
High	1
Moderate	1
Low	0

Summary

This inspection identified findings requiring prioritized corrective action. Critical and High findings should be assigned an owner and closure date without delay.

Inspection Information

FIELD	DETAIL
Site / facility	Riverside Bridge Deck Project
Inspection	Full Inspection
Inspection date	August 18, 2026
Inspector	Riley Okafor
Status	Completed
Regulatory context	OSHA - General Industry (29 CFR 1910), set for this inspection

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Electrical	Moderate	Finalized	Open
2	Lockout Tagout	High	Finalized	Open

Detailed Findings

Finding 1 — Electrical

WHAT WAS OBSERVED

manual finding: the extension cord feeding the shrink-wrap station has exposed copper conductors

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

A packaging line mechanic is servicing the case sealer with power connected and no lock or tag applied while the belt is capable of starting. Manual finding: the extension cord feeding the shrink-wrap station has exposed copper conductors and is still plugged in.

RISK

MODERATE

APPLICABLE STANDARD

29 CFR 1910.303 — OSHA General Industry live electrical parts

HazLenz standard summary: Supported by submitted evidence for OSHA General Industry live electrical parts; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 1

Immediate: Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.

Permanent: Repair or replace the electrical component with appropriately rated equipment and verify the installation.

Verification: Have a qualified person document the electrical inspection before returning the equipment to service.

Status: Open · Priority: Urgent

Finding 2 — Lockout Tagout

WHAT WAS OBSERVED

a packaging line mechanic is servicing the case sealer with power connected and no lock or tag applied while the belt is capable of starting.

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

A packaging line mechanic is servicing the case sealer with power connected and no lock or tag applied while the belt is capable of starting. Manual finding: the extension cord feeding the shrink-wrap station has exposed copper conductors and is still plugged in.

RISK

HIGH

APPLICABLE STANDARD

29 CFR 1910.147 — OSHA General Industry hazardous energy control

HazLenz standard summary: Supported by submitted evidence for OSHA General Industry hazardous energy control; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Isolate the affected extension cord from service and route damaged electrical-integrity concerns for qualified review before reuse.

Permanent: Replace damaged wiring assemblies with rated replacement components appropriate for the affected equipment and environment to ensure continuous, safe electrical-integrity barriers.

Verification: Perform a formal inspection and functional verification by a competent person before removing interim controls or resuming normal operations.

Status: Open · Priority: Urgent

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.	Unassigned	—	Open
#2	Isolate the affected extension cord from service and route damaged electrical-integrity concerns for qualified review before reuse.	Unassigned	—	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.