

INSITE

Inspection Report

Field Safety Inspection Record

Riverside Bridge Deck Project

Full Inspection

Inspection date: August 18, 2026

Inspector: Riley Okafor

Findings documented: 2

Report generated: August 18, 2026

Executive Summary

METRIC	VALUE
Total findings	2
Critical / High risk findings	2
Open corrective actions	2
Inspection status	Completed

Risk Distribution

Critical		1
High		1
Moderate		0
Low		0

Summary

This inspection identified findings requiring prioritized corrective action. Critical and High findings should be assigned an owner and closure date without delay.

Inspection Information

FIELD	DETAIL
Site / facility	Riverside Bridge Deck Project
Inspection	Full Inspection
Inspection date	August 18, 2026
Inspector	Riley Okafor
Status	Completed
Regulatory context	MSHA (30 CFR), set for this inspection

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	Critical	Finalized	Open
2	Lockout Tagout	High	Finalized	Open

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

the guard on the secondary crusher conveyor tail pulley is missing

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The guard on the secondary crusher conveyor tail pulley is missing, exposing miners walking the travelway to the moving parts.
Manual finding: a miner is servicing the screen deck drive with power connected and no lock or tag applied.

RISK

CRITICAL

Severity 4 · Likelihood 4 · Score 16

APPLICABLE STANDARD

30 CFR 56.14107(a) — MSHA moving machine parts guarding

HazLenz standard summary: Supported by submitted evidence for MSHA moving machine parts guarding; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 1

Immediate: Keep the equipment out of service and restrict access to the point of operation.

Permanent: Install or restore guarding that prevents access to the moving hazard during operation and foreseeable tasks.

Verification: Test the guard and document that access to the moving hazard is prevented.

Status: Open · Priority: Urgent

Finding 2 — Lockout Tagout

WHAT WAS OBSERVED

manual finding: a miner is servicing the screen deck drive with power connected and no lock or tag applied.

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The guard on the secondary crusher conveyor tail pulley is missing, exposing miners walking the travelway to the moving parts.
Manual finding: a miner is servicing the screen deck drive with power connected and no lock or tag applied.

RISK

HIGH

Severity 4 · Likelihood 3 · Score 12

APPLICABLE STANDARD

30 CFR 56.12016 — MSHA energy control

HazLenz standard summary: Supported by submitted evidence for MSHA energy control; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Stop servicing and control hazardous energy before anyone enters the danger zone.

Permanent: Implement the applicable energy-control procedure with isolation, lockout, release of stored energy, and verification.

Verification: Document zero-energy verification before returning the equipment to service.

Status: Open · Priority: Urgent

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Keep the equipment out of service and restrict access to the point of operation.	Unassigned	—	Open
#2	Stop servicing and control hazardous energy before anyone enters the danger zone.	Unassigned	—	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.