

INSITE

Inspection Report

Field Safety Inspection Record

Riverside Bridge Deck Project

Full Inspection

Inspection date: August 18, 2026

Inspector: Riley Okafor

Findings documented: 2

Report generated: August 18, 2026

Executive Summary

2

FINDINGS

2

CRITICAL / HIGH

2

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		1
High		1
Moderate		0
Low		0

INSPECTION RECORD

SITE / FACILITY

Riverside Bridge Deck Project

INSPECTION

Full Inspection

INSPECTION DATE

August 18, 2026

INSPECTOR

Riley Okafor

REGULATORY CONTEXT

MSHA (30 CFR)

ASSESSMENT

This inspection documented 2 findings: 1 Critical, 1 High. 2 findings rated Critical or High require prioritized corrective action and should be assigned an owner and a closure date without delay. 2 corrective actions were logged for this inspection, of which 2 remain open.

BASIS AND LIMITATIONS

Regulatory context: MSHA (30 CFR) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	Critical	Finalized	Open
2	Lockout Tagout	High	Finalized	Open

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

the guard on the secondary crusher conveyor tail pulley is missing

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The guard on the secondary crusher conveyor tail pulley is missing, exposing miners walking the travelway to the moving parts.

Manual finding: a miner is servicing the screen deck drive with power connected and no lock or tag applied.

Risk: **Critical**

Severity 4 · Likelihood 4 · Risk score 16

APPLICABLE STANDARD

30 CFR 56.14107(a) — MSHA moving machine parts guarding

HazLenz standard summary: Supported by submitted evidence for MSHA moving machine parts guarding; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 1

Immediate: Keep the equipment out of service and restrict access to the point of operation.

Permanent: Install or restore guarding that prevents access to the moving hazard during operation and foreseeable tasks.

Verification: Test the guard and document that access to the moving hazard is prevented.

Status: Open · Priority: Urgent

Assigned To: Riley Okafor

NOTES

Finding 2 — Lockout Tagout

WHAT WAS OBSERVED

manual finding: a miner is servicing the screen deck drive with power connected and no lock or tag applied.

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The guard on the secondary crusher conveyor tail pulley is missing, exposing miners walking the travelway to the moving parts.

Manual finding: a miner is servicing the screen deck drive with power connected and no lock or tag applied.

Risk: **High**

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

30 CFR 56.12016 — MSHA energy control

Finding 2 — Lockout Tagout (continued)

HazLenz standard summary: Supported by submitted evidence for MSHA energy control; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Stop servicing and control hazardous energy before anyone enters the danger zone.

Permanent: Implement the applicable energy-control procedure with isolation, lockout, release of stored energy, and verification.

Verification: Document zero-energy verification before returning the equipment to service.

Status: Open · Priority: Urgent

Assigned To: Riley Okafor

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Keep the equipment out of service and restrict access to the point of operation.	Riley Okafor	—	Open
#2	Stop servicing and control hazardous energy before anyone enters the danger zone.	Riley Okafor	—	Open