

INSITE

Inspection Report

Field Safety Inspection Record

Riverside Bridge Deck Project

Post-semantics-fix report verification

Inspection date: August 18, 2026

Inspector: Riley Okafor

Findings documented: 3

Report generated: August 18, 2026

Executive Summary

3

FINDINGS

2

CRITICAL / HIGH

3

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		0
High		2
Moderate		1
Low		0

INSPECTION RECORD

SITE / FACILITY

Riverside Bridge Deck Project

INSPECTION

Post-semantics-fix report verification

INSPECTION DATE

August 18, 2026

INSPECTOR

Riley Okafor

REGULATORY CONTEXT

OSHA - General Industry (29 CFR 1910)

ASSESSMENT

This inspection documented 3 findings: 2 High, 1 Moderate. 2 findings rated Critical or High require prioritized corrective action and should be assigned an owner and a closure date without delay. 3 corrective actions were logged for this inspection, of which 3 remain open.

BASIS AND LIMITATIONS

Regulatory context: OSHA - General Industry (29 CFR 1910) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	High	Finalized	Open
2	Lockout Tagout	High	Finalized	Open
3	Egress	Moderate	Finalized	Open

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

the interlock guard on the press brake is installed but has been bypassed with a jumper wire so the machine runs with the guard open

Risk: **High**

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

Not established for this specific finding.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 1

Immediate: Keep the equipment out of service and restrict access to the point of operation.

Permanent: Install or restore guarding that prevents access to the moving hazard during operation and foreseeable tasks.

Verification: Test the guard and document that access to the moving hazard is prevented.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 2 — Lockout Tagout

WHAT WAS OBSERVED

but the disconnect was found in the on position. no lock or tag was present on it

Risk: **High**

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

Not established for this specific finding.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Stop servicing and control hazardous energy before anyone enters the danger zone.

Finding 2 — Lockout Tagout (continued)

Permanent: Implement the applicable energy-control procedure with isolation, lockout, release of stored energy, and verification.

Verification: Document zero-energy verification before returning the equipment to service.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 3 — Egress

WHAT WAS OBSERVED

exit door by shipping blocked w/ pallets abt 4 high

Risk: **Moderate**

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

29 CFR 1910.37(a)(3) — Candidate requirements related to emergency preparedness.

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 3

Immediate: Immediate hazard control required to prevent contact/exposure to Egress hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Keep the equipment out of service and restrict access to the point of operation.	Riley Okafor	—	Open
#2	Stop servicing and control hazardous energy before anyone enters the danger zone.	Riley Okafor	—	Open
#3	Immediate hazard control required to prevent contact/exposure to Egress hazard.	Riley Okafor	—	Open