

SAFETY INSITE

# Inspection Report

Field Safety Inspection Record

---

## Northline Plant 2

§286 S — S5 multiple findings with different severities

Inspection date: September 14, 2026

Inspector: Review 286 Pro

Findings documented: 3

Report generated: September 14, 2026

# Executive Summary

3

FINDINGS

2

CRITICAL / HIGH

3

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

|          |             |   |
|----------|-------------|---|
| Critical | <div></div> | 1 |
| High     | <div></div> | 1 |
| Moderate | <div></div> | 1 |
| Low      | <div></div> | 0 |

INSPECTION RECORD

SITE / FACILITY

Northline Plant 2

INSPECTION

\$286 S — S5 multiple findings with different...

INSPECTION DATE

September 14, 2026

INSPECTOR

Review 286 Pro

REGULATORY CONTEXT

OSHA - General Industry (29 CFR 1910)

ASSESSMENT

This inspection documented 3 findings: 1 Critical, 1 High, 1 Moderate. 2 findings rated Critical or High require prioritized corrective action and should be assigned an owner and a closure date without delay. 3 corrective actions were logged for this inspection, of which 3 remain open.

BASIS AND LIMITATIONS

Regulatory context: OSHA - General Industry (29 CFR 1910) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

# Findings Summary

Concise reference of every finding documented in this inspection.

| # | HAZARD           | RISK     | STATUS    | ACTION STATUS |
|---|------------------|----------|-----------|---------------|
| 1 | Machine Guarding | Critical | Finalized | Open          |
| 2 | Electrical       | High     | Finalized | Open          |
| 3 | Lockout Tagout   | Moderate | Finalized | Open          |

## Detailed Findings

---

### Finding 1 — Machine Guarding

#### WHAT WAS OBSERVED

Fixed guard removed from the conveyor nip point while the belt was running.

#### FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

Three separate defects on one walk: the conveyor nip guard is off, a damaged extension cord crosses the walkway, and the lockout box at the press is empty.

**Risk:** **Critical**

Severity Major · Likelihood Frequent · Reviewer-confirmed

#### APPLICABLE STANDARD

*Not established for this specific finding.*

#### QUALIFIED-PERSON REVIEW

Accepted — Confirmed on the matrix by the qualified person reviewing this finding.

#### RECOMMENDED CORRECTIVE ACTION

##### Control Machine Guarding Exposure

Immediate: Immediate hazard control required to prevent contact/exposure to Machine Guarding hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Urgent

**Assigned To:** \_\_\_\_\_

#### NOTES

---

---

---

---

### Finding 2 — Electrical

#### WHAT WAS OBSERVED

Split strain relief exposing inner conductors on an energised extension cord.

#### FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

Three separate defects on one walk: the conveyor nip guard is off, a damaged extension cord crosses the walkway, and the lockout box at the press is empty.

**Risk:** **High**

Severity Moderate · Likelihood Frequent · Reviewer-confirmed

#### APPLICABLE STANDARD

*Not established for this specific finding.*

#### QUALIFIED-PERSON REVIEW

Accepted — Confirmed on the matrix by the qualified person reviewing this finding.

*Finding 2 — Electrical (continued)*

**RECOMMENDED CORRECTIVE ACTION**

**Control Electrical Exposure**

Immediate: Immediate hazard control required to prevent contact/exposure to Electrical hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Urgent

**Assigned To:** \_\_\_\_\_

**NOTES**

---

---

---

---

**Finding 3 — Lockout Tagout**

**WHAT WAS OBSERVED**

Lockout box at the press was empty; no locks or tags available.

**FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)**

Three separate defects on one walk: the conveyor nip guard is off, a damaged extension cord crosses the walkway, and the lockout box at the press is empty.

**Risk:** **Moderate**  
Severity Minor · Likelihood Frequent · Reviewer-confirmed · HazLenz analysis: High

**APPLICABLE STANDARD**

*Not established for this specific finding.*

**QUALIFIED-PERSON REVIEW**

Accepted — Confirmed on the matrix by the qualified person reviewing this finding.

**RECOMMENDED CORRECTIVE ACTION**

**Control Lockout Tagout Exposure**

Immediate: Immediate hazard control required to prevent contact/exposure to Lockout Tagout hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Urgent

**Assigned To:** \_\_\_\_\_

**NOTES**

---

---

---

# Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

| FINDING | ACTION                            | OWNER      | DUE | STATUS |
|---------|-----------------------------------|------------|-----|--------|
| #1      | Control Machine Guarding Exposure | Unassigned | —   | Open   |
| #2      | Control Electrical Exposure       | Unassigned | —   | Open   |
| #3      | Control Lockout Tagout Exposure   | Unassigned | —   | Open   |