

SAFETY INSITE

Inspection Report

Field Safety Inspection Record

VALIDATION-276-W6 Fabrication Bay

Full Inspection

Inspection date: September 13, 2026

Inspector: Validation 276 a

Findings documented: 2

Report generated: September 13, 2026

Executive Summary

2

FINDINGS

2

CRITICAL / HIGH

2

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		0
High		2
Moderate		0
Low		0

INSPECTION RECORD

SITE / FACILITY

VALIDATION-276-W6 Fabrication Bay

INSPECTION

Full Inspection

INSPECTION DATE

September 13, 2026

INSPECTOR

Validation 276 a

REGULATORY CONTEXT

OSHA - General Industry (29 CFR 1910)

ASSESSMENT

This inspection documented 2 findings: 2 High. 2 findings rated Critical or High require prioritized corrective action and should be assigned an owner and a closure date without delay. 2 corrective actions were logged for this inspection, of which 2 remain open.

BASIS AND LIMITATIONS

Regulatory context: OSHA - General Industry (29 CFR 1910) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	High	Finalized	Open
2	Machine Guarding	High	Finalized	Open

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

the point of operation guard on the 60-ton punch press in the fabrication bay has been removed

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The point of operation guard on the 60-ton punch press in the fabrication bay has been removed and is sitting on the floor beside the machine. The press is energized and cycling on production parts, and the operator's hands enter the die area between strokes to reposition the blank. There is no light curtain or two-hand control fitted.

Risk:

High

Severity 4 · Likelihood 3 · Risk score 12 · Reviewer-confirmed

APPLICABLE STANDARD

29 CFR 1910.212(a)(1) — OSHA General Industry machine guarding

HazLenz standard summary: Supported by submitted evidence for OSHA General Industry machine guarding; qualified review remains required.

QUALIFIED-PERSON REVIEW

Edited — Hands enter the die area every cycle, so likelihood is higher than the proposal.

RECOMMENDED CORRECTIVE ACTION

VALIDATION-276-GAP-1789330038072 replayed action

replayed

Due: 09/19/2026 · Status: Open · Priority: Medium

Assigned To:

NOTES

Finding 2 — Machine Guarding

WHAT WAS OBSERVED

there is no light curtain or two-hand control fitted

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The point of operation guard on the 60-ton punch press in the fabrication bay has been removed and is sitting on the floor beside the machine. The press is energized and cycling on production parts, and the operator's hands enter the die area between strokes to reposition the blank. There is no light curtain or two-hand control fitted.

Risk:

High

Severity 4 · Likelihood 4 · Risk score 16 · Reviewer-confirmed · HazLenz analysis: Critical

APPLICABLE STANDARD

Not established for this specific finding.

Finding 2 — Machine Guarding (continued)

QUALIFIED-PERSON REVIEW

Edited — Reviewer-confirmed on the Standard 5x5 matrix: severity 4 x likelihood 4 = 16.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Control Machine Guarding Exposure: Immediate hazard control required to prevent contact/exposure to Machine Guarding hazard.

Permanent:

Verification:

Due: 09/16/2026 · Status: Open · Priority: Urgent

Assigned To: _____

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#2	Control Machine Guarding Exposure: Immediate hazard control required to prevent contact/exposure to Machine Guarding hazard.	Unassigned	09/16/2026	Open
#1	VALIDATION-276- GAP-1789330038072 replayed action	Unassigned	09/19/2026	Open