

INSITE

Inspection Report

Field Safety Inspection Record

Browser E2E Closure Site

Full Inspection

Inspection date: August 16, 2026

Inspector: matrix-closure

Findings documented: 4

Report generated: August 16, 2026

Executive Summary

METRIC	VALUE
Total findings	4
Critical / High risk findings	3
Open corrective actions	4
Inspection status	Completed

Risk Distribution

Critical		2
High		1
Moderate		1
Low		0

Summary

This inspection identified findings requiring prioritized corrective action. Critical and High findings should be assigned an owner and closure date without delay.

Inspection Information

FIELD	DETAIL
Site / facility	Browser E2E Closure Site
Inspection	Full Inspection
Inspection date	August 16, 2026
Inspector	matrix-closure
Status	Completed

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	Critical	Finalized	Open
2	Hydraulic Pneumatic Energy	Moderate	Finalized	Open
3	Electrical	Critical	Finalized	Open
4	Fall Protection	High	Finalized	Open

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

An employee reached through an unguarded rotating pulley on a running conveyor drive while a nearby open junction box had exposed live parts with stripped insulation and bare conductors. Hydraulic pressure remained in a nearby baler ram. An unprotected edge on the loading dock had no guardrail. The nearby emergency shower was inspected and is fully functional with no deficiencies noted.

FINDING

conveyor

RISK

CRITICAL

APPLICABLE STANDARD

30 CFR 56.14107(a)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ISO / ANSI Consensus Standards - ISO 13857 / ANSI B11.19)

QUALIFIED-PERSON REVIEW

Edited — Exposed energized bus/conductors confirmed reachable during direct inspection; escalating from proposed Moderate to Critical.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 1

Immediate: Keep the equipment out of service and restrict access to the point of operation.

Permanent: Install or restore guarding that prevents access to the moving hazard during operation and foreseeable tasks.

Verification: Test the guard and document that access to the moving hazard is prevented.

Status: Open · Priority: Urgent

Finding 2 — Hydraulic Pneumatic Energy

WHAT WAS OBSERVED

An employee reached through an unguarded rotating pulley on a running conveyor drive while a nearby open junction box had exposed live parts with stripped insulation and bare conductors. Hydraulic pressure remained in a nearby baler ram. An unprotected edge on the loading dock had no guardrail. The nearby emergency shower was inspected and is fully functional with no deficiencies noted.

FINDING

hazardous hydraulic/pneumatic stored energy

RISK

MODERATE

APPLICABLE STANDARD

30 CFR 56.14107(a)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ISO / ANSI Consensus Standards - ISO 13857 / ANSI B11.19)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Stop servicing and control hazardous energy before anyone enters the danger zone.

Permanent: Implement the applicable energy-control procedure with isolation, lockout, release of stored energy, and verification.

Verification: Document zero-energy verification before returning the equipment to service.

Status: Open · Priority: Urgent

Finding 3 — Electrical

WHAT WAS OBSERVED

An employee reached through an unguarded rotating pulley on a running conveyor drive while a nearby open junction box had exposed live parts with stripped insulation and bare conductors. Hydraulic pressure remained in a nearby baler ram. An unprotected edge on the loading dock had no guardrail. The nearby emergency shower was inspected and is fully functional with no deficiencies noted.

FINDING

energized accessible electrical parts

RISK

CRITICAL

APPLICABLE STANDARD

30 CFR 56.14107(a)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ISO / ANSI Consensus Standards - ISO 13857 / ANSI B11.19)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 3

Immediate: Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.

Permanent: Repair or replace the electrical component with appropriately rated equipment and verify the installation.

Verification: Have a qualified person document the electrical inspection before returning the equipment to service.

Status: Open · Priority: Urgent

Finding 4 — Fall Protection

WHAT WAS OBSERVED

An employee reached through an unguarded rotating pulley on a running conveyor drive while a nearby open junction box had exposed live parts with stripped insulation and bare conductors. Hydraulic pressure remained in a nearby baler ram. An unprotected edge on the loading dock had no guardrail. The nearby emergency shower was inspected and is fully functional with no deficiencies noted.

FINDING

edge

RISK

HIGH

APPLICABLE STANDARD

30 CFR 56.14107(a)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ISO / ANSI Consensus Standards - ISO 13857 / ANSI B11.19)

QUALIFIED-PERSON REVIEW

Edited — Unprotected loading dock edge, fall distance material; escalating to High per fall-protection auto risk.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 4

Immediate: Restrict access to the elevated exposure and stop the task until compliant fall protection is verified.

Permanent: Provide and maintain a compliant guardrail, personal fall-arrest system, or other approved fall control for the work area.

Verification: Verify the fall-control system and access route before resuming work.

Status: Open · Priority: Urgent

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Verify and correct reviewed condition 1	Unassigned	—	Open
#2	Verify and correct reviewed condition 2	Unassigned	—	Open
#3	Verify and correct reviewed condition 3	Unassigned	—	Open
#4	Verify and correct reviewed condition 4	Unassigned	—	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.