

INSITE

Inspection Report

Field Safety Inspection Record

Closure Report B 1786925553290

Closure Report B 1786925553290

Inspection date: August 16, 2026

Inspector: matrix-closure

Findings documented: 3

Report generated: August 16, 2026

Executive Summary

METRIC	VALUE
Total findings	3
Critical / High risk findings	0
Open corrective actions	3
Inspection status	Completed

Risk Distribution

Critical	0
High	0
Moderate	0
Low	0

3 finding(s) do not yet have an established risk rating.

Summary

Findings from this inspection are currently rated low risk based on available evidence and should still be tracked through closure.

Inspection Information

FIELD	DETAIL
Site / facility	Closure Report B 1786925553290
Inspection	Closure Report B 1786925553290
Inspection date	August 16, 2026
Inspector	matrix-closure
Status	Completed

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Hazardous Energy	Not rated	Finalized	Open
2	Electrical	Not rated	Finalized	Open
3	Fall Protection	Not rated	Finalized	Open

Detailed Findings

Finding 1 — Hazardous Energy

WHAT WAS OBSERVED

A mechanic reached into the baler to clear a jam while hydraulic pressure remained in the ram, a nearby open junction box had exposed live parts, and an unprotected edge on the loading dock had no guardrail.

FINDING

Apply lockout/tagout and verify zero energy before servicing the baler ram.

QUALIFIED-PERSON REVIEW

Accepted — Confirmed during direct inspection: A mechanic reached into the baler to clear a jam while hydraulic pressure remain

RECOMMENDED CORRECTIVE ACTION

Apply LOTO to baler hydraulic system

Apply lockout/tagout and verify zero energy before servicing the baler ram.

Due: 08/31/2026 · Status: Open · Priority: High

Finding 2 — Electrical

WHAT WAS OBSERVED

A mechanic reached into the baler to clear a jam while hydraulic pressure remained in the ram, a nearby open junction box had exposed live parts, and an unprotected edge on the loading dock had no guardrail.

FINDING

De-energize and cover the open junction box; replace missing cover plate.

QUALIFIED-PERSON REVIEW

Accepted — Confirmed during direct inspection: A mechanic reached into the baler to clear a jam while hydraulic pressure remain

RECOMMENDED CORRECTIVE ACTION

Cover exposed junction box

De-energize and cover the open junction box; replace missing cover plate.

Due: 08/31/2026 · Status: Open · Priority: High

Finding 3 — Fall Protection

WHAT WAS OBSERVED

A mechanic reached into the baler to clear a jam while hydraulic pressure remained in the ram, a nearby open junction box had exposed live parts, and an unprotected edge on the loading dock had no guardrail.

FINDING

Install guardrail or equivalent edge protection at the loading dock.

QUALIFIED-PERSON REVIEW

Accepted — Confirmed during direct inspection: A mechanic reached into the baler to clear a jam while hydraulic pressure remain

RECOMMENDED CORRECTIVE ACTION

Install loading dock guardrail

Install guardrail or equivalent edge protection at the loading dock.

Due: 08/31/2026 · Status: Open · Priority: High

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Apply LOTO to baler hydraulic system	Unassigned	08/31/2026	Open
#2	Cover exposed junction box	Unassigned	08/31/2026	Open
#3	Install loading dock guardrail	Unassigned	08/31/2026	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.