

INSITE

Inspection Report

Field Safety Inspection Record

Risk-Standard Check 1786925659513

Risk-Standard Check 1786925659513

Inspection date: August 16, 2026

Inspector: matrix-closure

Findings documented: 1

Report generated: August 16, 2026

Executive Summary

METRIC	VALUE
Total findings	1
Critical / High risk findings	0
Open corrective actions	1
Inspection status	Completed

Risk Distribution

Critical	0
High	0
Moderate	0
Low	0

1 finding(s) do not yet have an established risk rating.

Summary

Findings from this inspection are currently rated low risk based on available evidence and should still be tracked through closure.

Inspection Information

FIELD	DETAIL
Site / facility	Risk-Standard Check 1786925659513
Inspection	Risk-Standard Check 1786925659513
Inspection date	August 16, 2026
Inspector	matrix-closure
Status	Completed

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Electrical	high	Finalized	Open

Detailed Findings

Finding 1 — Electrical

WHAT WAS OBSERVED

Exposed energized bus bars in an open electrical panel accessible to workers.

FINDING

De-energize and cover the panel immediately.

RISK

HIGH

APPLICABLE STANDARD

29 CFR 1910.303(g)(1) — Electrical — working space about equipment

QUALIFIED-PERSON REVIEW

Accepted — Confirmed exposed energized bus bars during direct inspection.

RECOMMENDED CORRECTIVE ACTION

De-energize and cover panel

De-energize and cover the panel immediately.

Due: 08/19/2026 · Status: Open · Priority: High

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	De-energize and cover panel	Unassigned	08/19/2026	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.