

INSITE

Inspection Report

Field Safety Inspection Record

Cascade Fabrication Works (mswc92jx)

ReportC — Cascade Fabrication Works

Inspection date: August 16, 2026

Inspector: Report P2 Tester

Findings documented: 7

Report generated: August 16, 2026

Executive Summary

METRIC	VALUE
Total findings	7
Critical / High risk findings	3
Open corrective actions	3
Inspection status	Completed

Risk Distribution

Critical		0
High		3
Moderate		4
Low		0

Summary

This inspection identified findings requiring prioritized corrective action. Critical and High findings should be assigned an owner and closure date without delay.

Inspection Information

FIELD	DETAIL
Site / facility	Cascade Fabrication Works (mswc92jx)
Inspection	ReportC — Cascade Fabrication Works
Inspection date	August 16, 2026
Inspector	Report P2 Tester
Status	Completed

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	High	Finalized	No action logged
2	Machine Guarding	High	Finalized	Open
3	Compressed Gas	High	Finalized	Open
4	Hot Work	Moderate	Finalized	No action logged
5	Housekeeping	Moderate	Finalized	No action logged
6	Egress	Moderate	Finalized	No action logged
7	Emergency Egress	Moderate	Finalized	Open

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. The point-of-operation guard interlock on Mill 3 was found bypassed with a zip tie, allowing the spindle to run with the guard door open. Operators reported this has been the case for approximately three weeks following a changeover procedure, and that a work order was submitted but not yet actioned by maintenance. Multiple operators across two shifts confirmed the same bypass condition, and no compensating controls (e.g., light curtains, presence-sensing devices) were in place at the time of observation.

FINDING

Additional hazard identified during decomposition: guard.

RISK

HIGH

Severity 4 · Likelihood 3 · Score 12

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

Finding 2 — Machine Guarding

WHAT WAS OBSERVED

During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. The point-of-operation guard interlock on Mill 3 was found bypassed with a zip tie, allowing the spindle to run with the guard door open. Operators reported this has been the case for approximately three weeks following a changeover procedure, and that a work order was submitted but not yet actioned by maintenance. Multiple operators across two shifts confirmed the same bypass condition, and no compensating controls (e.g., light curtains, presence-sensing devices) were in place at the time of observation.

FINDING

During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. During a full-shift walkthrough of the fabrication bay, the inspector observed a series of related conditions around the CNC mill cell. The interlock bypass constitutes a direct point-of-operation hazard during spindle rotation.

RISK

HIGH

Severity 4 · Likelihood 3 · Score 12

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

RECOMMENDED CORRECTIVE ACTION

Restore CNC Mill 3 point-of-operation interlock and remove bypass

Restore the point-of-operation interlock on Mill 3 to full working order and remove the zip-tie bypass immediately.
Restore the point-of-operation interlock on Mill 3 to full working order and remove the zip-tie bypass immediately.
Restore the point-of-operation interlock on Mill 3 to full working order and remove the zip-tie bypass immediately.
Restore the point-of-operation interlock on Mill 3 to full working order and remove the zip-tie bypass immediately. Verify interlock function with a documented functional test (guard-open spindle-stop confirmation) before returning the machine to production use. Notify all shifts operating this cell of the corrective action and confirm understanding via toolbox talk sign-off. Escalate to the plant safety committee if the same bypass pattern recurs on any other CNC cell within the next 90 days, and consider a engineering root-cause review of the changeover procedure that is prompting operators to bypass the interlock in the first place.

Owner: Plant Maintenance Supervisor · Due: 08/16/2026 · Status: Open · Priority: Urgent

Finding 3 — Compressed Gas

WHAT WAS OBSERVED

Compressed gas cylinders (oxygen and acetylene) stored together without separation and without secure chaining, near an active welding station.

FINDING

Oxygen and acetylene cylinders were stored together unchained and unseparated near an active ignition source, contrary to standard compressed-gas storage practice.

RISK

HIGH

Severity 4 · Likelihood 3 · Score 12

APPLICABLE STANDARD

29 CFR 1910.101(b)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

RECOMMENDED CORRECTIVE ACTION

Separate and secure compressed gas cylinders

Separate oxygen and fuel-gas cylinders by the required distance or fire-rated barrier, and secure all cylinders with chains or stands to prevent tipping.

Owner: Shop Supervisor · Due: 08/25/2026 · Status: Open · Priority: Medium

Finding 4 — Hot Work

WHAT WAS OBSERVED

Compressed gas cylinders (oxygen and acetylene) stored together without separation and without secure chaining, near an active welding station.

FINDING

Additional hazard identified during decomposition: hot_work.

RISK

MODERATE

Severity 2 · Likelihood 3 · Score 6

APPLICABLE STANDARD

29 CFR 1910.101(b)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

Finding 5 — Housekeeping

WHAT WAS OBSERVED

Housekeeping walkway near the receiving dock was obstructed with pallets and stretch-wrap debris, partially blocking a marked emergency egress route.

FINDING

Additional hazard identified during decomposition: debris.

RISK

MODERATE

Severity 2 · Likelihood 3 · Score 6

APPLICABLE STANDARD

30 CFR 56.20003(a)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

Finding 6 — Egress

WHAT WAS OBSERVED

Housekeeping walkway near the receiving dock was obstructed with pallets and stretch-wrap debris, partially blocking a marked emergency egress route.

FINDING

Additional hazard identified during decomposition: egress.

RISK

MODERATE

Severity 2 · Likelihood 3 · Score 6

APPLICABLE STANDARD

30 CFR 56.20003(a)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

Finding 7 — Emergency Egress

WHAT WAS OBSERVED

Housekeeping walkway near the receiving dock was obstructed with pallets and stretch-wrap debris, partially blocking a marked emergency egress route.

FINDING

Pallets and packaging debris were partially obstructing a marked emergency egress route near the receiving dock.

RISK

MODERATE

Severity 3 · Likelihood 3 · Score 9

APPLICABLE STANDARD

30 CFR 56.20003(a)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

RECOMMENDED CORRECTIVE ACTION

Clear obstructed egress route at receiving dock

Remove pallets and debris from the marked egress path and establish a daily housekeeping check for this area during receiving shifts.

Owner: Warehouse Lead · Due: 08/29/2026 · Status: Open · Priority: Low

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#2	Restore CNC Mill 3 point-of-operation interlock and remove bypass	Plant Maintenance Supervisor	08/16/2026	Open
#3	Separate and secure compressed gas cylinders	Shop Supervisor	08/25/2026	Open
#7	Clear obstructed egress route at receiving dock	Warehouse Lead	08/29/2026	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.