

Safety InSite Inspection Report

Inspection: Finding Review Browser Proof
Inspection ID: 1805f2d5-491b-4e8c-ab52-a07d1abaa68b
Version: 3
Completed: 2026-08-06T00:34:09.395Z

Observations and Findings

Observation: Damaged insulation on a live electrical panel is beside an open elevated edge on the mill platform. Workers can contact the electrical exposure and can fall from the unprotected edge; no compliant fall protection is visible.

Finding [electrical]: panel

Status: finalized

Finding [fall-protection]: edge

Status: finalized

Human review: accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

Human review: accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

Corrective Actions

Verify and correct reviewed condition 1 [finding e6e0067d-e2f1-4e95-8328-0846e68eae92] (open)

Immediate: Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.

Permanent: Repair or replace the electrical component with appropriately rated equipment and verify the installation.

Verification: Have a qualified person document the electrical inspection before returning the equipment to service.

Verify and correct reviewed condition 2 [finding cd87c150-60b6-402f-92ed-d7688d2a7ff3] (open)

Immediate: Restrict access to the elevated exposure and stop the task until compliant fall protection is verified.

Permanent: Provide and maintain a compliant guardrail, personal fall-arrest system, or other approved fall control for the work area.

Verification: Verify the fall-control system and access route before resuming work.

HazLenz output is advisory and requires qualified human review.