



SERVICE BULLETIN



SUBJECT: Humidity Sensors

BULLETIN NO: C 053

DATE: October 8, 2002

The following information relates to recent changes in the installed (or Service Parts) humidity sensors. The three sensors pictured all have the same elements, just different housings. The sensors have the same fit and function. The plastic housing is what is supplied today OEM and from Service Parts. Different sensors types are interchangeable.



Stainless housing with brass cap
P/N 41-2573



Stainless housing with stainless cap
P/N 41-2573



Plastic housing with plastic cap
P/N 41-4748

MGR



SALES



SERVICE



PARTS



USE ONLY **THERMO KING** FACTORY APPROVED REPLACEMENT PARTS

314 West 90th Street, Minneapolis, Minnesota 55420