




A wiring diagram for a ESP32 weather station featuring:
 DHT11 Humidity and Temp Sensor
 MAX31865 Temp converter connected to a PT100 RTD
 Hall Effect Sensor (x3)
 QMC5803P Compass
 Blue Status LED
 Red Fault LED
 Switch to turn of 3.3v Line from ESP32

Mepwoofer96

Sheet: /
 File: weather_station.kicad_sch

Title: Weather Station ESP32 Diagram

Size: A4	Date: 2026-07-16	Rev: 1
KiCad E.D.A. 9.0.9		Id: 1/1