VOLKSWAGEN

AKTIENGESELLSCHAFT

Diagnosedatentabelle Ereignisspeicher

NE, 0x03 Bremsenelektronik

Technische Entwicklung, Diagnosedokumentation

Autor	Anders, Peter
Abt./OE	EFBS/2 / 15080
Telefon	+49 5361 9 79847
Mobil	+49 5361 9 91048
Telefax	+49 5361 9 5779847
E-Mail	peter.anders@volkswagen.de

Erstausgabe	15.07.2008
Änderungsstand	29.03.2011
Modul-View	SPEC-GROUP for module 08 - RIF2PDF with view 08 - RIF2PDF
Dokument-Version	V12
Lastenheft-Nummer	LAH —.—.—.-
Baseline	3.21 (nach Export MQB A) current

DiagnosedatentabelleEreignisspeicher_NE,0x03Bremsenelektronik_3.21(nachExportMQBA)current_20140723.pdf

Inhaltsverzeichnis

Inhaltsverzeichnis . . . 11
1 Diagnosedatentabelle Ereignisspeicher, Technische Entwicklung . . . 12
1.1 Übersicht . . . 12
1.2 Details . . . 21
1.2.1 loop processing failure . . . 21
1.2.2 MCU RAM ckeck . . . 22
1.2.3 MCU checksum check . . . 22
1.2.4 MCU parity error: calculated ECC not identical to stored ECC . . . 22
1.2.5 MCU redundancy error between the two CPUs . . . 22
1.2.6 illegal reset source causes and undefined boot procedure of the ECU . . . 23
1.2.7 Internal_signal . . . 23
1.2.8 PCU watch dog: loop timing failure . . . 23
1.2.9 PCU is not able to deactivate the low-side drivers . . . 23
1.2.10 incorrect voltage drop at the high-side driver . . . 24
1.2.11 ECU contains incorrect software version lower F07 level . . . 24
1.2.12 EEPROM anomaly suspicion . . . 24
1.2.13 erroneous performance of HW components . . . 24
1.2.14 missing or false signal of rotational sense . . . 25
1.2.15 mismatch between internal configuration and connected wheel speed sensor type . . . 25
1.2.16 sensor signal current temporarily too low . . . 25
1.2.17 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high . . . 25
1.2.18 wheel speed too low . . . 26
1.2.19 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed . . . 26
1.2.20 pressure reduction phase and the following pressure hold phase too long . . . 26
1.2.21 deformation of tone wheel or one wheel defect temporarily . . . 27
1.2.22 sensor signal indicates noise . . . 27
1.2.23 sensor signal indicates noise . . . 27
1.2.24 missing or false signal of rotational sense . . . 27
1.2.25 mismatch between internal configuration and connected wheel speed sensor type . . . 28
1.2.26 sensor signal current temporarily too low . . . 28
1.2.27 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high . . . 28
1.2.28 wheel speed too low . . . 29
1.2.29 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed . . . 29
1.2.30 pressure reduction phase and the following pressure hold phase too long . . . 29
1.2.31 deformation of tone wheel or one wheel defect temporarily . . . 29
1.2.32 sensor signal indicates noise . . . 30
1.2.33 sensor signal indicates noise . . . 30
1.2.34 missing or false signal of rotational sense . . . 30
1.2.35 mismatch between internal configuration and connected wheel speed sensor type . . . 30
1.2.36 sensor signal current temporarily too low . . . 31

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.37 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high . . . 31
1.2.38 wheel speed too low . . . 31
1.2.39 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed . . . 32
1.2.40 pressure reduction phase and the following pressure hold phase too long . . . 32
1.2.41 deformation of tone wheel or one wheel defect temporarily . . . 32
1.2.42 sensor signal indicates noise . . . 32
1.2.43 sensor signal indicates noise . . . 33
1.2.44 missing or false signal of rotational sense . . . 33
1.2.45 mismatch between internal configuration and connected wheel speed sensor type . . . 33
1.2.46 sensor signal current temporarily too low . . . 33
1.2.47 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high . . . 34
1.2.48 wheel speed too low . . . 34
1.2.49 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed . . . 34
1.2.50 pressure reduction phase and the following pressure hold phase too long . . . 35
1.2.51 deformation of tone wheel or one wheel defect temporarily . . . 35
1.2.52 sensor signal indicates noise . . . 35
1.2.53 sensor signal indicates noise . . . 35
1.2.54 erroneous performance of HW components or supply voltage is out of range or FMON or PCU is not able to deactivate the high-side driver(s) . . . 36
1.2.55 erroneous performance of HW components or supply voltage is out of range . . . 36
1.2.56 supply voltage is out of range . . . 36
1.2.57 pump freewheel . . . 36
1.2.58 Pump life time ended . . . 37
1.2.59 insufficient pump motor generator voltage after end of pump motor activation . . . 37
1.2.60 voltage at pump motor too high/low when pump motor is deactivated . . . 37
1.2.61 voltage drop across the solid state pump switch is too high when the pump motor is activated - mechanically locked pump? . . . 37
1.2.62 pump connection . . . 38
1.2.63 inlet valve front left wheel . . . 38
1.2.64 inlet valve front right wheel . . . 38
1.2.65 inlet valve rear left wheel . . . 39
1.2.66 inlet valve rear right wheel . . . 39
1.2.67 outlet valve front left wheel . . . 39
1.2.68 outlet valve front right wheel . . . 39
1.2.69 outlet valve rear left wheel . . . 40
1.2.70 outlet valve rear right wheel . . . 40
1.2.71 master cylinder isolation valve 1 . . . 40
1.2.72 master cylinder isolation valve 2 . . . 40
1.2.73 low pressure feed valve 1 . . . 41
1.2.74 low pressure feed valve 2 . . . 41
1.2.75 valve redundancy monitoring . . . 41
1.2.76 valve current monitoring . . . 41

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.77 valve active test . . . 42
1.2.78 valve passive test . . . 42
1.2.79 Undervoltage . . . 42
1.2.80 Overvoltage . . . 42
1.2.81 supply voltage for external analog sensors out of the specified range . . . 43
1.2.82 supply voltage for external analog sensors out of the specified range . . . 43
1.2.83 supply voltage for external analog sensors out of the specified range . . . 43
1.2.84 duration of ESP brake intervention too long . . . 43
1.2.85 valve calibrating data missing . . . 44
1.2.86 unplausible CAN signal of brake light switch . . . 44
1.2.87 unplausible signal of TC (ESC) tip switch . . . 44
1.2.88 unplausible signal of RKA tip switch . . . 44
1.2.89 defective CAN Mailbox RAM cells . . . 45
1.2.90 ACAN: too many Bus Off events . . . 45
1.2.91 ACAN: mLW_1 frame timeout . . . 45
1.2.92 no valid Steering Wheel Angle Sensor signal received while storage of CAN signal faults inhibited . . . 45
1.2.93 unplausible stored parameter code . . . 46
1.2.94 ECU marked as Not Configured because vehicle ID is invalid . . . 46
1.2.95 CAN signal MO_Getriebe_Code wrong . . . 46
1.2.96 incoherent information at non-volatile Memory . . . 46
1.2.97 no valid Reverse Gear Switch signal received via CAN . . . 47
1.2.98 sensor signal out of range . . . 47
1.2.99 calculated sensor offset out of specified range . . . 47
1.2.100 difference between sensor signal and calculated reference signal too high . . . 47
1.2.101 sensor selftest not passed . . . 48
1.2.102 immobilizer sends wrong vehicle identification number or sensor not calibrated . . . 48
1.2.103 Single Vacuum Pressure Sensor sends no valid data . . . 48
1.2.104 Single Vacuum Pressure Sensor value changes with too high gradient . . . 49
1.2.105 Single Vacuum Pressure Sensor value out of expected operating range . . . 49
1.2.106 Single Vacuum Pressure Sensor value out of expected operating range . . . 49
1.2.107 Single Vacuum Pressure Sensor value out of expected operating range . . . 49
1.2.108 sensor signal out of range while vehicle is standing still . . . 50
1.2.109 calculated zero point of sensor out of specified range . . . 50
1.2.110 difference between sensor signal and calculated reference signal too high . . . 50
1.2.111 sensor selftest not passed . . . 50
1.2.112 difference between sensor signal and calculated reference signal too high . . . 51
1.2.113 sensor clamping during dynamic driving . . . 51
1.2.114 yaw rate scale factor out of range . . . 51
1.2.115 suspicion of plausibility failure . . . 51
1.2.116 sensor signal out of range . . . 52
1.2.117 calculated sensor offset out of specified range . . . 52
1.2.118 sensor signal out of range while vehicle is standing still . . . 52
1.2.119 sensor selftest not passed . . . 52
1.2.120 difference between sensor signal and calculated reference signal too high . . . 53

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.121 sensor clamping during dynamic driving 53
1.2.122 immobilizer sends wrong vehicle identification number or sensor not calibrated 53
1.2.123 suspicion of plausibility failure 53
1.2.124 pressure signal P1 out of range or P1 signal shorted to P2T signal 54
1.2.125 the calculated pressure sensor signal offset is out of range 54
1.2.126 sensor noise out of range 54
1.2.127 signal mismatch between pressure sensor output P1 and P2 54
1.2.128 immobilizer sends wrong vehicle identification number or sensor not calibrated 55
1.2.129 ne corrupted pressure sensor date has been detected within the relevant sensor EEPROM segments resp. registers during the init phase or if at least one failure condition within a loop has been detected longer than the specified min. fault duration during normal operation. 55
1.2.130 the calculated pressure sensor signal offset is out of range 55
1.2.131 at least one corrupted pressure sensor data transfer or command failure within a loop has been detected longer than the specified min. fault duration 56
1.2.132 temperature signal gradient out of range or time exceeded 56
1.2.133 calculated steering wheel angle offset is out of the specified range 56
1.2.134 difference between sensor signal and calculated reference signal too high 56
1.2.135 sensor clamping during dynamic driving 57
1.2.136 invalid message / status defective from steering wheel angle sensor 57
1.2.137 difference between sensor signal and calculated reference signal too high 57
1.2.138 steering wheel angle sensor status changed into Not Initialized 57
1.2.139 immobilizer sends wrong vehicle identification number or sensor not calibrated 58
1.2.140 measured output signal of steering wheel angle sensor is out of range 58
1.2.141 suspicion of plausibility failure 58
1.2.142 difference between measured signals and the calculated reference signals is too high . 59
1.2.143 vehicle deceleration higher than allowed for ACC brake intervention 59
1.2.144 ACAN: Unplausible signal from ACC ECU 59
1.2.145 ACC ECU does not deactivate the ACC function while driver is braking 59
1.2.146 inlet valve calibration data missing 60
1.2.147 Coa_reset_error 60
1.2.148 Operating System fatal error 60
1.2.149 Operating System task 1 processing did not finish 60
1.2.150 Operating System task 2 processing did not finish 61
1.2.151 Operating System task 1 stackoverflow 61
1.2.152 Operating System task 2 stackoverflow 61
1.2.153 CSW task tries to access memory which is not assigned to CSW task context 61
1.2.154 The function AYC+TCS or EDS were deactivated by adaption 62
1.2.155 Roller test bench mode active 62
1.2.156 Vehicle equipped with vacuum sensor but no vacuum sensor coded 62
1.2.157 unplausible high acceleration value is detected 62
1.2.158 ACAN: unplausible signal of collision mitigation message 63
1.2.159 ACAN: unplausible signal of collision mitigation message 63
1.2.160 PCU bandgap error 63
1.2.161 Defective control of valve supply voltage 63
1.2.162 valve calculated current 64
1.2.163 Supply voltage for internal brake pressure sensor(s) out of range 64

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.164 One of relevant VIN numbers does not match the selected vehicle variant 64
1.2.165 mismatch between VIN on CAN and VIN in coding word 65
1.2.166 One of relevant VIN numbers is '-', 'X' or missing 65
1.2.167 ECU defect 65
1.2.168 sensor signal current too high 65
1.2.169 sensor signal current temporarily too high 66
1.2.170 sensor signal current too high 66
1.2.171 sensor signal current temporarily too high 66
1.2.172 sensor signal current too high 66
1.2.173 sensor signal current temporarily too high 67
1.2.174 sensor signal current too high 67
1.2.175 sensor signal current temporarily too high 67
1.2.176 Parity bit of wheel sensor has occured more than 7 times 67
1.2.177 Parity bit of wheel sensor has occured more than 7 times 68
1.2.178 Parity bit of wheel sensor has occured more than 7 times 68
1.2.179 Parity bit of wheel sensor has occured more than 7 times 68
1.2.180 Static or no significant variation of the vacuum signal during braking 68
1.2.181 sensor signal 90 degrees turned 69
1.2.182 sensor signal 180 degrees turned 69
1.2.183 calculated vehicle acceleration compared with measured signal not plausible 69
1.2.184 No frames received from the vacuum sensor or Invalid data received from the sensor . 69
1.2.185 ECU calibration data in non-volatile memory missing or corrupt 70
1.2.186 Hecu_mismatch_fixable 70
1.2.187 Hecu_mismatch_final 70
1.2.188 absolute value of sensor signal is continuously too high 70
1.2.189 absolute value of sensor signal is continuously too high 71
1.2.190 internal SPI communication errors 71
1.2.191 internal SPI communication errors 71
1.2.192 internal SPI communication errors 72
1.2.193 customer software deactivated (RKA+ task aborted) 72
1.2.194 Combustion Engine (CE) does not provide sufficient vacuum 72
1.2.195 inplausible vacuum consumption without booster activation 72
1.2.196 FCAN: ACC_07 message is not received 73
1.2.197 ACAN: LH2_Zaehler signal failure 73
1.2.198 ACAN: mLenkhilfe_2 frame timeout 73
1.2.199 ACAN: mLenkhilfe_2 frame DLC failure 73
1.2.200 ACAN: LH3_Zaehler signal failure 74
1.2.201 ACAN: LH3_Checksumme signal failure 74
1.2.202 FCAN: ACC_10 message is received with invalid checksum 74
1.2.203 ACAN: LH3_Sta_DSR signal timeout value 74
1.2.204 ACAN: LH3_Sta_DSR wrong range 75
1.2.205 ACAN: LH3_Lenkungstyp signal failure 75
1.2.206 ACAN: mLenkhilfe_3 frame DLC failure 75
1.2.207 ACAN: mLenkhilfe_3 frame timeout 75
1.2.208 ACAN: AL1_Ist_Proz and RDL closed failure 76

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.209 FCAN: Airbag_02 message is received with invalid length . . . 76
1.2.210 ACAN: AL1_Ist_Proz and AL1_KupSteifig_F failure . . . 76
1.2.211 ACAN: MO1_Drehzahl signal failure value . . . 76
1.2.212 ACAN: MO1_Sta_Pedal signal failure value . . . 77
1.2.213 ACAN: MO1_Verlustmo signal failure value . . . 77
1.2.214 ACAN: MO1_Mo_m_ex signal failure value . . . 77
1.2.215 ACAN: MO1_Mo_o_ex signal failure value . . . 77
1.2.216 FCAN: Diagnose_01 message is not received . . . 78
1.2.217 ACAN: MO2_Leerlauf_Solldrehzahl signal failure value . . . 78
1.2.218 ACAN: MO3_FPGradient signal failure value . . . 78
1.2.219 ACAN: MO3_Pedalwert signal failure value . . . 79
1.2.220 ACAN: MO5_Checksumme failure value . . . 79
1.2.221 ACAN: Gearbox coding missmatch . . . 79
1.2.222 ACAN: GE1_Wahl_Pos signal falure value . . . 79
1.2.223 ACAN: GE1_Zaehler signal falure . . . 80
1.2.224 ACAN: KO3_Verbau_Br signal wrong value . . . 80
1.2.225 ACAN: AB1_Checksumme failure . . . 80
1.2.226 ACAN: Airbag coding missmatch . . . 80
1.2.227 ACAN: AB1_Zaehler signal failure . . . 81
1.2.228 ACAN: Airbag_03_CRC failure . . . 81
1.2.229 ACAN: Airbag_03_BZ failure . . . 81
1.2.230 ACAN: Airbag_03 frame DLC timeout . . . 81
1.2.231 FCAN: Klemmen_Status_01 message is received with invalid length . . . 82
1.2.232 FCAN: Klemmen_Status_01 message is received with invalid checksum . . . 82
1.2.233 FCAN: Klemmen_Status_01 message is received with invalid counter . . . 82
1.2.234 FCAN: Kombi_02 message is not received . . . 82
1.2.235 ACAN: AL1_Ist_Proz signal failure value . . . 83
1.2.236 ACAN: AL1_Sta_Kup signal wrong value . . . 83
1.2.237 ACAN: Allrad_1 message RDL coding missmatch . . . 83
1.2.238 FCAN: Kombi_01 messagei is not received . . . 83
1.2.239 FCAN: Kombi_01 message is received with invalid length . . . 84
1.2.240 FCAN: LH_EPS_01 message is not received . . . 84
1.2.241 ACAN: AL1_Zaehler failure 3 . . . 84
1.2.242 ACAN: GK1_Sta_Licht1 signal timeout . . . 84
1.2.243 ACAN: GK1_Sta_ILM_F_1 signal timeout . . . 85
1.2.244 ACAN: GK1_Sta_Tuerkont signal timeout . . . 85
1.2.245 ACAN: MOB_Checksum signal failure . . . 85
1.2.246 ACAN: MOB_Zaehler signal failure . . . 85
1.2.247 ACAN: QS1_Kupplung signal failure value . . . 86
1.2.248 FCAN: Motor_Code_01 message is not received . . . 86
1.2.249 FCAN: Motor_Code_01 message is received with invalid length . . . 86
1.2.250 FCAN: Motor_Code_01 message is received with invalid checksum . . . 86
1.2.251 FCAN: Motor_Code_01 message is received with invalid counter . . . 87
1.2.252 ACAN: PL1_Stat_PLA_EPS signal wrong value received . . . 87
1.2.253 ACAN: SY1_Verbauinfo signal is not set . . . 87

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.254 ACAN: SY1_Lenker signal coding missmatch . . . 87
1.2.255 ACAN: AWV_Checksumme signal failure . . . 88
1.2.256 FCAN: Motor_12 message is not received . . . 88
1.2.257 ACAN: mMotor_1 frame timeout . . . 88
1.2.258 ACAN: mMotor_1 frame DLC failure . . . 88
1.2.259 FCAN: Motor_14 message is received with invalid length . . . 89
1.2.260 FCAN: Motor_20 message is not received . . . 89
1.2.261 FCAN: Motor_20 message is received with invalid length . . . 89
1.2.262 ACAN: mMotor_3 frame DLC failure . . . 89
1.2.263 ACAN: mMotor_5 frame timeout . . . 90
1.2.264 ACAN: mMotor_5 frame DLC failure . . . 90
1.2.265 FCAN: Pla_01 message is received with invalid counter . . . 90
1.2.266 ACAN: mMotor_7 frame DLC failure . . . 90
1.2.267 ACAN: mGetriebe_1 frame timeout . . . 91
1.2.268 ACAN: mGetriebe_1 frame DLC failure . . . 91
1.2.269 ACAN: mGetriebe_6 frame timeout . . . 91
1.2.270 ACAN: mGetriebe_6 frame DLC failure . . . 91
1.2.271 ACAN: mAllrad_1 frame timeout . . . 92
1.2.272 ACAN: mAllrad_1 frame timeout 1 . . . 92
1.2.273 FCAN: Lwi_01 message is received with invalid checksum . . . 92
1.2.274 FCAN: Lwi_01 message is received with invalid counter . . . 92
1.2.275 FCAN: MO_Fahrpedalgradient signal is invalid . . . 93
1.2.276 FCAN: MO_Fahrpedalrohwert signal is invalid . . . 93
1.2.277 ACAN: mAllrad_1 frame DLC failure 3 . . . 93
1.2.278 ACAN: mGate_Komf_1 frame timeout . . . 93
1.2.279 ACAN: mGate_Komf_1 frame DLC failure . . . 94
1.2.280 FCAN: manual gearbox coded and gearbox messages received . . . 94
1.2.281 ACAN: mKombi_2 frame DLC failure . . . 94
1.2.282 ACAN: mKombi_3 frame timeout . . . 94
1.2.283 ACAN: mKombi_3 frame DLC failure . . . 95
1.2.284 ACAN: mAirbag_1 frame timeout . . . 95
1.2.285 ACAN: mAirbag_1 frame DLC failure . . . 95
1.2.286 ACAN: mAWV frame timeout . . . 95
1.2.287 ACAN: mAWV frame DLC failure . . . 96
1.2.288 ACAN: mMotor_Bremse frame timeout . . . 96
1.2.289 ACAN: mMotor_Bremse frame DLC failure . . . 96
1.2.290 ACAN: mQuersperre_1 frame timeout . . . 96
1.2.291 ACAN: mQuersperre_1 frame DLC failure . . . 97
1.2.292 ACAN: mSoll_Verbauliste_neu frame timeout . . . 97
1.2.293 ACAN: mSoll_Verbauliste_neu frame DLC failure . . . 97
1.2.294 ACAN: mSoll_Verbauliste_neu frame timeout 1 . . . 97
1.2.295 ACAN: mSoll_Verbauliste_neu frame DLC failure 1 . . . 98
1.2.296 ACAN: mIdent frame timeout . . . 98
1.2.297 ACAN: mIdent frame DLC failure . . . 98
1.2.298 ACAN: mIdent signal timeout . . . 98

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.299 ACAN: mDiagnose_1 frame timeout . . . 99
1.2.300 ACAN: mDiagnose_1 frame DLC failure . . . 99
1.2.301 ACAN: mPLA_1 frame DLC failure . . . 99
1.2.302 ACAN: mSysteminfo_1 frame timeout . . . 99
1.2.303 ACAN: mSysteminfo_1 frame DLC failure . . . 100
1.2.304 sensor signal current temporarily too low . . . 100
1.2.305 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high . . . 100
1.2.306 wheel speed too low . . . 101
1.2.307 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed . . . 101
1.2.308 pressure reduction phase and the following pressure hold phase too long . . . 101
1.2.309 deformation of tone wheel or one wheel defect temporarily . . . 101
1.2.310 sensor signal current temporarily too low . . . 102
1.2.311 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high . . . 102
1.2.312 wheel speed too low . . . 102
1.2.313 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed . . . 103
1.2.314 pressure reduction phase and the following pressure hold phase too long . . . 103
1.2.315 deformation of tone wheel or one wheel defect temporarily . . . 103
1.2.316 sensor signal current temporarily too low . . . 103
1.2.317 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high . . . 104
1.2.318 wheel speed too low . . . 104
1.2.319 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed . . . 104
1.2.320 pressure reduction phase and the following pressure hold phase too long . . . 105
1.2.321 deformation of tone wheel or one wheel defect temporarily . . . 105
1.2.322 sensor signal current temporarily too low . . . 105
1.2.323 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high . . . 105
1.2.324 wheel speed too low . . . 106
1.2.325 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed . . . 106
1.2.326 pressure reduction phase and the following pressure hold phase too long . . . 106
1.2.327 deformation of tone wheel or one wheel defect temporarily . . . 106
1.2.328 Reifenkontrollanzeige Systemstörung . . . 107
1.2.329 Taster für Reifenkontrollanzeige mechanischer Fehler . . . 107
1.2.330 unplausible coding request - invalid combination . . . 107
1.2.331 Integrity f TMC pressure sensor . . . 107
1.2.332 Swa_lost_initialization . . . 108
1.2.333 Swa_tol_check_wl_event . . . 108
1.2.334 Eol_test_active . . . 108
1.2.335 Eol_test_timeout . . . 109
1.2.336 Eol_yaw_rate_adjust . . . 109

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.337 Eol_yaw_rate_sensor . . . 109
1.2.338 Eol_lat_acc_sensor . . . 109
1.2.339 Eol_yr_la_exchanged . . . 110
1.2.340 Eol_yaw_rate_mounting . . . 110
1.2.341 Eol_lat_acc_mounting . . . 110
1.2.342 Eol_swa_sensor . . . 110
1.2.343 Eol_brake_light_switch . . . 111
1.2.344 Eol_front_wheel_sensors_swap_a . . . 111
1.2.345 Eol_front_wheel_sensors_swap_b . . . 111
1.2.346 Eol_rear_wheel_sensors_swap_a . . . 111
1.2.347 Eol_rear_wheel_sensors_swap_b . . . 112
1.2.348 Reifendruckwarnung . . . 112
1.2.349 Reifenkontrollanzeige zur Zeit nicht verfügbar . . . 112
1.2.350 Raddurchmesser unplausibel . . . 112
1.2.351 Unreliable_velo_filt . . . 113
1.2.352 Reifenkontrollanzeige nicht verfügbar . . . 113
1.2.353 VIN stored in Eeprom is not identical to VIN on BUS . . . 113
1.2.354 TMC pressure is higher than 15 bar but the BLS was inactive for more than 1 s . . . 113
1.2.355 Pump motor calibration is corrupt or non-restorable . . . 114
1.2.356 ACAN: MO1_Sta_Bremse signal failure value . . . 114
1.2.357 ACAN: MO1_Sta_MotMo signal failure value . . . 114
1.2.358 ACAN: mAllrad_1 frame DLC failure . . . 114
1.2.359 ACAN: mPLA_1 frame timeout . . . 115
1.2.360 FCAN: WWSs_01_alt veraltet bit is set . . . 115
1.2.361 FCAN: Getriebe_12_alt veraltet bit is set /Hybrid vehicles/ . . . 115
1.2.362 FCAN: Unplausible VIN number . . . 115
1.2.363 FCAN: PLA_Status_PLA_ESP signal is invalid . . . 116
1.2.364 FCAN: StartStop not coded but MO_StartStopp_Status not equal 0 . . . 116
1.2.365 FCAN: TSK_Codierung signal is invalid . . . 116
1.2.366 FCAN: Damper not coded but Fahrwerk_01 message received . . . 116
1.2.367 FCAN: Coding of ESP and TSK does not fit together . . . 117
1.2.368 FCAN: Motor_20 message is received with invalid checksum . . . 117
1.2.369 FCAN: Motor_20 message is received with invalid counter . . . 117
1.2.370 FCAN: Allrad_03 message is received with invalid counter . . . 117
1.2.371 FCAN: Motor_11 message is received with invalid checksum . . . 118
1.2.372 FCAN: Motor_11 message is received with invalid counter . . . 118
1.2.373 FCAN: Motor_12 message is received with invalid checksum . . . 118
1.2.374 FCAN: Motor_12 message is received with invalid counter . . . 118
1.2.375 HiL_CCan_Sens_Clust1_Checksum . . . 119
1.2.376 HiL_CCan_Sens_Clust1_Counter . . . 119
1.2.377 HiL_CCan_Sens_Clust1_Timeout . . . 119
1.2.378 HiL_CCan_Sens_Clust1_Length . . . 120
1.2.379 HiL_CCan_Sens_Clust2_Checksum . . . 120
1.2.380 HiL_CCan_Sens_Clust2_Counter . . . 120
1.2.381 HiL_CCan_Sens_Clust2_Timeout . . . 120

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.382 HiL_CCan_Sens_Clust2_Length . . . 121
1.2.383 ACAN: MO_QBit_Fahrpedalrohwert signal is invalid . . . 121
1.2.384 steering wheel angle sensor transmits internal state Not Calibrated . . . 121
1.2.385 ACAN: LH2_Checksumme signal failure . . . 121
1.2.386 ACAN: LH3_Sta_DSR signal failure value . . . 122
1.2.387 ACAN: AL1_Ist_Proz and RDL open failure . . . 122
1.2.388 ACAN: MO2_Mo_ZWR signal failure value . . . 122
1.2.389 ACAN: Airbag_03 frame timeout . . . 122
1.2.390 ACAN: 4WD coding missmatch . . . 123
1.2.391 ACAN: AL1_Ist_Proz is open failure . . . 123
1.2.392 ACAN: AL1_Ist_Proz is closed failure . . . 123
1.2.393 ACAN: AL1_Quersp_Sta signal failure value . . . 123
1.2.394 ACAN: AL1_Zaehler failure . . . 124
1.2.395 ACAN: AL1_Zaehler failure 2 . . . 124
1.2.396 ACAN: IDT_VIN signals wrong value . . . 124
1.2.397 ACAN: VL1_ABS signal not set . . . 124
1.2.398 ACAN: PL1_Checksumme signal failure . . . 125
1.2.399 ACAN: PL1_Zaehler signal failure . . . 125
1.2.400 ACAN: AWV_Zaehler signal failure . . . 125
1.2.401 ACAN: mMotor_2 frame timeout . . . 125
1.2.402 ACAN: mMotor_2 frame DLC failure . . . 126
1.2.403 ACAN: mMotor_3 frame timeout . . . 126
1.2.404 ACAN: mMotor_7 frame timeout . . . 126
1.2.405 ACAN: mAllrad_1 frame DLC failure 1 . . . 126
1.2.406 ACAN: mAllrad_1 frame timeout 2 . . . 127
1.2.407 ACAN: mAllrad_1 frame DLC failure 2 . . . 127
1.2.408 ACAN: mAllrad_1 frame timeout 3 . . . 127
1.2.409 ACAN: mKombi_2 frame timeout . . . 127
1.2.410 BUS_FAILURE_RAM07.00 . . . 128
1.2.411 BUS_FAILURE_RAM07.01 . . . 128
1.2.412 BUS_FAILURE_RAM07.02 . . . 128
1.2.413 BUS_FAILURE_RAM07.03 . . . 128
1.2.414 BUS_FAILURE_RAM07.04 . . . 129
1.2.415 BUS_FAILURE_RAM07.05 . . . 129
1.2.416 BUS_FAILURE_RAM07.06 . . . 129
1.2.417 BUS_FAILURE_RAM07.07 . . . 129
1.2.418 BUS_FAILURE_RAM07.08 . . . 130
1.2.419 BUS_FAILURE_RAM07.09 . . . 130
1.2.420 BUS_FAILURE_RAM07.0A . . . 130
1.2.421 BUS_FAILURE_RAM07.0B . . . 130
1.2.422 ACAN: mLWR_Zustand frame timeout . . . 131
1.2.423 ACAN: mLWR_Zustand frame DLC failure . . . 131
1.2.424 ACAN: M10_rel_Saugrohrdruck signal failure value . . . 131
1.2.425 ACAN: mMotor_10 Start_Stop coding missmatch . . . 131
1.2.426 ACAN: mMotor_10 Start_Stop configuration failure . . . 132

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.427 ACAN: mMotor_10 frame DLC failure 132
1.2.428 ACAN: mMotor_10 frame timeout 132
1.2.429 ACAN: LW1_CRC signal failure 132
1.2.430 ACAN: LW1_ID wrong value 133
1.2.431 ACAN: LW1_Zaehler signal failure 133
1.2.432 ACAN: mLW_1 frame DLC failure 133
1.2.433 ACAN: mLW_1 frame timeout 133
1.2.434 ACAN: Global CAN frame timeout 134
1.2.435 ACAN: mKombi_1 frame timeout 134
1.2.436 ACAN: mKombi_1 frame DLC failure 134
1.2.437 ACAN: RCTA_01_CHK signal failure 134
1.2.438 ACAN: RCTA_01_BZ signal failure 135
1.2.439 ACAN: RCTA_01 frame timeout 135
1.2.440 ACAN: RCTA_01 frame DLC failure 135
1.2.441 ACAN: MO1_TiOut_Br signal is set 135
1.2.442 ACAN: AL1_Ist_Proz signal is set to not defined value 136
1.2.443 ACAN: AL1_Zaehler failure 4 136
1.2.444 ACAN: MO1_Pedalwert 136
1.2.445 ACAN: GE1_Zielgang 136

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1 Diagnosedatentabelle Ereignisspeicher, Technische Entwicklung

1.1 Übersicht

Überschrift	Seite
loop processing failure	21
MCU RAM ckeck	22
MCU checksum check	22
MCU parity error: calculated ECC not identical to stored ECC	22
MCU redundancy error between the two CPUs	22
illegal reset source causes and undefined boot procedure of the ECU	23
Internal_signal	23
PCU watch dog: loop timing failure	23
PCU is not able to deactivate the low-side drivers	23
incorrect voltage drop at the high-side driver	24
ECU contains incorrect software version lower F07 level	24
EEPROM anomaly suspicion	24
erroneous performance of HW components	24
missing or false signal of rotational sense	25
mismatch between internal configuration and connected wheel speed sensor type	25
sensor signal current temporarily too low	25
wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high	25
wheel speed too low	26
missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed	26
pressure reduction phase and the following pressure hold phase too long	26
deformation of tone wheel or one wheel defect temporarily	27
sensor signal indicates noise	27
sensor signal indicates noise	27
missing or false signal of rotational sense	27
mismatch between internal configuration and connected wheel speed sensor type	28
sensor signal current temporarily too low	28
wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high	28
wheel speed too low	29
missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed	29
pressure reduction phase and the following pressure hold phase too long	29
deformation of tone wheel or one wheel defect temporarily	29
sensor signal indicates noise	30
sensor signal indicates noise	30
missing or false signal of rotational sense	30
mismatch between internal configuration and connected wheel speed sensor type	30
sensor signal current temporarily too low	31
wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high	31
wheel speed too low	31
missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed	32
pressure reduction phase and the following pressure hold phase too long	32

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
deformation of tone wheel or one wheel defect temporarily	32
sensor signal indicates noise	32
sensor signal indicates noise	33
missing or false signal of rotational sense	33
mismatch between internal configuration and connected wheel speed sensor type	33
sensor signal current temporarily too low	33
wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high	34
wheel speed too low	34
missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed	34
pressure reduction phase and the following pressure hold phase too long	35
deformation of tone wheel or one wheel defect temporarily	35
sensor signal indicates noise	35
sensor signal indicates noise	35
erroneous performance of HW components or supply voltage is out of range or FMON or PCU is not able to deactivate the high-side driver(s)	36
erroneous performance of HW components or supply voltage is out of range	36
supply voltage is out of range	36
pump freewheel	36
Pump life time ended	37
insufficient pump motor generator voltage after end of pump motor activation	37
voltage at pump motor too high/low when pump motor is deactivated	37
voltage drop across the solid state pump switch is too high when the pump motor is activated - mechanically locked pump?	37
pump connection	38
inlet valve front left wheel	38
inlet valve front right wheel	38
inlet valve rear left wheel	39
inlet valve rear right wheel	39
outlet valve front left wheel	39
outlet valve front right wheel	39
outlet valve rear left wheel	40
outlet valve rear right wheel	40
master cylinder isolation valve 1	40
master cylinder isolation valve 2	40
low pressure feed valve 1	41
low pressure feed valve 2	41
valve redundancy monitoring	41
valve current monitoring	41
valve active test	42
valve passive test	42
Undervoltage	42
Overvoltage	42
supply voltage for external analog sensors out of the specified range	43
supply voltage for external analog sensors out of the specified range	43
supply voltage for external analog sensors out of the specified range	43
duration of ESP brake intervention too long	43
valve calibrating data missing	44

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
unplausible CAN signal of brake light switch	44
unplausible signal of TC (ESC) tip switch	44
unplausible signal of RKA tip switch	44
defective CAN Mailbox RAM cells	45
ACAN: too many Bus Off events	45
ACAN: mLW_1 frame timeout	45
no valid Steering Wheel Angle Sensor signal received while storage of CAN signal faults inhibited	45
unplausible stored parameter code	46
ECU marked as Not Configured because vehicle ID is invalid	46
CAN signal MO_Getriebe_Code wrong	46
incoherent information at non-volatile Memory	46
no valid Reverse Gear Switch signal received via CAN	47
sensor signal out of range	47
calculated sensor offset out of specified range	47
difference between sensor signal and calculated reference signal too high	47
sensor selftest not passed	48
immobilizer sends wrong vehicle identification number or sensor not calibrated	48
Single Vacuum Pressure Sensor sends no valid data	48
Single Vacuum Pressure Sensor value changes with too high gradient	49
Single Vacuum Pressure Sensor value out of expected operating range	49
Single Vacuum Pressure Sensor value out of expected operating range	49
Single Vacuum Pressure Sensor value out of expected operating range	49
sensor signal out of range while vehicle is standing still	50
calculated zero point of sensor out of specified range	50
difference between sensor signal and calculated reference signal too high	50
sensor selftest not passed	50
difference between sensor signal and calculated reference signal too high	51
sensor clamping during dynamic driving	51
yaw rate scale factor out of range	51
suspicion of plausibility failure	51
sensor signal out of range	52
calculated sensor offset out of specified range	52
sensor signal out of range while vehicle is standing still	52
sensor selftest not passed	52
difference between sensor signal and calculated reference signal too high	53
sensor clamping during dynamic driving	53
immobilizer sends wrong vehicle identification number or sensor not calibrated	53
suspicion of plausibility failure	53
pressure signal P1 out of range or P1 signal shorted to P2T signal	54
the calculated pressure sensor signal offset is out of range	54
sensor noise out of range	54
signal mismatch between pressure sensor output P1 and P2	54
immobilizer sends wrong vehicle identification number or sensor not calibrated	55
ne corrupted pressure sensor date has been detected within the relevant sensor EEPROM segments resp. registers during the init phase or if at least one failure condition within a loop has been detected longer than the specified min. fault duration during normal operation.	55

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
the calculated pressure sensor signal offset is out of range	55
at least one corrupted pressure sensor data transfer or command failure within a loop has been detected longer than the specified min. fault duration	56
temperature signal gradient out of range or time exceeded	56
calculated steering wheel angle offset is out of the specified range	56
difference between sensor signal and calculated reference signal too high	56
sensor clamping during dynamic driving	57
invalid message / status defective from steering wheel angle sensor	57
difference between sensor signal and calculated reference signal too high	57
steering wheel angle sensor status changed into Not Initialized	57
immobilizer sends wrong vehicle identification number or sensor not calibrated	58
measured output signal of steering wheel angle sensor is out of range	58
suspicion of plausibility failure	58
difference between measured signals and the calculated reference signals is too high	59
vehicle deceleration higher than allowed for ACC brake intervention	59
ACAN: Unplausible signal from ACC ECU	59
ACC ECU does not deactivate the ACC function while driver is braking	59
inlet valve calibration data missing	60
Coa_reset_error	60
Operating System fatal error	60
Operating System task 1 processing did not finish	60
Operating System task 2 processing did not finish	61
Operating System task 1 stackoverflow	61
Operating System task 2 stackoverflow	61
CSW task tries to access memory which is not assigned to CSW task context	61
The function AYC+TCS or EDS were deactivated by adaption	62
Roller test bench mode active	62
Vehicle equipped with vacuum sensor but no vacuum sensor coded	62
unplausible high acceleration value is detected	62
ACAN: unplausible signal of collision mitigation message	63
ACAN: unplausible signal of collision mitigation message	63
PCU bandgap error	63
Defective control of valve supply voltage	63
valve calculated current	64
Supply voltage for internal brake pressure sensor(s) out of range	64
One of relevant VIN numbers does not match the selected vehicle variant	64
mismatch between VIN on CAN and VIN in coding word	65
One of relevant VIN numbers is '-', 'X' or missing	65
ECU defect	65
sensor signal current too high	65
sensor signal current temporarily too high	66
sensor signal current too high	66
sensor signal current temporarily too high	66
sensor signal current too high	66
sensor signal current temporarily too high	67
sensor signal current too high	67
sensor signal current temporarily too high	67

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
Parity bit of wheel sensor has occured more than 7 times	67
Parity bit of wheel sensor has occured more than 7 times	68
Parity bit of wheel sensor has occured more than 7 times	68
Parity bit of wheel sensor has occured more than 7 times	68
Static or no significant variation of the vacuum signal during braking	68
sensor signal 90 degrees turned	69
sensor signal 180 degrees turned	69
calculated vehicle acceleration compared with measured signal not plausible	69
No frames received from the vacuum sensor or Invalid data received from the sensor	69
ECU calibration data in non-volatile memory missing or corrupt	70
Hecu_mismatch_fixable	70
Hecu_mismatch_final	70
absolute value of sensor signal is continuously too high	70
absolute value of sensor signal is continuously too high	71
internal SPI communication errors	71
internal SPI communication errors	71
internal SPI communication errors	72
customer software deactivated (RKA+ task aborted)	72
Combustion Engine (CE) does not provide sufficient vacuum	72
inplausible vacuum consumption without booster activation	72
FCAN: ACC_07 message is not received	73
ACAN: LH2_Zaehler signal failure	73
ACAN: mLenkhilfe_2 frame timeout	73
ACAN: mLenkhilfe_2 frame DLC failure	73
ACAN: LH3_Zaehler signal failure	74
ACAN: LH3_Checksumme signal failure	74
FCAN: ACC_10 message is received with invalid checksum	74
ACAN: LH3_Sta_DSR signal timeout value	74
ACAN: LH3_Sta_DSR wrong range	75
ACAN: LH3_Lenkungstyp signal failure	75
ACAN: mLenkhilfe_3 frame DLC failure	75
ACAN: mLenkhilfe_3 frame timeout	75
ACAN: AL1_Ist_Proz and RDL closed failure	76
FCAN: Airbag_02 message is received with invalid length	76
ACAN: AL1_Ist_Proz and AL1_KupSteifig_F failure	76
ACAN: MO1_Drehzahl signal failure value	76
ACAN: MO1_Sta_Pedal signal failure value	77
ACAN: MO1_Verlustmo signal failure value	77
ACAN: MO1_Mo_m_ex signal failure value	77
ACAN: MO1_Mo_o_ex signal failure value	77
FCAN: Diagnose_01 message is not received	78
ACAN: MO2_Leerlauf_Solldrehzahl signal failure value	78
ACAN: MO3_FPGradient signal failure value	78
ACAN: MO3_Pedalwert signal failure value	79
ACAN: MO5_Checksumme failure value	79
ACAN: Gearbox coding missmatch	79
ACAN: GE1_Wahl_Pos signal falure value	79

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
ACAN: GE1_Zaehler signal falure	80
ACAN: KO3_Verbau_Br signal wrong value	80
ACAN: AB1_Checksumme failure	80
ACAN: Airbag coding missmatch	80
ACAN: AB1_Zaehler signal failure	81
ACAN: Airbag_03_CRC failure	81
ACAN: Airbag_03_BZ failure	81
ACAN: Airbag_03 frame DLC timeout	81
FCAN: Klemmen_Status_01 message is received with invalid length	82
FCAN: Klemmen_Status_01 message is received with invalid checksum	82
FCAN: Klemmen_Status_01 message is received with invalid counter	82
FCAN: Kombi_02 message is not received	82
ACAN: AL1_Ist_Proz signal failure value	83
ACAN: AL1_Sta_Kup signal wrong value	83
ACAN: Allrad_1 message RDL coding missmatch	83
FCAN: Kombi_01 messagei is not received	83
FCAN: Kombi_01 message is received with invalid length	84
FCAN: LH_EPS_01 message is not received	84
ACAN: AL1_Zaehler failure 3	84
ACAN: GK1_Sta_Licht1 signal timeout	84
ACAN: GK1_Sta_ILM_F_1 signal timeout	85
ACAN: GK1_Sta_Tuerkont signal timeout	85
ACAN: MOB_Checksum signal failure	85
ACAN: MOB_Zaehler signal failure	85
ACAN: QS1_Kupplung signal failure value	86
FCAN: Motor_Code_01 message is not received	86
FCAN: Motor_Code_01 message is received with invalid length	86
FCAN: Motor_Code_01 message is received with invalid checksum	86
FCAN: Motor_Code_01 message is received with invalid counter	87
ACAN: PL1_Stat_PLA_EPS signal wrong value received	87
ACAN: SY1_Verbauinfo signal is not set	87
ACAN: SY1_Lenker signal coding missmatch	87
ACAN: AWV_Checksumme signal failure	88
FCAN: Motor_12 message is not received	88
ACAN: mMotor_1 frame timeout	88
ACAN: mMotor_1 frame DLC failure	88
FCAN: Motor_14 message is received with invalid length	89
FCAN: Motor_20 message is not received	89
FCAN: Motor_20 message is received with invalid length	89
ACAN: mMotor_3 frame DLC failure	89
ACAN: mMotor_5 frame timeout	90
ACAN: mMotor_5 frame DLC failure	90
FCAN: Pla_01 message is received with invalid counter	90
ACAN: mMotor_7 frame DLC failure	90
ACAN: mGetriebe_1 frame timeout	91
ACAN: mGetriebe_1 frame DLC failure	91
ACAN: mGetriebe_6 frame timeout	91

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
ACAN: mGetriebe_6 frame DLC failure	91
ACAN: mAllrad_1 frame timeout	92
ACAN: mAllrad_1 frame timeout 1	92
FCAN: Lwi_01 message is received with invalid checksum	92
FCAN: Lwi_01 message is received with invalid counter	92
FCAN: MO_Fahrpedalgradient signal is invalid	93
FCAN: MO_Fahrpedalrohwert signal is invalid	93
ACAN: mAllrad_1 frame DLC failure 3	93
ACAN: mGate_Komf_1 frame timeout	93
ACAN: mGate_Komf_1 frame DLC failure	94
FCAN: manual gearbox coded and gearbox messages received	94
ACAN: mKombi_2 frame DLC failure	94
ACAN: mKombi_3 frame timeout	94
ACAN: mKombi_3 frame DLC failure	95
ACAN: mAirbag_1 frame timeout	95
ACAN: mAirbag_1 frame DLC failure	95
ACAN: mAWV frame timeout	95
ACAN: mAWV frame DLC failure	96
ACAN: mMotor_Bremse frame timeout	96
ACAN: mMotor_Bremse frame DLC failure	96
ACAN: mQuersperre_1 frame timeout	96
ACAN: mQuersperre_1 frame DLC failure	97
ACAN: mSoll_Verbauliste_neu frame timeout	97
ACAN: mSoll_Verbauliste_neu frame DLC failure	97
ACAN: mSoll_Verbauliste_neu frame timeout 1	97
ACAN: mSoll_Verbauliste_neu frame DLC failure 1	98
ACAN: mIdent frame timeout	98
ACAN: mIdent frame DLC failure	98
ACAN: mIdent signal timeout	98
ACAN: mDiagnose_1 frame timeout	99
ACAN: mDiagnose_1 frame DLC failure	99
ACAN: mPLA_1 frame DLC failure	99
ACAN: mSysteminfo_1 frame timeout	99
ACAN: mSysteminfo_1 frame DLC failure	100
sensor signal current temporarily too low	100
wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high	100
wheel speed too low	101
missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed	101
pressure reduction phase and the following pressure hold phase too long	101
deformation of tone wheel or one wheel defect temporarily	101
sensor signal current temporarily too low	102
wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high	102
wheel speed too low	102
missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed	103
pressure reduction phase and the following pressure hold phase too long	103
deformation of tone wheel or one wheel defect temporarily	103

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
sensor signal current temporarily too low	103
wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high	104
wheel speed too low	104
missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed	104
pressure reduction phase and the following pressure hold phase too long	105
deformation of tone wheel or one wheel defect temporarily	105
sensor signal current temporarily too low	105
wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high	105
wheel speed too low	106
missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed	106
pressure reduction phase and the following pressure hold phase too long	106
deformation of tone wheel or one wheel defect temporarily	106
Reifenkontrollanzeige Systemstörung	107
Taster für Reifenkontrollanzeige mechanischer Fehler	107
unplausible coding request - invalid combination	107
Integrity f TMC pressure sensor	107
Swa_lost_initialization	108
Swa_tol_check_wl_event	108
Eol_test_active	108
Eol_test_timeout	109
Eol_yaw_rate_adjust	109
Eol_yaw_rate_sensor	109
Eol_lat_acc_sensor	109
Eol_yr_la_exchanged	110
Eol_yaw_rate_mounting	110
Eol_lat_acc_mounting	110
Eol_swa_sensor	110
Eol_brake_light_switch	111
Eol_front_wheel_sensors_swap_a	111
Eol_front_wheel_sensors_swap_b	111
Eol_rear_wheel_sensors_swap_a	111
Eol_rear_wheel_sensors_swap_b	112
Reifendruckwarnung	112
Reifenkontrollanzeige zur Zeit nicht verfügbar	112
Raddurchmesser unplausibel	112
Unreliable_velo_filt	113
Reifenkontrollanzeige nicht verfügbar	113
VIN stored in Eeprom is not identical to VIN on BUS	113
TMC pressure is higher than 15 bar but the BLS was inactive for more than 1 s	113
Pump motor calibration is corrupt or non-restorable	114
ACAN: MO1_Sta_Bremse signal failure value	114
ACAN: MO1_Sta_MotMo signal failure value	114
ACAN: mAllrad_1 frame DLC failure	114
ACAN: mPLA_1 frame timeout	115
FCAN: WWSs_01_alt veraltet bit is set	115
FCAN: Getriebe_12_alt veraltet bit is set /Hybrid vehicles/	115

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
FCAN: Unplausible VIN number	115
FCAN: PLA_Status_PLA_ESP signal is invalid	116
FCAN: StartStop not coded but MO_StartStopp_Status not equal 0	116
FCAN: TSK_Codierung signal is invalid	116
FCAN: Damper not coded but Fahrwerk_01 message received	116
FCAN: Coding of ESP and TSK does not fit together	117
FCAN: Motor_20 message is received with invalid checksum	117
FCAN: Motor_20 message is received with invalid counter	117
FCAN: Allrad_03 message is received with invalid counter	117
FCAN: Motor_11 message is received with invalid checksum	118
FCAN: Motor_11 message is received with invalid counter	118
FCAN: Motor_12 message is received with invalid checksum	118
FCAN: Motor_12 message is received with invalid counter	118
HiL_CCan_Sens_Clust1_Checksum	119
HiL_CCan_Sens_Clust1_Counter	119
HiL_CCan_Sens_Clust1_Timeout	119
HiL_CCan_Sens_Clust1_Length	120
HiL_CCan_Sens_Clust2_Checksum	120
HiL_CCan_Sens_Clust2_Counter	120
HiL_CCan_Sens_Clust2_Timeout	120
HiL_CCan_Sens_Clust2_Length	121
ACAN: MO_QBit_Fahrpedalrohwert signal is invalid	121
steering wheel angle sensor transmits internal state Not Calibrated	121
ACAN: LH2_Checksumme signal failure	121
ACAN: LH3_Sta_DSR signal failure value	122
ACAN: AL1_Ist_Proz and RDL open failure	122
ACAN: MO2_Mo_ZWR signal failure value	122
ACAN: Airbag_03 frame timeout	122
ACAN: 4WD coding missmatch	123
ACAN: AL1_Ist_Proz is open failure	123
ACAN: AL1_Ist_Proz is closed failure	123
ACAN: AL1_Quersp_Sta signal failure value	123
ACAN: AL1_Zaehler failure	124
ACAN: AL1_Zaehler failure 2	124
ACAN: IDT_VIN signals wrong value	124
ACAN: VL1_ABS signal not set	124
ACAN: PL1_Checksumme signal failure	125
ACAN: PL1_Zaehler signal failure	125
ACAN: AWV_Zaehler signal failure	125
ACAN: mMotor_2 frame timeout	125
ACAN: mMotor_2 frame DLC failure	126
ACAN: mMotor_3 frame timeout	126
ACAN: mMotor_7 frame timeout	126
ACAN: mAllrad_1 frame DLC failure 1	126
ACAN: mAllrad_1 frame timeout 2	127
ACAN: mAllrad_1 frame DLC failure 2	127
ACAN: mAllrad_1 frame timeout 3	127

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Überschrift	Seite
ACAN: mKombi_2 frame timeout	127
BUS_FAILURE_RAM07.00	128
BUS_FAILURE_RAM07.01	128
BUS_FAILURE_RAM07.02	128
BUS_FAILURE_RAM07.03	128
BUS_FAILURE_RAM07.04	129
BUS_FAILURE_RAM07.05	129
BUS_FAILURE_RAM07.06	129
BUS_FAILURE_RAM07.07	129
BUS_FAILURE_RAM07.08	130
BUS_FAILURE_RAM07.09	130
BUS_FAILURE_RAM07.0A	130
BUS_FAILURE_RAM07.0B	130
ACAN: mLWR_Zustand frame timeout	131
ACAN: mLWR_Zustand frame DLC failure	131
ACAN: M10_rel_Saugrohrdruck signal failure value	131
ACAN: mMotor_10 Start_Stop coding missmatch	131
ACAN: mMotor_10 Start_Stop configuration failure	132
ACAN: mMotor_10 frame DLC failure	132
ACAN: mMotor_10 frame timeout	132
ACAN: LW1_CRC signal failure	132
ACAN: LW1_ID wrong value	133
ACAN: LW1_Zaehler signal failure	133
ACAN: mLW_1 frame DLC failure	133
ACAN: mLW_1 frame timeout	133
ACAN: Global CAN frame timeout	134
ACAN: mKombi_1 frame timeout	134
ACAN: mKombi_1 frame DLC failure	134
ACAN: RCTA_01_CHK signal failure	134
ACAN: RCTA_01_BZ signal failure	135
ACAN: RCTA_01 frame timeout	135
ACAN: RCTA_01 frame DLC failure	135
ACAN: MO1_TiOut_Br signal is set	135
ACAN: AL1_Ist_Proz signal is set to not defined value	136
ACAN: AL1_Zaehler failure 4	136
ACAN: MO1_Pedalwert	136
ACAN: GE1_Zielgang	136

1.2 Details

1.2.1 loop processing failure

Object Identifier	Dia_Err_3
Object Text	loop processing failure
DTC-DFCC	0x000010
DTC-DFCC Text	loop processing failure
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.2 MCU RAM ckeck

Object Identifier	Dia_Err_4
Object Text	MCU RAM ckeck
DTC-DFCC	0x000011
DTC-DFCC Text	MCU RAM ckeck
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.3 MCU checksum check

Object Identifier	Dia_Err_5
Object Text	MCU checksum check
DTC-DFCC	0x000012
DTC-DFCC Text	MCU checksum check
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.4 MCU parity error: calculated ECC not identical to stored ECC

Object Identifier	Dia_Err_6
Object Text	MCU parity error: calculated ECC not identical to stored ECC
DTC-DFCC	0x000013
DTC-DFCC Text	MCU parity error: calculated ECC not identical to stored ECC
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.5 MCU redundancy error between the two CPUs

Object Identifier	Dia_Err_7
Object Text	MCU redundancy error between the two CPUs
DTC-DFCC	0x000014
DTC-DFCC Text	MCU redundancy error between the two CPUs
DTC-TI	B200FF0
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.6 illegal reset source causes and undefined boot procedure of the ECU

Object Identifier	Dia_Err_8
Object Text	illegal reset source causes and undefined boot procedure of the ECU
DTC-DFCC	0x000015
DTC-DFCC Text	illegal reset source causes and undefined boot procedure of the ECU
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.7 Internal_signal

Object Identifier	Dia_Err_9
Object Text	Internal_signal
DTC-DFCC	0x000017
DTC-DFCC Text	Internal_signal
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.8 PCU watch dog: loop timing failure

Object Identifier	Dia_Err_10
Object Text	PCU watch dog: loop timing failure
DTC-DFCC	0x000018
DTC-DFCC Text	PCU watch dog: loop timing failure
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.9 PCU is not able to deactivate the low-side drivers

Object Identifier	Dia_Err_11
Object Text	PCU is not able to deactivate the low-side drivers
DTC-DFCC	0x000019
DTC-DFCC Text	PCU is not able to deactivate the low-side drivers
DTC-TI	B200FF0

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.10 incorrect voltage drop at the high-side driver

Object Identifier	Dia_Err_12
Object Text	incorrect voltage drop at the high-side driver
DTC-DFCC	0x00001B
DTC-DFCC Text	incorrect voltage drop at the high-side driver
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.11 ECU contains incorrect software version lower F07 level

Object Identifier	Dia_Err_13
Object Text	ECU contains incorrect software version lower F07 level
DTC-DFCC	0x00001D
DTC-DFCC Text	ECU contains incorrect software version lower F07 level
DTC-TI	C109F00
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.12 EEPROM anomaly suspicion

Object Identifier	Dia_Err_14
Object Text	EEPROM anomaly suspicion
DTC-DFCC	0x00001E
DTC-DFCC Text	EEPROM anomaly suspicion
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.13 erroneous performance of HW components

Object Identifier	Dia_Err_15
Object Text	erroneous performance of HW components
DTC-DFCC	0x00001F
DTC-DFCC Text	erroneous performance of HW components

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.14 missing or false signal of rotational sense

Object Identifier	Dia_Err_16
Object Text	missing or false signal of rotational sense
DTC-DFCC	0x000026
DTC-DFCC Text	missing or false signal of rotational sense
DTC-TI	C101A29
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.15 mismatch between internal configuration and connected wheel speed sensor type

Object Identifier	Dia_Err_17
Object Text	mismatch between internal configuration and connected wheel speed sensor type
DTC-DFCC	0x000027
DTC-DFCC Text	mismatch between internal configuration and connected wheel speed sensor type
DTC-TI	C101A4A
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.16 sensor signal current temporarily too low

Object Identifier	Dia_Err_18
Object Text	sensor signal current temporarily too low
DTC-DFCC	0x000028
DTC-DFCC Text	sensor signal current temporarily too low
DTC-TI	C101A01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.17 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_19
Object Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-DFCC	0x000029
DTC-DFCC Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-TI	C101A29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.18 wheel speed too low

Object Identifier	Dia_Err_20
Object Text	wheel speed too low
DTC-DFCC	0x00002A
DTC-DFCC Text	wheel speed too low
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.19 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed

Object Identifier	Dia_Err_21
Object Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-DFCC	0x00002B
DTC-DFCC Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.20 pressure reduction phase and the following pressure hold phase too long

Object Identifier	Dia_Err_22
Object Text	pressure reduction phase and the following pressure hold phase too long
DTC-DFCC	0x00002C
DTC-DFCC Text	pressure reduction phase and the following pressure hold phase too long
DTC-TI	C101A07
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.21 deformation of tone wheel or one wheel defect temporarily

Object Identifier	Dia_Err_23
Object Text	deformation of tone wheel or one wheel defect temporarily
DTC-DFCC	0x00002D
DTC-DFCC Text	deformation of tone wheel or one wheel defect temporarily
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.22 sensor signal indicates noise

Object Identifier	Dia_Err_24
Object Text	sensor signal indicates noise
DTC-DFCC	0x00002E
DTC-DFCC Text	sensor signal indicates noise
DTC-TI	C101A29
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.23 sensor signal indicates noise

Object Identifier	Dia_Err_25
Object Text	sensor signal indicates noise
DTC-DFCC	0x00002F
DTC-DFCC Text	sensor signal indicates noise
DTC-TI	C101A29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.24 missing or false signal of rotational sense

Object Identifier	Dia_Err_26
Object Text	missing or false signal of rotational sense
DTC-DFCC	0x000036
DTC-DFCC Text	missing or false signal of rotational sense
DTC-TI	C101B29

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.25 mismatch between internal configuration and connected wheel speed sensor type

Object Identifier	Dia_Err_27
Object Text	mismatch between internal configuration and connected wheel speed sensor type
DTC-DFCC	0x000037
DTC-DFCC Text	mismatch between internal configuration and connected wheel speed sensor type
DTC-TI	C101B4A
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.26 sensor signal current temporarily too low

Object Identifier	Dia_Err_28
Object Text	sensor signal current temporarily too low
DTC-DFCC	0x000038
DTC-DFCC Text	sensor signal current temporarily too low
DTC-TI	C101B01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.27 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high

Object Identifier	Dia_Err_29
Object Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-DFCC	0x000039
DTC-DFCC Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-TI	C101B29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.28 wheel speed too low

Object Identifier	Dia_Err_30
Object Text	wheel speed too low
DTC-DFCC	0x00003A
DTC-DFCC Text	wheel speed too low
DTC-TI	C101B07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.29 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed

Object Identifier	Dia_Err_31
Object Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-DFCC	0x00003B
DTC-DFCC Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-TI	C101B07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.30 pressure reduction phase and the following pressure hold phase too long

Object Identifier	Dia_Err_32
Object Text	pressure reduction phase and the following pressure hold phase too long
DTC-DFCC	0x00003C
DTC-DFCC Text	pressure reduction phase and the following pressure hold phase too long
DTC-TI	C101B07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.31 deformation of tone wheel or one wheel defect temporarily

Object Identifier	Dia_Err_33
Object Text	deformation of tone wheel or one wheel defect temporarily
DTC-DFCC	0x00003D
DTC-DFCC Text	deformation of tone wheel or one wheel defect temporarily
DTC-TI	C101B07
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.32 sensor signal indicates noise

Object Identifier	Dia_Err_34
Object Text	sensor signal indicates noise
DTC-DFCC	0x00003E
DTC-DFCC Text	sensor signal indicates noise
DTC-TI	C101B29
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.33 sensor signal indicates noise

Object Identifier	Dia_Err_35
Object Text	sensor signal indicates noise
DTC-DFCC	0x00003F
DTC-DFCC Text	sensor signal indicates noise
DTC-TI	C101B29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.34 missing or false signal of rotational sense

Object Identifier	Dia_Err_36
Object Text	missing or false signal of rotational sense
DTC-DFCC	0x000046
DTC-DFCC Text	missing or false signal of rotational sense
DTC-TI	C101C29
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.35 mismatch between internal configuration and connected wheel speed sensor type

Object Identifier	Dia_Err_37
Object Text	mismatch between internal configuration and connected wheel speed sensor type
DTC-DFCC	0x000047

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC Text	mismatch between internal configuration and connected wheel speed sensor type
DTC-TI	C101C4A
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.36 sensor signal current temporarily too low

Object Identifier	Dia_Err_38
Object Text	sensor signal current temporarily too low
DTC-DFCC	0x000048
DTC-DFCC Text	sensor signal current temporarily too low
DTC-TI	C101C01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.37 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high

Object Identifier	Dia_Err_39
Object Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-DFCC	0x000049
DTC-DFCC Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-TI	C101C29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.38 wheel speed too low

Object Identifier	Dia_Err_40
Object Text	wheel speed too low
DTC-DFCC	0x00004A
DTC-DFCC Text	wheel speed too low
DTC-TI	C101C07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.39 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed

Object Identifier	Dia_Err_41
Object Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-DFCC	0x00004B
DTC-DFCC Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-TI	C101C07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.40 pressure reduction phase and the following pressure hold phase too long

Object Identifier	Dia_Err_42
Object Text	pressure reduction phase and the following pressure hold phase too long
DTC-DFCC	0x00004C
DTC-DFCC Text	pressure reduction phase and the following pressure hold phase too long
DTC-TI	C101C07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.41 deformation of tone wheel or one wheel defect temporarily

Object Identifier	Dia_Err_43
Object Text	deformation of tone wheel or one wheel defect temporarily
DTC-DFCC	0x00004D
DTC-DFCC Text	deformation of tone wheel or one wheel defect temporarily
DTC-TI	C101C07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.42 sensor signal indicates noise

Object Identifier	Dia_Err_44
Object Text	sensor signal indicates noise
DTC-DFCC	0x00004E
DTC-DFCC Text	sensor signal indicates noise
DTC-TI	C101C29
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.43 sensor signal indicates noise

Object Identifier	Dia_Err_45
Object Text	sensor signal indicates noise
DTC-DFCC	0x00004F
DTC-DFCC Text	sensor signal indicates noise
DTC-TI	C101C29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.44 missing or false signal of rotational sense

Object Identifier	Dia_Err_46
Object Text	missing or false signal of rotational sense
DTC-DFCC	0x000056
DTC-DFCC Text	missing or false signal of rotational sense
DTC-TI	C101D29
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.45 mismatch between internal configuration and connected wheel speed sensor type

Object Identifier	Dia_Err_47
Object Text	mismatch between internal configuration and connected wheel speed sensor type
DTC-DFCC	0x000057
DTC-DFCC Text	mismatch between internal configuration and connected wheel speed sensor type
DTC-TI	C101D4A
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.46 sensor signal current temporarily too low

Object Identifier	Dia_Err_48
Object Text	sensor signal current temporarily too low
DTC-DFCC	0x000058

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC Text	sensor signal current temporarily too low
DTC-TI	C101D01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.47 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high

Object Identifier	Dia_Err_49
Object Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-DFCC	0x000059
DTC-DFCC Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-TI	C101D29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.48 wheel speed too low

Object Identifier	Dia_Err_50
Object Text	wheel speed too low
DTC-DFCC	0x00005A
DTC-DFCC Text	wheel speed too low
DTC-TI	C101D07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.49 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed

Object Identifier	Dia_Err_51
Object Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-DFCC	0x00005B
DTC-DFCC Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-TI	C101D07
Beschreibung	n/a
Priorität (Level)	2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.50 pressure reduction phase and the following pressure hold phase too long

Object Identifier	Dia_Err_52
Object Text	pressure reduction phase and the following pressure hold phase too long
DTC-DFCC	0x00005C
DTC-DFCC Text	pressure reduction phase and the following pressure hold phase too long
DTC-TI	C101D07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.51 deformation of tone wheel or one wheel defect temporarily

Object Identifier	Dia_Err_53
Object Text	deformation of tone wheel or one wheel defect temporarily
DTC-DFCC	0x00005D
DTC-DFCC Text	deformation of tone wheel or one wheel defect temporarily
DTC-TI	C101D07
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.52 sensor signal indicates noise

Object Identifier	Dia_Err_54
Object Text	sensor signal indicates noise
DTC-DFCC	0x00005E
DTC-DFCC Text	sensor signal indicates noise
DTC-TI	C101D29
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.53 sensor signal indicates noise

Object Identifier	Dia_Err_55
Object Text	sensor signal indicates noise
DTC-DFCC	0x00005F
DTC-DFCC Text	sensor signal indicates noise
DTC-TI	C101D29
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.54 erroneous performance of HW components or supply voltage is out of range or FMON or PCU is not able to deactivate the high-side driver(s)

Object Identifier	Dia_Err_56
Object Text	erroneous performance of HW components or supply voltage is out of range or FMON or PCU is not able to deactivate the high-side driver(s)
DTC-DFCC	0x000060
DTC-DFCC Text	erroneous performance of HW components or supply voltage is out of range or FMON or PCU is not able to deactivate the high-side driver(s)
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.55 erroneous performance of HW components or supply voltage is out of range

Object Identifier	Dia_Err_57
Object Text	erroneous performance of HW components or supply voltage is out of range
DTC-DFCC	0x000062
DTC-DFCC Text	erroneous performance of HW components or supply voltage is out of range
DTC-TI	C101600
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.56 supply voltage is out of range

Object Identifier	Dia_Err_58
Object Text	supply voltage is out of range
DTC-DFCC	0x000064
DTC-DFCC Text	supply voltage is out of range
DTC-TI	C101600
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.57 pump freewheel

Object Identifier	Dia_Err_59
Object Text	pump freewheel

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC	0x000066
DTC-DFCC Text	pump freewheel
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.58 Pump life time ended

Object Identifier	Dia_Err_60
Object Text	Pump life time ended
DTC-DFCC	0x000067
DTC-DFCC Text	Pump life time ended
DTC-TI	C101504
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.59 insufficient pump motor generator voltage after end of pump motor activation

Object Identifier	Dia_Err_61
Object Text	insufficient pump motor generator voltage after end of pump motor activation
DTC-DFCC	0x000068
DTC-DFCC Text	insufficient pump motor generator voltage after end of pump motor activation
DTC-TI	C107704
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.60 voltage at pump motor too high/low when pump motor is deactivated

Object Identifier	Dia_Err_62
Object Text	voltage at pump motor too high/low when pump motor is deactivated
DTC-DFCC	0x000069
DTC-DFCC Text	voltage at pump motor too high/low when pump motor is deactivated
DTC-TI	C107701
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.61 voltage drop across the solid state pump switch is too high when the pump motor is activated - mechanically locked pump?

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_63
Object Text	voltage drop across the solid state pump switch is too high when the pump motor is activated - mechanically locked pump?
DTC-DFCC	0x00006A
DTC-DFCC Text	voltage drop across the solid state pump switch is too high when the pump motor is activated - mechanically locked pump?
DTC-TI	C107704
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.62 pump connection

Object Identifier	Dia_Err_64
Object Text	pump connection
DTC-DFCC	0x00006B
DTC-DFCC Text	pump connection
DTC-TI	C107701
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.63 inlet valve front left wheel

Object Identifier	Dia_Err_65
Object Text	inlet valve front left wheel
DTC-DFCC	0x000070
DTC-DFCC Text	inlet valve front left wheel
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.64 inlet valve front right wheel

Object Identifier	Dia_Err_66
Object Text	inlet valve front right wheel
DTC-DFCC	0x000071
DTC-DFCC Text	inlet valve front right wheel
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.65 inlet valve rear left wheel

Object Identifier	Dia_Err_67
Object Text	inlet valve rear left wheel
DTC-DFCC	0x000072
DTC-DFCC Text	inlet valve rear left wheel
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.66 inlet valve rear right wheel

Object Identifier	Dia_Err_68
Object Text	inlet valve rear right wheel
DTC-DFCC	0x000073
DTC-DFCC Text	inlet valve rear right wheel
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.67 outlet valve front left wheel

Object Identifier	Dia_Err_69
Object Text	outlet valve front left wheel
DTC-DFCC	0x000074
DTC-DFCC Text	outlet valve front left wheel
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.68 outlet valve front right wheel

Object Identifier	Dia_Err_70
Object Text	outlet valve front right wheel
DTC-DFCC	0x000075
DTC-DFCC Text	outlet valve front right wheel
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.69 outlet valve rear left wheel

Object Identifier	Dia_Err_71
Object Text	outlet valve rear left wheel
DTC-DFCC	0x000076
DTC-DFCC Text	outlet valve rear left wheel
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.70 outlet valve rear right wheel

Object Identifier	Dia_Err_72
Object Text	outlet valve rear right wheel
DTC-DFCC	0x000077
DTC-DFCC Text	outlet valve rear right wheel
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.71 master cylinder isolation valve 1

Object Identifier	Dia_Err_73
Object Text	master cylinder isolation valve 1
DTC-DFCC	0x000078
DTC-DFCC Text	master cylinder isolation valve 1
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.72 master cylinder isolation valve 2

Object Identifier	Dia_Err_74
Object Text	master cylinder isolation valve 2
DTC-DFCC	0x000079
DTC-DFCC Text	master cylinder isolation valve 2
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.73 low pressure feed valve 1

Object Identifier	Dia_Err_75
Object Text	low pressure feed valve 1
DTC-DFCC	0x00007A
DTC-DFCC Text	low pressure feed valve 1
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.74 low pressure feed valve 2

Object Identifier	Dia_Err_76
Object Text	low pressure feed valve 2
DTC-DFCC	0x00007B
DTC-DFCC Text	low pressure feed valve 2
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.75 valve redundancy monitoring

Object Identifier	Dia_Err_77
Object Text	valve redundancy monitoring
DTC-DFCC	0x00007C
DTC-DFCC Text	valve redundancy monitoring
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.76 valve current monitoring

Object Identifier	Dia_Err_78
Object Text	valve current monitoring
DTC-DFCC	0x00007D
DTC-DFCC Text	valve current monitoring
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.77 valve active test

Object Identifier	Dia_Err_79
Object Text	valve active test
DTC-DFCC	0x00007E
DTC-DFCC Text	valve active test
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.78 valve passive test

Object Identifier	Dia_Err_80
Object Text	valve passive test
DTC-DFCC	0x00007F
DTC-DFCC Text	valve passive test
DTC-TI	C101629
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.79 Undervoltage

Object Identifier	Dia_Err_81
Object Text	Undervoltage
DTC-DFCC	0x000080
DTC-DFCC Text	Undervoltage
DTC-TI	U140000
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.80 Overvoltage

Object Identifier	Dia_Err_82
Object Text	Overvoltage
DTC-DFCC	0x000081
DTC-DFCC Text	Overvoltage
DTC-TI	U140100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.81 supply voltage for external analog sensors out of the specified range

Object Identifier	Dia_Err_83
Object Text	supply voltage for external analog sensors out of the specified range
DTC-DFCC	0x000082
DTC-DFCC Text	supply voltage for external analog sensors out of the specified range
DTC-TI	B10AD01
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.82 supply voltage for external analog sensors out of the specified range

Object Identifier	Dia_Err_84
Object Text	supply voltage for external analog sensors out of the specified range
DTC-DFCC	0x000083
DTC-DFCC Text	supply voltage for external analog sensors out of the specified range
DTC-TI	B10AD01
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.83 supply voltage for external analog sensors out of the specified range

Object Identifier	Dia_Err_85
Object Text	supply voltage for external analog sensors out of the specified range
DTC-DFCC	0x000084
DTC-DFCC Text	supply voltage for external analog sensors out of the specified range
DTC-TI	B10AD01
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.84 duration of ESP brake intervention too long

Object Identifier	Dia_Err_86
Object Text	duration of ESP brake intervention too long
DTC-DFCC	0x00008B
DTC-DFCC Text	duration of ESP brake intervention too long
DTC-TI	C107529
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.85 valve calibrating data missing

Object Identifier	Dia_Err_87
Object Text	valve calibrating data missing
DTC-DFCC	0x00008F
DTC-DFCC Text	valve calibrating data missing
DTC-TI	U10C500
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.86 unplausible CAN signal of brake light switch

Object Identifier	Dia_Err_89
Object Text	unplausible CAN signal of brake light switch
DTC-DFCC	0x000094
DTC-DFCC Text	unplausible CAN signal of brake light switch
DTC-TI	P057100
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.87 unplausible signal of TC (ESC) tip switch

Object Identifier	Dia_Err_90
Object Text	unplausible signal of TC (ESC) tip switch
DTC-DFCC	0x00009C
DTC-DFCC Text	unplausible signal of TC (ESC) tip switch
DTC-TI	C109C29
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.88 unplausible signal of RKA tip switch

Object Identifier	Dia_Err_92
Object Text	unplausible signal of RKA tip switch
DTC-DFCC	***0x***
DTC-DFCC Text	unplausible signal of RKA tip switch
DTC-TI	C10C629
Beschreibung	Unplausibles Signal des RKA+ -Tasters über HeadUnit (Soft Key) bzw. nicht bedienbar
Priorität (Level)	2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.89 defective CAN Mailbox RAM cells

Object Identifier	Dia_Err_93
Object Text	defective CAN Mailbox RAM cells
DTC-DFCC	0x0000A0
DTC-DFCC Text	defective CAN Mailbox RAM cells
DTC-TI	C101600
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.90 ACAN: too many Bus Off events

Object Identifier	Dia_Err_94
Object Text	ACAN: too many Bus Off events
DTC-DFCC	0x0000A1
DTC-DFCC Text	ACAN: too many Bus Off events
DTC-TI	U120000
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.91 ACAN: mLW_1 frame timeout

Object Identifier	Dia_Err_95
Object Text	ACAN: mLW_1 frame timeout
DTC-DFCC	0x0000A6
DTC-DFCC Text	ACAN: mLW_1 frame timeout
DTC-TI	B116831
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.92 no valid Steering Wheel Angle Sensor signal received while storage of CAN signal faults inhibited

Object Identifier	Dia_Err_96
Object Text	no valid Steering Wheel Angle Sensor signal received while storage of CAN signal faults inhibited
DTC-DFCC	0x0000A7
DTC-DFCC Text	no valid Steering Wheel Angle Sensor signal received while storage of CAN signal faults inhibited

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.93 unplausible stored parameter code

Object Identifier	Dia_Err_97
Object Text	unplausible stored parameter code
DTC-DFCC	0x0000C1
DTC-DFCC Text	unplausible stored parameter code
DTC-TI	U101400
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.94 ECU marked as Not Configured because vehicle ID is invalid

Object Identifier	Dia_Err_98
Object Text	ECU marked as Not Configured because vehicle ID is invalid
DTC-DFCC	0x0000C3
DTC-DFCC Text	ECU marked as Not Configured because vehicle ID is invalid
DTC-TI	U101300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.95 CAN signal MO_Getriebe_Code wrong

Object Identifier	Dia_Err_100
Object Text	CAN signal MO_Getriebe_Code wrong
DTC-DFCC	0x0000C5
DTC-DFCC Text	CAN signal MO_Getriebe_Code wrong
DTC-TI	P164700
Beschreibung	Es wird eine ungültige Getriebecodierung vom Motor SG auf dem CAN gesendet.
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.96 incoherent information at non-volatile Memory

Object Identifier	Dia_Err_101
Object Text	incoherent information at non-volatile Memory

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC	0x0000C6
DTC-DFCC Text	incoherent information at non-volatile Memory
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.97 no valid Reverse Gear Switch signal received via CAN

Object Identifier	Dia_Err_102
Object Text	no valid Reverse Gear Switch signal received via CAN
DTC-DFCC	0x0000CA
DTC-DFCC Text	no valid Reverse Gear Switch signal received via CAN
DTC-TI	C109E29
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.98 sensor signal out of range

Object Identifier	Dia_Err_103
Object Text	sensor signal out of range
DTC-DFCC	0x0000D0
DTC-DFCC Text	sensor signal out of range
DTC-TI	C101729
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.99 calculated sensor offset out of specified range

Object Identifier	Dia_Err_104
Object Text	calculated sensor offset out of specified range
DTC-DFCC	0x0000D1
DTC-DFCC Text	calculated sensor offset out of specified range
DTC-TI	C101729
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.100 difference between sensor signal and calculated reference signal too high

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_105
Object Text	difference between sensor signal and calculated reference signal too high
DTC-DFCC	0x0000D2
DTC-DFCC Text	difference between sensor signal and calculated reference signal too high
DTC-TI	C101729
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.101 sensor selftest not passed

Object Identifier	Dia_Err_106
Object Text	sensor selftest not passed
DTC-DFCC	0x0000D3
DTC-DFCC Text	sensor selftest not passed
DTC-TI	C101701
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.102 immobilizer sends wrong vehicle identification number or sensor not calibrated

Object Identifier	Dia_Err_107
Object Text	immobilizer sends wrong vehicle identification number or sensor not calibrated
DTC-DFCC	0x0000D4
DTC-DFCC Text	immobilizer sends wrong vehicle identification number or sensor not calibrated
DTC-TI	C101754
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.103 Single Vacuum Pressure Sensor sends no valid data

Object Identifier	Dia_Err_108
Object Text	Single Vacuum Pressure Sensor sends no valid data
DTC-DFCC	0x0000D5
DTC-DFCC Text	Single Vacuum Pressure Sensor sends no valid data
DTC-TI	C10A301
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.104 Single Vacuum Pressure Sensor value changes with too high gradient

Object Identifier	Dia_Err_109
Object Text	Single Vacuum Pressure Sensor value changes with too high gradient
DTC-DFCC	0x0000D6
DTC-DFCC Text	Single Vacuum Pressure Sensor value changes with too high gradient
DTC-TI	C10A329
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.105 Single Vacuum Pressure Sensor value out of expected operating range

Object Identifier	Dia_Err_110
Object Text	Single Vacuum Pressure Sensor value out of expected operating range
DTC-DFCC	0x0000D8
DTC-DFCC Text	Single Vacuum Pressure Sensor value out of expected operating range
DTC-TI	C10A322
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.106 Single Vacuum Pressure Sensor value out of expected operating range

Object Identifier	Dia_Err_111
Object Text	Single Vacuum Pressure Sensor value out of expected operating range
DTC-DFCC	0x0000D9
DTC-DFCC Text	Single Vacuum Pressure Sensor value out of expected operating range
DTC-TI	C10A321
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.107 Single Vacuum Pressure Sensor value out of expected operating range

Object Identifier	Dia_Err_112
Object Text	Single Vacuum Pressure Sensor value out of expected operating range
DTC-DFCC	0x0000DA
DTC-DFCC Text	Single Vacuum Pressure Sensor value out of expected operating range
DTC-TI	C10A329
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.108 sensor signal out of range while vehicle is standing still

Object Identifier	Dia_Err_113
Object Text	sensor signal out of range while vehicle is standing still
DTC-DFCC	0x000100
DTC-DFCC Text	sensor signal out of range while vehicle is standing still
DTC-TI	C107D01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.109 calculated zero point of sensor out of specified range

Object Identifier	Dia_Err_114
Object Text	calculated zero point of sensor out of specified range
DTC-DFCC	0x000101
DTC-DFCC Text	calculated zero point of sensor out of specified range
DTC-TI	C107D01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.110 difference between sensor signal and calculated reference signal too high

Object Identifier	Dia_Err_115
Object Text	difference between sensor signal and calculated reference signal too high
DTC-DFCC	0x000102
DTC-DFCC Text	difference between sensor signal and calculated reference signal too high
DTC-TI	C107D01
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.111 sensor selftest not passed

Object Identifier	Dia_Err_116
Object Text	sensor selftest not passed
DTC-DFCC	0x000103
DTC-DFCC Text	sensor selftest not passed
DTC-TI	C107D01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.112 difference between sensor signal and calculated reference signal too high

Object Identifier	Dia_Err_117
Object Text	difference between sensor signal and calculated reference signal too high
DTC-DFCC	0x000104
DTC-DFCC Text	difference between sensor signal and calculated reference signal too high
DTC-TI	C107D29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.113 sensor clamping during dynamic driving

Object Identifier	Dia_Err_118
Object Text	sensor clamping during dynamic driving
DTC-DFCC	0x000105
DTC-DFCC Text	sensor clamping during dynamic driving
DTC-TI	C107D29
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.114 yaw rate scale factor out of range

Object Identifier	Dia_Err_119
Object Text	yaw rate scale factor out of range
DTC-DFCC	0x000106
DTC-DFCC Text	yaw rate scale factor out of range
DTC-TI	C107D29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.115 suspicion of plausibility failure

Object Identifier	Dia_Err_120
Object Text	suspicion of plausibility failure
DTC-DFCC	0x000107
DTC-DFCC Text	suspicion of plausibility failure
DTC-TI	C107D29
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.116 sensor signal out of range

Object Identifier	Dia_Err_121
Object Text	sensor signal out of range
DTC-DFCC	0x000108
DTC-DFCC Text	sensor signal out of range
DTC-TI	C107901
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.117 calculated sensor offset out of specified range

Object Identifier	Dia_Err_122
Object Text	calculated sensor offset out of specified range
DTC-DFCC	0x000109
DTC-DFCC Text	calculated sensor offset out of specified range
DTC-TI	C107901
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.118 sensor signal out of range while vehicle is standing still

Object Identifier	Dia_Err_123
Object Text	sensor signal out of range while vehicle is standing still
DTC-DFCC	0x00010A
DTC-DFCC Text	sensor signal out of range while vehicle is standing still
DTC-TI	C107901
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.119 sensor selftest not passed

Object Identifier	Dia_Err_124
Object Text	sensor selftest not passed
DTC-DFCC	0x00010B
DTC-DFCC Text	sensor selftest not passed
DTC-TI	C107901
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.120 difference between sensor signal and calculated reference signal too high

Object Identifier	Dia_Err_125
Object Text	difference between sensor signal and calculated reference signal too high
DTC-DFCC	0x00010C
DTC-DFCC Text	difference between sensor signal and calculated reference signal too high
DTC-TI	C107929
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.121 sensor clamping during dynamic driving

Object Identifier	Dia_Err_126
Object Text	sensor clamping during dynamic driving
DTC-DFCC	0x00010D
DTC-DFCC Text	sensor clamping during dynamic driving
DTC-TI	C107929
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.122 immobilizer sends wrong vehicle identification number or sensor not calibrated

Object Identifier	Dia_Err_127
Object Text	immobilizer sends wrong vehicle identification number or sensor not calibrated
DTC-DFCC	0x00010E
DTC-DFCC Text	immobilizer sends wrong vehicle identification number or sensor not calibrated
DTC-TI	C107954
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.123 suspicion of plausibility failure

Object Identifier	Dia_Err_128
Object Text	suspicion of plausibility failure
DTC-DFCC	0x00010F
DTC-DFCC Text	suspicion of plausibility failure
DTC-TI	C107929
Beschreibung	n/a
Priorität (Level)	2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	n/a

1.2.124 pressure signal P1 out of range or P1 signal shorted to P2T signal

Object Identifier	Dia_Err_129
Object Text	pressure signal P1 out of range or P1 signal shorted to P2T signal
DTC-DFCC	0x000110
DTC-DFCC Text	pressure signal P1 out of range or P1 signal shorted to P2T signal
DTC-TI	C107A01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.125 the calculated pressure sensor signal offset is out of range

Object Identifier	Dia_Err_130
Object Text	the calculated pressure sensor signal offset is out of range
DTC-DFCC	0x000111
DTC-DFCC Text	the calculated pressure sensor signal offset is out of range
DTC-TI	C107A01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.126 sensor noise out of range

Object Identifier	Dia_Err_131
Object Text	sensor noise out of range
DTC-DFCC	0x000112
DTC-DFCC Text	sensor noise out of range
DTC-TI	C107A01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.127 signal mismatch between pressure sensor output P1 and P2

Object Identifier	Dia_Err_132
Object Text	signal mismatch between pressure sensor output P1 and P2
DTC-DFCC	0x000116
DTC-DFCC Text	signal mismatch between pressure sensor output P1 and P2
DTC-TI	C107A29
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.128 immobilizer sends wrong vehicle identification number or sensor not calibrated

Object Identifier	Dia_Err_133
Object Text	immobilizer sends wrong vehicle identification number or sensor not calibrated
DTC-DFCC	0x000117
DTC-DFCC Text	immobilizer sends wrong vehicle identification number or sensor not calibrated
DTC-TI	C107A54
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.129 ne corrupted pressure sensor date has been detected within the relevant sensor EEPROM segments resp. registers during the init phase or if at least one failure condition within a loop has been detected longer than the specified min. fault duration during normal operation.

Object Identifier	Dia_Err_134
Object Text	ne corrupted pressure sensor date has been detected within the relevant sensor EEPROM segments resp. registers during the init phase or if at least one failure condition within a loop has been detected longer than the specified min. fault duration during normal operation.
DTC-DFCC	0x000118
DTC-DFCC Text	ne corrupted pressure sensor date has been detected within the relevant sensor EEPROM segments resp. registers during the init phase or if at least one failure condition within a loop has been detected longer than the specified min. fault duration during normal operation.
DTC-TI	C107A01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.130 the calculated pressure sensor signal offset is out of range

Object Identifier	Dia_Err_135
Object Text	the calculated pressure sensor signal offset is out of range
DTC-DFCC	0x000119
DTC-DFCC Text	the calculated pressure sensor signal offset is out of range
DTC-TI	C107A01
Beschreibung	n/a
Priorität (Level)	2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.131 at least one corrupted pressure sensor data transfer or command failure within a loop has been detected longer than the specified min. fault duration

Object Identifier	Dia_Err_136
Object Text	at least one corrupted pressure sensor data transfer or command failure within a loop has been detected longer than the specified min. fault duration
DTC-DFCC	0x00011B
DTC-DFCC Text	at least one corrupted pressure sensor data transfer or command failure within a loop has been detected longer than the specified min. fault duration
DTC-TI	C107A01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.132 temperature signal gradient out of range or time exceeded

Object Identifier	Dia_Err_137
Object Text	temperature signal gradient out of range or time exceeded
DTC-DFCC	0x00011C
DTC-DFCC Text	temperature signal gradient out of range or time exceeded
DTC-TI	C107A01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.133 calculated steering wheel angle offset is out of the specified range

Object Identifier	Dia_Err_138
Object Text	calculated steering wheel angle offset is out of the specified range
DTC-DFCC	0x000120
DTC-DFCC Text	calculated steering wheel angle offset is out of the specified range
DTC-TI	B116807
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.134 difference between sensor signal and calculated reference signal too high

Object Identifier	Dia_Err_139
Object Text	difference between sensor signal and calculated reference signal too high
DTC-DFCC	0x000121

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC Text	difference between sensor signal and calculated reference signal too high
DTC-TI	B116829
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.135 sensor clamping during dynamic driving

Object Identifier	Dia_Err_140
Object Text	sensor clamping during dynamic driving
DTC-DFCC	0x000122
DTC-DFCC Text	sensor clamping during dynamic driving
DTC-TI	B116829
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.136 invalid message / status defective from steering wheel angle sensor

Object Identifier	Dia_Err_141
Object Text	invalid message / status defective from steering wheel angle sensor
DTC-DFCC	0x000124
DTC-DFCC Text	invalid message / status defective from steering wheel angle sensor
DTC-TI	B116804
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.137 difference between sensor signal and calculated reference signal too high

Object Identifier	Dia_Err_142
Object Text	difference between sensor signal and calculated reference signal too high
DTC-DFCC	0x000125
DTC-DFCC Text	difference between sensor signal and calculated reference signal too high
DTC-TI	B116829
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.138 steering wheel angle sensor status changed into Not Initialized

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_143
Object Text	steering wheel angle sensor status changed into Not Initialized
DTC-DFCC	0x000126
DTC-DFCC Text	steering wheel angle sensor status changed into Not Initialized
DTC-TI	B116816
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.139 immobilizer sends wrong vehicle identification number or sensor not calibrated

Object Identifier	Dia_Err_144
Object Text	immobilizer sends wrong vehicle identification number or sensor not calibrated
DTC-DFCC	0x000127
DTC-DFCC Text	immobilizer sends wrong vehicle identification number or sensor not calibrated
DTC-TI	B116854
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.140 measured output signal of steering wheel angle sensor is out of range

Object Identifier	Dia_Err_145
Object Text	measured output signal of steering wheel angle sensor is out of range
DTC-DFCC	0x00012C
DTC-DFCC Text	measured output signal of steering wheel angle sensor is out of range
DTC-TI	B116807
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.141 suspicion of plausibility failure

Object Identifier	Dia_Err_146
Object Text	suspicion of plausibility failure
DTC-DFCC	0x00012D
DTC-DFCC Text	suspicion of plausibility failure
DTC-TI	B116829
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.142 difference between measured signals and the calculated reference signals is too high

Object Identifier	Dia_Err_147
Object Text	difference between measured signals and the calculated reference signals is too high
DTC-DFCC	0x00012E
DTC-DFCC Text	difference between measured signals and the calculated reference signals is too high
DTC-TI	C107529
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.143 vehicle deceleration higher than allowed for ACC brake intervention

Object Identifier	Dia_Err_148
Object Text	vehicle deceleration higher than allowed for ACC brake intervention
DTC-DFCC	0x00013B
DTC-DFCC Text	vehicle deceleration higher than allowed for ACC brake intervention
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.144 ACAN: Unplausible signal from ACC ECU

Object Identifier	Dia_Err_149
Object Text	ACAN: Unplausible signal from ACC ECU
DTC-DFCC	0x00013C
DTC-DFCC Text	ACAN: Unplausible signal from ACC ECU
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.145 ACC ECU does not deactivate the ACC function while driver is braking

Object Identifier	Dia_Err_150
Object Text	ACC ECU does not deactivate the ACC function while driver is braking
DTC-DFCC	0x00013D
DTC-DFCC Text	ACC ECU does not deactivate the ACC function while driver is braking
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.146 inlet valve calibration data missing

Object Identifier	Dia_Err_151
Object Text	inlet valve calibration data missing
DTC-DFCC	0x000152
DTC-DFCC Text	inlet valve calibration data missing
DTC-TI	U10C500
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.147 Coa_reset_error

Object Identifier	Dia_Err_152
Object Text	Coa_reset_error
DTC-DFCC	0x000157
DTC-DFCC Text	Coa_reset_error
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.148 Operating System fatal error

Object Identifier	Dia_Err_153
Object Text	Operating System fatal error
DTC-DFCC	0x000158
DTC-DFCC Text	Operating System fatal error
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.149 Operating System task 1 processing did not finish

Object Identifier	Dia_Err_154
Object Text	Operating System task 1 processing did not finish
DTC-DFCC	0x000159
DTC-DFCC Text	Operating System task 1 processing did not finish
DTC-TI	B200FF0
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.150 Operating System task 2 processing did not finish

Object Identifier	Dia_Err_155
Object Text	Operating System task 2 processing did not finish
DTC-DFCC	0x00015A
DTC-DFCC Text	Operating System task 2 processing did not finish
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.151 Operating System task 1 stackoverflow

Object Identifier	Dia_Err_156
Object Text	Operating System task 1 stackoverflow
DTC-DFCC	0x00015C
DTC-DFCC Text	Operating System task 1 stackoverflow
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.152 Operating System task 2 stackoverflow

Object Identifier	Dia_Err_157
Object Text	Operating System task 2 stackoverflow
DTC-DFCC	0x00015D
DTC-DFCC Text	Operating System task 2 stackoverflow
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.153 CSW task tries to access memory which is not assigned to CSW task context

Object Identifier	Dia_Err_158
Object Text	CSW task tries to access memory which is not assigned to CSW task context
DTC-DFCC	0x00015F
DTC-DFCC Text	CSW task tries to access memory which is not assigned to CSW task context
DTC-TI	B200FF0

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.154 The function AYC+TCS or EDS were deactivated by adaption

Object Identifier	Dia_Err_159
Object Text	The function AYC+TCS or EDS were deactivated by adaption
DTC-DFCC	0x00018A
DTC-DFCC Text	The function AYC+TCS or EDS were deactivated by adaption
DTC-TI	C10C800
Beschreibung	Die Funktion
	ESP, ASR oder MSR wurde per Anpassung im Steuergerät deaktiviert.
Priorität (Level)	6
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.155 Roller test bench mode active

Object Identifier	Dia_Err_160
Object Text	Roller test bench mode active
DTC-DFCC	0x00018C
DTC-DFCC Text	Roller test bench mode active
DTC-TI	C10A700
Beschreibung	n/a
Priorität (Level)	6
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.156 Vehicle equipped with vacuum sensor but no vacuum sensor coded

Object Identifier	Dia_Err_161
Object Text	Vehicle equipped with vacuum sensor but no vacuum sensor coded
DTC-DFCC	0x00018E
DTC-DFCC Text	Vehicle equipped with vacuum sensor but no vacuum sensor coded
DTC-TI	U101400
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.157 unplausible high acceleration value is detected

Object Identifier	Dia_Err_162
Object Text	unplausible high acceleration value is detected
DTC-DFCC	0x0001AA

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC Text	unplausible high acceleration value is detected
DTC-TI	C10B129
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.158 ACAN: unplausible signal of collision mitigation message

Object Identifier	Dia_Err_164
Object Text	ACAN: unplausible signal of collision mitigation message
DTC-DFCC	0x0001AC
DTC-DFCC Text	ACAN: unplausible signal of collision mitigation message
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.159 ACAN: unplausible signal of collision mitigation message

Object Identifier	Dia_Err_165
Object Text	ACAN: unplausible signal of collision mitigation message
DTC-DFCC	0x0001AD
DTC-DFCC Text	ACAN: unplausible signal of collision mitigation message
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.160 PCU bandgap error

Object Identifier	Dia_Err_166
Object Text	PCU bandgap error
DTC-DFCC	0x001000
DTC-DFCC Text	PCU bandgap error
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.161 Defective control of valve supply voltage

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_168
Object Text	Defective control of valve supply voltage
DTC-DFCC	0x001006
DTC-DFCC Text	Defective control of valve supply voltage
DTC-TI	B200FF0
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.162 valve calculated current

Object Identifier	Dia_Err_169
Object Text	valve calculated current
DTC-DFCC	0x001008
DTC-DFCC Text	valve calculated current
DTC-TI	C101600
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.163 Supply voltage for internal brake pressure sensor(s) out of range

Object Identifier	Dia_Err_170
Object Text	Supply voltage for internal brake pressure sensor(s) out of range
DTC-DFCC	0x001016
DTC-DFCC Text	Supply voltage for internal brake pressure sensor(s) out of range
DTC-TI	C107A29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.164 One of relevant VIN numbers does not match the selected vehicle variant

Object Identifier	Dia_Err_171
Object Text	One of relevant VIN numbers does not match the selected vehicle variant
DTC-DFCC	0x001040
DTC-DFCC Text	One of relevant VIN numbers does not match the selected vehicle variant
DTC-TI	U10D900
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.165 mismatch between VIN on CAN and VIN in coding word

Object Identifier	Dia_Err_172
Object Text	mismatch between VIN on CAN and VIN in coding word
DTC-DFCC	0x001041
DTC-DFCC Text	mismatch between VIN on CAN and VIN in coding word
DTC-TI	U10DA00
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.166 One of relevant VIN numbers is '-', 'X' or missing

Object Identifier	Dia_Err_173
Object Text	One of relevant VIN numbers is '-', 'X' or missing
DTC-DFCC	0x001042
DTC-DFCC Text	One of relevant VIN numbers is '-', 'X' or missing
DTC-TI	U10BC00
Beschreibung	n/a
Priorität (Level)	6
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.167 ECU defect

Object Identifier	Dia_Err_174
Object Text	ECU defect
DTC-DFCC	0x001045
DTC-DFCC Text	ECU defect
DTC-TI	B200000
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.168 sensor signal current too high

Object Identifier	Dia_Err_178
Object Text	sensor signal current too high
DTC-DFCC	0x001060
DTC-DFCC Text	sensor signal current too high
DTC-TI	C101A14
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.169 sensor signal current temporarily too high

Object Identifier	Dia_Err_179
Object Text	sensor signal current temporarily too high
DTC-DFCC	0x001061
DTC-DFCC Text	sensor signal current temporarily too high
DTC-TI	C101A14
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.170 sensor signal current too high

Object Identifier	Dia_Err_180
Object Text	sensor signal current too high
DTC-DFCC	0x001062
DTC-DFCC Text	sensor signal current too high
DTC-TI	C101B14
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.171 sensor signal current temporarily too high

Object Identifier	Dia_Err_181
Object Text	sensor signal current temporarily too high
DTC-DFCC	0x001063
DTC-DFCC Text	sensor signal current temporarily too high
DTC-TI	C101B14
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.172 sensor signal current too high

Object Identifier	Dia_Err_182
Object Text	sensor signal current too high
DTC-DFCC	0x001064
DTC-DFCC Text	sensor signal current too high
DTC-TI	C101C14
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.173 sensor signal current temporarily too high

Object Identifier	Dia_Err_183
Object Text	sensor signal current temporarily too high
DTC-DFCC	0x001065
DTC-DFCC Text	sensor signal current temporarily too high
DTC-TI	C101C14
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.174 sensor signal current too high

Object Identifier	Dia_Err_184
Object Text	sensor signal current too high
DTC-DFCC	0x001066
DTC-DFCC Text	sensor signal current too high
DTC-TI	C101D14
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.175 sensor signal current temporarily too high

Object Identifier	Dia_Err_185
Object Text	sensor signal current temporarily too high
DTC-DFCC	0x001067
DTC-DFCC Text	sensor signal current temporarily too high
DTC-TI	C101D14
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.176 Parity bit of wheel sensor has occured more than 7 times

Object Identifier	Dia_Err_186
Object Text	Parity bit of wheel sensor has occured more than 7 times
DTC-DFCC	0x00106C
DTC-DFCC Text	Parity bit of wheel sensor has occured more than 7 times
DTC-TI	C101A29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.177 Parity bit of wheel sensor has occured more than 7 times

Object Identifier	Dia_Err_187
Object Text	Parity bit of wheel sensor has occured more than 7 times
DTC-DFCC	0x00106D
DTC-DFCC Text	Parity bit of wheel sensor has occured more than 7 times
DTC-TI	C101B29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.178 Parity bit of wheel sensor has occured more than 7 times

Object Identifier	Dia_Err_188
Object Text	Parity bit of wheel sensor has occured more than 7 times
DTC-DFCC	0x00106E
DTC-DFCC Text	Parity bit of wheel sensor has occured more than 7 times
DTC-TI	C101C29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.179 Parity bit of wheel sensor has occured more than 7 times

Object Identifier	Dia_Err_189
Object Text	Parity bit of wheel sensor has occured more than 7 times
DTC-DFCC	0x00106F
DTC-DFCC Text	Parity bit of wheel sensor has occured more than 7 times
DTC-TI	C101D29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.180 Static or no significant variation of the vacuum signal during braking

Object Identifier	Dia_Err_191
Object Text	Static or no significant variation of the vacuum signal during braking
DTC-DFCC	0x001082
DTC-DFCC Text	Static or no significant variation of the vacuum signal during braking
DTC-TI	C10A329
Beschreibung	Der gemessene Unterdruck vom Einzelvakuumsensor steigt stark an / driftet stark.
Priorität (Level)	3

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.181 sensor signal 90 degrees turned

Object Identifier	Dia_Err_192
Object Text	sensor signal 90 degrees turned
DTC-DFCC	0x001088
DTC-DFCC Text	sensor signal 90 degrees turned
DTC-TI	C101729
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.182 sensor signal 180 degrees turned

Object Identifier	Dia_Err_193
Object Text	sensor signal 180 degrees turned
DTC-DFCC	0x001089
DTC-DFCC Text	sensor signal 180 degrees turned
DTC-TI	C101729
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.183 calculated vehicle acceleration compared with measured signal not plausible

Object Identifier	Dia_Err_194
Object Text	calculated vehicle acceleration compared with measured signal not plausible
DTC-DFCC	0x00108A
DTC-DFCC Text	calculated vehicle acceleration compared with measured signal not plausible
DTC-TI	C101729
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.184 No frames received from the vacuum sensor or Invalid data received from the sensor

Object Identifier	Dia_Err_195
Object Text	No frames received from the vacuum sensor or Invalid data received from the sensor
DTC-DFCC	0x00108B
DTC-DFCC Text	No frames received from the vacuum sensor or Invalid data received from the sensor

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-TI	C10A301
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.185 ECU calibration data in non-volatile memory missing or corrupt

Object Identifier	Dia_Err_196
Object Text	ECU calibration data in non-volatile memory missing or corrupt
DTC-DFCC	0x001090
DTC-DFCC Text	ECU calibration data in non-volatile memory missing or corrupt
DTC-TI	U10C500
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.186 Hecu_mismatch_fixable

Object Identifier	Dia_Err_198
Object Text	Hecu_mismatch_fixable
DTC-DFCC	0x00109E
DTC-DFCC Text	Hecu_mismatch_fixable
DTC-TI	B200FF0
Beschreibung	Fehler beim Vergleich der gespeicherten Daten für den PS100 Drucksensor und den Sensordaten selbst entdeckt.
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.187 Hecu_mismatch_final

Object Identifier	Dia_Err_199
Object Text	Hecu_mismatch_final
DTC-DFCC	0x00109F
DTC-DFCC Text	Hecu_mismatch_final
DTC-TI	B200FF0
Beschreibung	Fehler beim Vergleich der gespeicherten Daten für den PS100 Drucksensor und den Sensordaten selbst entdeckt.
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.188 absolute value of sensor signal is continuously too high

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_200
Object Text	absolute value of sensor signal is continuously too high
DTC-DFCC	0x0010B1
DTC-DFCC Text	absolute value of sensor signal is continuously too high
DTC-TI	C107D01
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.189 absolute value of sensor signal is continuously too high

Object Identifier	Dia_Err_201
Object Text	absolute value of sensor signal is continuously too high
DTC-DFCC	0x0010B2
DTC-DFCC Text	absolute value of sensor signal is continuously too high
DTC-TI	C107D01
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.190 internal SPI communication errors

Object Identifier	Dia_Err_202
Object Text	internal SPI communication errors
DTC-DFCC	0x0010B9
DTC-DFCC Text	internal SPI communication errors
DTC-TI	C107D29
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.191 internal SPI communication errors

Object Identifier	Dia_Err_203
Object Text	internal SPI communication errors
DTC-DFCC	0x0010BA
DTC-DFCC Text	internal SPI communication errors
DTC-TI	C107929
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.192 internal SPI communication errors

Object Identifier	Dia_Err_204
Object Text	internal SPI communication errors
DTC-DFCC	0x0010BB
DTC-DFCC Text	internal SPI communication errors
DTC-TI	C101729
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.193 customer software deactivated (RKA+ task aborted)

Object Identifier	Dia_Err_205
Object Text	customer software deactivated (RKA+ task aborted)
DTC-DFCC	0x0010E6
DTC-DFCC Text	customer software deactivated (RKA+ task aborted)
DTC-TI	C114600
Beschreibung	n/a
Priorität (Level)	9
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.194 Combustion Engine (CE) does not provide sufficient vacuum

Object Identifier	Dia_Err_206
Object Text	Combustion Engine (CE) does not provide sufficient vacuum
DTC-DFCC	0x0010F1
DTC-DFCC Text	Combustion Engine (CE) does not provide sufficient vacuum
DTC-TI	C10A321
Beschreibung	Der gemessene Unterdruck vom Einzelvakuumsensor liegt unterhalb des erwarteten Bereichs oder der gemessene Unterdruck vom Einzelvakuumsensor driftet stark
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.195 inplausible vacuum consumption without booster activation

Object Identifier	Dia_Err_207
Object Text	inplausible vacuum consumption without booster activation
DTC-DFCC	0x0010F3
DTC-DFCC Text	inplausible vacuum consumption without booster activation
DTC-TI	C10A129
Beschreibung	n/a
Priorität (Level)	3

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.196 FCAN: ACC_07 message is not received

Object Identifier	Dia_Err_208
Object Text	FCAN: ACC_07 message is not received
DTC-DFCC	0x002000
DTC-DFCC Text	FCAN: ACC_07 message is not received
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.197 ACAN: LH2_Zaehler signal failure

Object Identifier	Dia_Err_209
Object Text	ACAN: LH2_Zaehler signal failure
DTC-DFCC	0x002001
DTC-DFCC Text	ACAN: LH2_Zaehler signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.198 ACAN: mLenkhilfe_2 frame timeout

Object Identifier	Dia_Err_210
Object Text	ACAN: mLenkhilfe_2 frame timeout
DTC-DFCC	0x002002
DTC-DFCC Text	ACAN: mLenkhilfe_2 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.199 ACAN: mLenkhilfe_2 frame DLC failure

Object Identifier	Dia_Err_211
Object Text	ACAN: mLenkhilfe_2 frame DLC failure
DTC-DFCC	0x002003
DTC-DFCC Text	ACAN: mLenkhilfe_2 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.200 ACAN: LH3_Zaehler signal failure

Object Identifier	Dia_Err_212
Object Text	ACAN: LH3_Zaehler signal failure
DTC-DFCC	0x002004
DTC-DFCC Text	ACAN: LH3_Zaehler signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.201 ACAN: LH3_Checksumme signal failure

Object Identifier	Dia_Err_213
Object Text	ACAN: LH3_Checksumme signal failure
DTC-DFCC	0x002005
DTC-DFCC Text	ACAN: LH3_Checksumme signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.202 FCAN: ACC_10 message is received with invalid checksum

Object Identifier	Dia_Err_214
Object Text	FCAN: ACC_10 message is received with invalid checksum
DTC-DFCC	0x002006
DTC-DFCC Text	FCAN: ACC_10 message is received with invalid checksum
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.203 ACAN: LH3_Sta_DSR signal timeout value

Object Identifier	Dia_Err_215
Object Text	ACAN: LH3_Sta_DSR signal timeout value
DTC-DFCC	0x002007
DTC-DFCC Text	ACAN: LH3_Sta_DSR signal timeout value
DTC-TI	U112300

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.204 ACAN: LH3_Sta_DSR wrong range

Object Identifier	Dia_Err_216
Object Text	ACAN: LH3_Sta_DSR wrong range
DTC-DFCC	0x002008
DTC-DFCC Text	ACAN: LH3_Sta_DSR wrong range
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.205 ACAN: LH3_Lenkungstyp signal failure

Object Identifier	Dia_Err_217
Object Text	ACAN: LH3_Lenkungstyp signal failure
DTC-DFCC	0x002009
DTC-DFCC Text	ACAN: LH3_Lenkungstyp signal failure
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.206 ACAN: mLenkhilfe_3 frame DLC failure

Object Identifier	Dia_Err_218
Object Text	ACAN: mLenkhilfe_3 frame DLC failure
DTC-DFCC	0x00200A
DTC-DFCC Text	ACAN: mLenkhilfe_3 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.207 ACAN: mLenkhilfe_3 frame timeout

Object Identifier	Dia_Err_219
Object Text	ACAN: mLenkhilfe_3 frame timeout
DTC-DFCC	0x00200B
DTC-DFCC Text	ACAN: mLenkhilfe_3 frame timeout

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.208 ACAN: AL1_Ist_Proz and RDL closed failure

Object Identifier	Dia_Err_220
Object Text	ACAN: AL1_Ist_Proz and RDL closed failure
DTC-DFCC	0x00200C
DTC-DFCC Text	ACAN: AL1_Ist_Proz and RDL closed failure
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.209 FCAN: Airbag_02 message is received with invalid length

Object Identifier	Dia_Err_221
Object Text	FCAN: Airbag_02 message is received with invalid length
DTC-DFCC	0x00200D
DTC-DFCC Text	FCAN: Airbag_02 message is received with invalid length
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.210 ACAN: AL1_Ist_Proz and AL1_KupSteifig_F failure

Object Identifier	Dia_Err_222
Object Text	ACAN: AL1_Ist_Proz and AL1_KupSteifig_F failure
DTC-DFCC	0x00200E
DTC-DFCC Text	ACAN: AL1_Ist_Proz and AL1_KupSteifig_F failure
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.211 ACAN: MO1_Drehzahl signal failure value

Object Identifier	Dia_Err_223
Object Text	ACAN: MO1_Drehzahl signal failure value
DTC-DFCC	0x00200F

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC Text	ACAN: MO1_Drehzahl signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.212 ACAN: MO1_Sta_Pedal signal failure value

Object Identifier	Dia_Err_224
Object Text	ACAN: MO1_Sta_Pedal signal failure value
DTC-DFCC	0x002010
DTC-DFCC Text	ACAN: MO1_Sta_Pedal signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.213 ACAN: MO1_Verlustmo signal failure value

Object Identifier	Dia_Err_225
Object Text	ACAN: MO1_Verlustmo signal failure value
DTC-DFCC	0x002011
DTC-DFCC Text	ACAN: MO1_Verlustmo signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.214 ACAN: MO1_Mo_m_ex signal failure value

Object Identifier	Dia_Err_226
Object Text	ACAN: MO1_Mo_m_ex signal failure value
DTC-DFCC	0x002012
DTC-DFCC Text	ACAN: MO1_Mo_m_ex signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.215 ACAN: MO1_Mo_o_ex signal failure value

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_227
Object Text	ACAN: MO1_Mo_o_ex signal failure value
DTC-DFCC	0x002013
DTC-DFCC Text	ACAN: MO1_Mo_o_ex signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.216 FCAN: Diagnose_01 message is not received

Object Identifier	Dia_Err_230
Object Text	FCAN: Diagnose_01 message is not received
DTC-DFCC	0x002016
DTC-DFCC Text	FCAN: Diagnose_01 message is not received
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.217 ACAN: MO2_Leerlauf_Solldrehzahl signal failure value

Object Identifier	Dia_Err_231
Object Text	ACAN: MO2_Leerlauf_Solldrehzahl signal failure value
DTC-DFCC	0x002017
DTC-DFCC Text	ACAN: MO2_Leerlauf_Solldrehzahl signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.218 ACAN: MO3_FPGradient signal failure value

Object Identifier	Dia_Err_232
Object Text	ACAN: MO3_FPGradient signal failure value
DTC-DFCC	0x002018
DTC-DFCC Text	ACAN: MO3_FPGradient signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.219 ACAN: MO3_Pedalwert signal failure value

Object Identifier	Dia_Err_233
Object Text	ACAN: MO3_Pedalwert signal failure value
DTC-DFCC	0x002019
DTC-DFCC Text	ACAN: MO3_Pedalwert signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.220 ACAN: MO5_Checksumme failure value

Object Identifier	Dia_Err_234
Object Text	ACAN: MO5_Checksumme failure value
DTC-DFCC	0x00201A
DTC-DFCC Text	ACAN: MO5_Checksumme failure value
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.221 ACAN: Gearbox coding missmatch

Object Identifier	Dia_Err_235
Object Text	ACAN: Gearbox coding missmatch
DTC-DFCC	0x00201B
DTC-DFCC Text	ACAN: Gearbox coding missmatch
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.222 ACAN: GE1_Wahl_Pos signal falure value

Object Identifier	Dia_Err_236
Object Text	ACAN: GE1_Wahl_Pos signal falure value
DTC-DFCC	0x00201C
DTC-DFCC Text	ACAN: GE1_Wahl_Pos signal falure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.223 ACAN: GE1_Zaehler signal falure

Object Identifier	Dia_Err_237
Object Text	ACAN: GE1_Zaehler signal falure
DTC-DFCC	0x00201D
DTC-DFCC Text	ACAN: GE1_Zaehler signal falure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.224 ACAN: KO3_Verbau_Br signal wrong value

Object Identifier	Dia_Err_238
Object Text	ACAN: KO3_Verbau_Br signal wrong value
DTC-DFCC	0x00201E
DTC-DFCC Text	ACAN: KO3_Verbau_Br signal wrong value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.225 ACAN: AB1_Checksumme failure

Object Identifier	Dia_Err_239
Object Text	ACAN: AB1_Checksumme failure
DTC-DFCC	0x00201F
DTC-DFCC Text	ACAN: AB1_Checksumme failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.226 ACAN: Airbag coding missmatch

Object Identifier	Dia_Err_240
Object Text	ACAN: Airbag coding missmatch
DTC-DFCC	0x002020
DTC-DFCC Text	ACAN: Airbag coding missmatch
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.227 ACAN: AB1_Zaehler signal failure

Object Identifier	Dia_Err_241
Object Text	ACAN: AB1_Zaehler signal failure
DTC-DFCC	0x002021
DTC-DFCC Text	ACAN: AB1_Zaehler signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.228 ACAN: Airbag_03_CRC failure

Object Identifier	Dia_Err_242
Object Text	ACAN: Airbag_03_CRC failure
DTC-DFCC	0x002022
DTC-DFCC Text	ACAN: Airbag_03_CRC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.229 ACAN: Airbag_03_BZ failure

Object Identifier	Dia_Err_243
Object Text	ACAN: Airbag_03_BZ failure
DTC-DFCC	0x002023
DTC-DFCC Text	ACAN: Airbag_03_BZ failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.230 ACAN: Airbag_03 frame DLC timeout

Object Identifier	Dia_Err_244
Object Text	ACAN: Airbag_03 frame DLC timeout
DTC-DFCC	0x002024
DTC-DFCC Text	ACAN: Airbag_03 frame DLC timeout
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.231 FCAN: Klemmen_Status_01 message is received with invalid length

Object Identifier	Dia_Err_245
Object Text	FCAN: Klemmen_Status_01 message is received with invalid length
DTC-DFCC	0x002025
DTC-DFCC Text	FCAN: Klemmen_Status_01 message is received with invalid length
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.232 FCAN: Klemmen_Status_01 message is received with invalid checksum

Object Identifier	Dia_Err_246
Object Text	FCAN: Klemmen_Status_01 message is received with invalid checksum
DTC-DFCC	0x002026
DTC-DFCC Text	FCAN: Klemmen_Status_01 message is received with invalid checksum
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.233 FCAN: Klemmen_Status_01 message is received with invalid counter

Object Identifier	Dia_Err_247
Object Text	FCAN: Klemmen_Status_01 message is received with invalid counter
DTC-DFCC	0x002027
DTC-DFCC Text	FCAN: Klemmen_Status_01 message is received with invalid counter
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.234 FCAN: Kombi_02 message is not received

Object Identifier	Dia_Err_248
Object Text	FCAN: Kombi_02 message is not received
DTC-DFCC	0x002028
DTC-DFCC Text	FCAN: Kombi_02 message is not received
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.235 ACAN: AL1_Ist_Proz signal failure value

Object Identifier	Dia_Err_249
Object Text	ACAN: AL1_Ist_Proz signal failure value
DTC-DFCC	0x002029
DTC-DFCC Text	ACAN: AL1_Ist_Proz signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.236 ACAN: AL1_Sta_Kup signal wrong value

Object Identifier	Dia_Err_250
Object Text	ACAN: AL1_Sta_Kup signal wrong value
DTC-DFCC	0x00202A
DTC-DFCC Text	ACAN: AL1_Sta_Kup signal wrong value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.237 ACAN: Allrad_1 message RDL coding missmatch

Object Identifier	Dia_Err_251
Object Text	ACAN: Allrad_1 message RDL coding missmatch
DTC-DFCC	0x00202B
DTC-DFCC Text	ACAN: Allrad_1 message RDL coding missmatch
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.238 FCAN: Kombi_01 messagei is not received

Object Identifier	Dia_Err_252
Object Text	FCAN: Kombi_01 messagei is not received
DTC-DFCC	0x00202C
DTC-DFCC Text	FCAN: Kombi_01 messagei is not received
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.239 FCAN: Kombi_01 message is received with invalid length

Object Identifier	Dia_Err_253
Object Text	FCAN: Kombi_01 message is received with invalid length
DTC-DFCC	0x00202D
DTC-DFCC Text	FCAN: Kombi_01 message is received with invalid length
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.240 FCAN: LH_EPS_01 message is not received

Object Identifier	Dia_Err_254
Object Text	FCAN: LH_EPS_01 message is not received
DTC-DFCC	0x00202E
DTC-DFCC Text	FCAN: LH_EPS_01 message is not received
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.241 ACAN: AL1_Zaehler failure 3

Object Identifier	Dia_Err_255
Object Text	ACAN: AL1_Zaehler failure 3
DTC-DFCC	0x00202F
DTC-DFCC Text	ACAN: AL1_Zaehler failure 3
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.242 ACAN: GK1_Sta_Licht1 signal timeout

Object Identifier	Dia_Err_256
Object Text	ACAN: GK1_Sta_Licht1 signal timeout
DTC-DFCC	0x002030
DTC-DFCC Text	ACAN: GK1_Sta_Licht1 signal timeout
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.243 ACAN: GK1_Sta_ILM_F_1 signal timeout

Object Identifier	Dia_Err_257
Object Text	ACAN: GK1_Sta_ILM_F_1 signal timeout
DTC-DFCC	0x002031
DTC-DFCC Text	ACAN: GK1_Sta_ILM_F_1 signal timeout
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.244 ACAN: GK1_Sta_Tuerkont signal timeout

Object Identifier	Dia_Err_258
Object Text	ACAN: GK1_Sta_Tuerkont signal timeout
DTC-DFCC	0x002032
DTC-DFCC Text	ACAN: GK1_Sta_Tuerkont signal timeout
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.245 ACAN: MOB_Checksum signal failure

Object Identifier	Dia_Err_259
Object Text	ACAN: MOB_Checksum signal failure
DTC-DFCC	0x002033
DTC-DFCC Text	ACAN: MOB_Checksum signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.246 ACAN: MOB_Zaehler signal failure

Object Identifier	Dia_Err_260
Object Text	ACAN: MOB_Zaehler signal failure
DTC-DFCC	0x002034
DTC-DFCC Text	ACAN: MOB_Zaehler signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.247 ACAN: QS1_Kupplung signal failure value

Object Identifier	Dia_Err_261
Object Text	ACAN: QS1_Kupplung signal failure value
DTC-DFCC	0x002035
DTC-DFCC Text	ACAN: QS1_Kupplung signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.248 FCAN: Motor_Code_01 message is not received

Object Identifier	Dia_Err_262
Object Text	FCAN: Motor_Code_01 message is not received
DTC-DFCC	0x002036
DTC-DFCC Text	FCAN: Motor_Code_01 message is not received
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.249 FCAN: Motor_Code_01 message is received with invalid length

Object Identifier	Dia_Err_263
Object Text	FCAN: Motor_Code_01 message is received with invalid length
DTC-DFCC	0x002037
DTC-DFCC Text	FCAN: Motor_Code_01 message is received with invalid length
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.250 FCAN: Motor_Code_01 message is received with invalid checksum

Object Identifier	Dia_Err_264
Object Text	FCAN: Motor_Code_01 message is received with invalid checksum
DTC-DFCC	0x002038
DTC-DFCC Text	FCAN: Motor_Code_01 message is received with invalid checksum
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.251 FCAN: Motor_Code_01 message is received with invalid counter

Object Identifier	Dia_Err_265
Object Text	FCAN: Motor_Code_01 message is received with invalid counter
DTC-DFCC	0x002039
DTC-DFCC Text	FCAN: Motor_Code_01 message is received with invalid counter
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.252 ACAN: PL1_Stat_PLA_EPS signal wrong value received

Object Identifier	Dia_Err_266
Object Text	ACAN: PL1_Stat_PLA_EPS signal wrong value received
DTC-DFCC	0x00203A
DTC-DFCC Text	ACAN: PL1_Stat_PLA_EPS signal wrong value received
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.253 ACAN: SY1_Verbauinfo signal is not set

Object Identifier	Dia_Err_267
Object Text	ACAN: SY1_Verbauinfo signal is not set
DTC-DFCC	0x00203B
DTC-DFCC Text	ACAN: SY1_Verbauinfo signal is not set
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.254 ACAN: SY1_Lenker signal coding missmatch

Object Identifier	Dia_Err_268
Object Text	ACAN: SY1_Lenker signal coding missmatch
DTC-DFCC	0x00203C
DTC-DFCC Text	ACAN: SY1_Lenker signal coding missmatch
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.255 ACAN: AWV_Checksumme signal failure

Object Identifier	Dia_Err_269
Object Text	ACAN: AWV_Checksumme signal failure
DTC-DFCC	0x00203D
DTC-DFCC Text	ACAN: AWV_Checksumme signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.256 FCAN: Motor_12 message is not received

Object Identifier	Dia_Err_270
Object Text	FCAN: Motor_12 message is not received
DTC-DFCC	0x00203E
DTC-DFCC Text	FCAN: Motor_12 message is not received
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.257 ACAN: mMotor_1 frame timeout

Object Identifier	Dia_Err_271
Object Text	ACAN: mMotor_1 frame timeout
DTC-DFCC	0x00203F
DTC-DFCC Text	ACAN: mMotor_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.258 ACAN: mMotor_1 frame DLC failure

Object Identifier	Dia_Err_272
Object Text	ACAN: mMotor_1 frame DLC failure
DTC-DFCC	0x002040
DTC-DFCC Text	ACAN: mMotor_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.259 FCAN: Motor_14 message is received with invalid length

Object Identifier	Dia_Err_273
Object Text	FCAN: Motor_14 message is received with invalid length
DTC-DFCC	0x002041
DTC-DFCC Text	FCAN: Motor_14 message is received with invalid length
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.260 FCAN: Motor_20 message is not received

Object Identifier	Dia_Err_274
Object Text	FCAN: Motor_20 message is not received
DTC-DFCC	0x002042
DTC-DFCC Text	FCAN: Motor_20 message is not received
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.261 FCAN: Motor_20 message is received with invalid length

Object Identifier	Dia_Err_275
Object Text	FCAN: Motor_20 message is received with invalid length
DTC-DFCC	0x002043
DTC-DFCC Text	FCAN: Motor_20 message is received with invalid length
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.262 ACAN: mMotor_3 frame DLC failure

Object Identifier	Dia_Err_276
Object Text	ACAN: mMotor_3 frame DLC failure
DTC-DFCC	0x002044
DTC-DFCC Text	ACAN: mMotor_3 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.263 ACAN: mMotor_5 frame timeout

Object Identifier	Dia_Err_277
Object Text	ACAN: mMotor_5 frame timeout
DTC-DFCC	0x002045
DTC-DFCC Text	ACAN: mMotor_5 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.264 ACAN: mMotor_5 frame DLC failure

Object Identifier	Dia_Err_278
Object Text	ACAN: mMotor_5 frame DLC failure
DTC-DFCC	0x002046
DTC-DFCC Text	ACAN: mMotor_5 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.265 FCAN: Pla_01 message is received with invalid counter

Object Identifier	Dia_Err_279
Object Text	FCAN: Pla_01 message is received with invalid counter
DTC-DFCC	0x002047
DTC-DFCC Text	FCAN: Pla_01 message is received with invalid counter
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.266 ACAN: mMotor_7 frame DLC failure

Object Identifier	Dia_Err_280
Object Text	ACAN: mMotor_7 frame DLC failure
DTC-DFCC	0x002048
DTC-DFCC Text	ACAN: mMotor_7 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.267 ACAN: mGetriebe_1 frame timeout

Object Identifier	Dia_Err_281
Object Text	ACAN: mGetriebe_1 frame timeout
DTC-DFCC	0x002049
DTC-DFCC Text	ACAN: mGetriebe_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.268 ACAN: mGetriebe_1 frame DLC failure

Object Identifier	Dia_Err_282
Object Text	ACAN: mGetriebe_1 frame DLC failure
DTC-DFCC	0x00204A
DTC-DFCC Text	ACAN: mGetriebe_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.269 ACAN: mGetriebe_6 frame timeout

Object Identifier	Dia_Err_283
Object Text	ACAN: mGetriebe_6 frame timeout
DTC-DFCC	0x00204B
DTC-DFCC Text	ACAN: mGetriebe_6 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.270 ACAN: mGetriebe_6 frame DLC failure

Object Identifier	Dia_Err_284
Object Text	ACAN: mGetriebe_6 frame DLC failure
DTC-DFCC	0x00204C
DTC-DFCC Text	ACAN: mGetriebe_6 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.271 ACAN: mAllrad_1 frame timeout

Object Identifier	Dia_Err_285
Object Text	ACAN: mAllrad_1 frame timeout
DTC-DFCC	0x00204D
DTC-DFCC Text	ACAN: mAllrad_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.272 ACAN: mAllrad_1 frame timeout 1

Object Identifier	Dia_Err_286
Object Text	ACAN: mAllrad_1 frame timeout 1
DTC-DFCC	0x00204F
DTC-DFCC Text	ACAN: mAllrad_1 frame timeout 1
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.273 FCAN: Lwi_01 message is received with invalid checksum

Object Identifier	Dia_Err_287
Object Text	FCAN: Lwi_01 message is received with invalid checksum
DTC-DFCC	0x002050
DTC-DFCC Text	FCAN: Lwi_01 message is received with invalid checksum
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.274 FCAN: Lwi_01 message is received with invalid counter

Object Identifier	Dia_Err_288
Object Text	FCAN: Lwi_01 message is received with invalid counter
DTC-DFCC	0x002051
DTC-DFCC Text	FCAN: Lwi_01 message is received with invalid counter
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.275 FCAN: MO_Fahrpedalgradient signal is invalid

Object Identifier	Dia_Err_289
Object Text	FCAN: MO_Fahrpedalgradient signal is invalid
DTC-DFCC	0x002052
DTC-DFCC Text	FCAN: MO_Fahrpedalgradient signal is invalid
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.276 FCAN: MO_Fahrpedalrohwert signal is invalid

Object Identifier	Dia_Err_290
Object Text	FCAN: MO_Fahrpedalrohwert signal is invalid
DTC-DFCC	0x002053
DTC-DFCC Text	FCAN: MO_Fahrpedalrohwert signal is invalid
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.277 ACAN: mAllrad_1 frame DLC failure 3

Object Identifier	Dia_Err_291
Object Text	ACAN: mAllrad_1 frame DLC failure 3
DTC-DFCC	0x002054
DTC-DFCC Text	ACAN: mAllrad_1 frame DLC failure 3
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.278 ACAN: mGate_Komf_1 frame timeout

Object Identifier	Dia_Err_292
Object Text	ACAN: mGate_Komf_1 frame timeout
DTC-DFCC	0x002055
DTC-DFCC Text	ACAN: mGate_Komf_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.279 ACAN: mGate_Komf_1 frame DLC failure

Object Identifier	Dia_Err_293
Object Text	ACAN: mGate_Komf_1 frame DLC failure
DTC-DFCC	0x002056
DTC-DFCC Text	ACAN: mGate_Komf_1 frame DLC failure
DTC-TI	U112200
Beschreibung	Rechts-/Linkslenkerinfo passt nicht zur Codierung
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.280 FCAN: manual gearbox coded and gearbox messages received

Object Identifier	Dia_Err_294
Object Text	FCAN: manual gearbox coded and gearbox messages received
DTC-DFCC	0x002057
DTC-DFCC Text	FCAN: manual gearbox coded and gearbox messages received
DTC-TI	P161200
Beschreibung	Motor SG sendet "Handschalter" bei gleichzeitigem Empfang von Getriebebotschaften
Priorität (Level)	1
ODX	n/a

1.2.281 ACAN: mKombi_2 frame DLC failure

Object Identifier	Dia_Err_295
Object Text	ACAN: mKombi_2 frame DLC failure
DTC-DFCC	0x002058
DTC-DFCC Text	ACAN: mKombi_2 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.282 ACAN: mKombi_3 frame timeout

Object Identifier	Dia_Err_296
Object Text	ACAN: mKombi_3 frame timeout
DTC-DFCC	0x002059
DTC-DFCC Text	ACAN: mKombi_3 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.283 ACAN: mKombi_3 frame DLC failure

Object Identifier	Dia_Err_297
Object Text	ACAN: mKombi_3 frame DLC failure
DTC-DFCC	0x00205A
DTC-DFCC Text	ACAN: mKombi_3 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.284 ACAN: mAirbag_1 frame timeout

Object Identifier	Dia_Err_298
Object Text	ACAN: mAirbag_1 frame timeout
DTC-DFCC	0x00205B
DTC-DFCC Text	ACAN: mAirbag_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.285 ACAN: mAirbag_1 frame DLC failure

Object Identifier	Dia_Err_299
Object Text	ACAN: mAirbag_1 frame DLC failure
DTC-DFCC	0x00205C
DTC-DFCC Text	ACAN: mAirbag_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.286 ACAN: mAWV frame timeout

Object Identifier	Dia_Err_300
Object Text	ACAN: mAWV frame timeout
DTC-DFCC	0x00205D
DTC-DFCC Text	ACAN: mAWV frame timeout
DTC-TI	U112100
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.287 ACAN: mAWV frame DLC failure

Object Identifier	Dia_Err_301
Object Text	ACAN: mAWV frame DLC failure
DTC-DFCC	0x00205E
DTC-DFCC Text	ACAN: mAWV frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.288 ACAN: mMotor_Bremse frame timeout

Object Identifier	Dia_Err_302
Object Text	ACAN: mMotor_Bremse frame timeout
DTC-DFCC	0x00205F
DTC-DFCC Text	ACAN: mMotor_Bremse frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.289 ACAN: mMotor_Bremse frame DLC failure

Object Identifier	Dia_Err_303
Object Text	ACAN: mMotor_Bremse frame DLC failure
DTC-DFCC	0x002060
DTC-DFCC Text	ACAN: mMotor_Bremse frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.290 ACAN: mQuersperre_1 frame timeout

Object Identifier	Dia_Err_304
Object Text	ACAN: mQuersperre_1 frame timeout
DTC-DFCC	0x002061
DTC-DFCC Text	ACAN: mQuersperre_1 frame timeout
DTC-TI	U112100

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.291 ACAN: mQuersperre_1 frame DLC failure

Object Identifier	Dia_Err_305
Object Text	ACAN: mQuersperre_1 frame DLC failure
DTC-DFCC	0x002062
DTC-DFCC Text	ACAN: mQuersperre_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.292 ACAN: mSoll_Verbauliste_neu frame timeout

Object Identifier	Dia_Err_306
Object Text	ACAN: mSoll_Verbauliste_neu frame timeout
DTC-DFCC	0x002063
DTC-DFCC Text	ACAN: mSoll_Verbauliste_neu frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.293 ACAN: mSoll_Verbauliste_neu frame DLC failure

Object Identifier	Dia_Err_307
Object Text	ACAN: mSoll_Verbauliste_neu frame DLC failure
DTC-DFCC	0x002064
DTC-DFCC Text	ACAN: mSoll_Verbauliste_neu frame DLC failure
DTC-TI	U112200
Beschreibung	Steuergerät nicht auf Allrad kodiert, empfängt aber Botschaften
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.294 ACAN: mSoll_Verbauliste_neu frame timeout 1

Object Identifier	Dia_Err_308
Object Text	ACAN: mSoll_Verbauliste_neu frame timeout 1
DTC-DFCC	0x002065
DTC-DFCC Text	ACAN: mSoll_Verbauliste_neu frame timeout 1

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.295 ACAN: mSoll_Verbauliste_neu frame DLC failure 1

Object Identifier	Dia_Err_309
Object Text	ACAN: mSoll_Verbauliste_neu frame DLC failure 1
DTC-DFCC	0x002066
DTC-DFCC Text	ACAN: mSoll_Verbauliste_neu frame DLC failure 1
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.296 ACAN: mIdent frame timeout

Object Identifier	Dia_Err_310
Object Text	ACAN: mIdent frame timeout
DTC-DFCC	0x002067
DTC-DFCC Text	ACAN: mIdent frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.297 ACAN: mIdent frame DLC failure

Object Identifier	Dia_Err_311
Object Text	ACAN: mIdent frame DLC failure
DTC-DFCC	0x002068
DTC-DFCC Text	ACAN: mIdent frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.298 ACAN: mIdent signal timeout

Object Identifier	Dia_Err_312
Object Text	ACAN: mIdent signal timeout
DTC-DFCC	0x002069

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC Text	ACAN: mIdent signal timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.299 ACAN: mDiagnose_1 frame timeout

Object Identifier	Dia_Err_313
Object Text	ACAN: mDiagnose_1 frame timeout
DTC-DFCC	0x00206A
DTC-DFCC Text	ACAN: mDiagnose_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.300 ACAN: mDiagnose_1 frame DLC failure

Object Identifier	Dia_Err_314
Object Text	ACAN: mDiagnose_1 frame DLC failure
DTC-DFCC	0x00206B
DTC-DFCC Text	ACAN: mDiagnose_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.301 ACAN: mPLA_1 frame DLC failure

Object Identifier	Dia_Err_315
Object Text	ACAN: mPLA_1 frame DLC failure
DTC-DFCC	0x00206D
DTC-DFCC Text	ACAN: mPLA_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.302 ACAN: mSysteminfo_1 frame timeout

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_316
Object Text	ACAN: mSysteminfo_1 frame timeout
DTC-DFCC	0x00206E
DTC-DFCC Text	ACAN: mSysteminfo_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.303 ACAN: mSysteminfo_1 frame DLC failure

Object Identifier	Dia_Err_317
Object Text	ACAN: mSysteminfo_1 frame DLC failure
DTC-DFCC	0x00206F
DTC-DFCC Text	ACAN: mSysteminfo_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	EV_Brake1ESCCONTIVN75XGP2

1.2.304 sensor signal current temporarily too low

Object Identifier	Dia_Err_449
Object Text	sensor signal current temporarily too low
DTC-DFCC	0x000020
DTC-DFCC Text	sensor signal current temporarily too low
DTC-TI	C101A01
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.305 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high

Object Identifier	Dia_Err_450
Object Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-DFCC	0x000021
DTC-DFCC Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-TI	C101A29
Beschreibung	n/a
Priorität (Level)	2

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	n/a

1.2.306 wheel speed too low

Object Identifier	Dia_Err_503
Object Text	wheel speed too low
DTC-DFCC	0x000022
DTC-DFCC Text	wheel speed too low
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.307 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed

Object Identifier	Dia_Err_502
Object Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-DFCC	0x000023
DTC-DFCC Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.308 pressure reduction phase and the following pressure hold phase too long

Object Identifier	Dia_Err_501
Object Text	pressure reduction phase and the following pressure hold phase too long
DTC-DFCC	0x000024
DTC-DFCC Text	pressure reduction phase and the following pressure hold phase too long
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.309 deformation of tone wheel or one wheel defect temporarily

Object Identifier	Dia_Err_500
Object Text	deformation of tone wheel or one wheel defect temporarily
DTC-DFCC	0x000025

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC Text	deformation of tone wheel or one wheel defect temporarily
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.310 sensor signal current temporarily too low

Object Identifier	Dia_Err_499
Object Text	sensor signal current temporarily too low
DTC-DFCC	0x000030
DTC-DFCC Text	sensor signal current temporarily too low
DTC-TI	C101A01
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.311 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high

Object Identifier	Dia_Err_498
Object Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-DFCC	0x000031
DTC-DFCC Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-TI	C101A29
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.312 wheel speed too low

Object Identifier	Dia_Err_497
Object Text	wheel speed too low
DTC-DFCC	0x000032
DTC-DFCC Text	wheel speed too low
DTC-TI	C101B07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.313 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed

Object Identifier	Dia_Err_496
Object Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-DFCC	0x000033
DTC-DFCC Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.314 pressure reduction phase and the following pressure hold phase too long

Object Identifier	Dia_Err_495
Object Text	pressure reduction phase and the following pressure hold phase too long
DTC-DFCC	0x000034
DTC-DFCC Text	pressure reduction phase and the following pressure hold phase too long
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.315 deformation of tone wheel or one wheel defect temporarily

Object Identifier	Dia_Err_494
Object Text	deformation of tone wheel or one wheel defect temporarily
DTC-DFCC	0x000035
DTC-DFCC Text	deformation of tone wheel or one wheel defect temporarily
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.316 sensor signal current temporarily too low

Object Identifier	Dia_Err_493
Object Text	sensor signal current temporarily too low
DTC-DFCC	0x000040
DTC-DFCC Text	sensor signal current temporarily too low
DTC-TI	C101A01
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	2
ODX	n/a

1.2.317 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high

Object Identifier	Dia_Err_492
Object Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-DFCC	0x000041
DTC-DFCC Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-TI	C101A29
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.318 wheel speed too low

Object Identifier	Dia_Err_491
Object Text	wheel speed too low
DTC-DFCC	0x000042
DTC-DFCC Text	wheel speed too low
DTC-TI	C101C07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.319 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed

Object Identifier	Dia_Err_490
Object Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-DFCC	0x000043
DTC-DFCC Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.320 pressure reduction phase and the following pressure hold phase too long

Object Identifier	Dia_Err_489
Object Text	pressure reduction phase and the following pressure hold phase too long
DTC-DFCC	0x000044
DTC-DFCC Text	pressure reduction phase and the following pressure hold phase too long
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.321 deformation of tone wheel or one wheel defect temporarily

Object Identifier	Dia_Err_488
Object Text	deformation of tone wheel or one wheel defect temporarily
DTC-DFCC	0x000045
DTC-DFCC Text	deformation of tone wheel or one wheel defect temporarily
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.322 sensor signal current temporarily too low

Object Identifier	Dia_Err_487
Object Text	sensor signal current temporarily too low
DTC-DFCC	0x000050
DTC-DFCC Text	sensor signal current temporarily too low
DTC-TI	C101A01
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.323 wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high

Object Identifier	Dia_Err_486
Object Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-DFCC	0x000051
DTC-DFCC Text	wheel speed sensor signal changes erratically, wheel speed sensor signal is impossibly high
DTC-TI	C101A29
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	2
ODX	n/a

1.2.324 wheel speed too low

Object Identifier	Dia_Err_485
Object Text	wheel speed too low
DTC-DFCC	0x000052
DTC-DFCC Text	wheel speed too low
DTC-TI	C101D07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.325 missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed

Object Identifier	Dia_Err_484
Object Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-DFCC	0x000053
DTC-DFCC Text	missing wheel speed sensor signal or wheel speed sensor signal continuously indicates a too low wheel speed
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.326 pressure reduction phase and the following pressure hold phase too long

Object Identifier	Dia_Err_483
Object Text	pressure reduction phase and the following pressure hold phase too long
DTC-DFCC	0x000054
DTC-DFCC Text	pressure reduction phase and the following pressure hold phase too long
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.327 deformation of tone wheel or one wheel defect temporarily

Object Identifier	Dia_Err_482
Object Text	deformation of tone wheel or one wheel defect temporarily

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC	0x000055
DTC-DFCC Text	deformation of tone wheel or one wheel defect temporarily
DTC-TI	C101A07
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.328 Reifenkontrollanzeige Systemstörung

Object Identifier	Dia_Err_481
Object Text	Reifenkontrollanzeige Systemstörung
DTC-DFCC	0x00008E
DTC-DFCC Text	Reifenkontrollanzeige Systemstörung
DTC-TI	C1146F2
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.329 Taster für Reifenkontrollanzeige mechanischer Fehler

Object Identifier	Dia_Err_480
Object Text	Taster für Reifenkontrollanzeige mechanischer Fehler
DTC-DFCC	0x00009D
DTC-DFCC Text	Taster für Reifenkontrollanzeige mechanischer Fehler
DTC-TI	C10C607
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.330 unplausible coding request - invalid combination

Object Identifier	Dia_Err_479
Object Text	unplausible coding request - invalid combination
DTC-DFCC	0x0000C2
DTC-DFCC Text	unplausible coding request - invalid combination
DTC-TI	U10DA00
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.331 Integrity f TMC pressure sensor

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_478
Object Text	Integrity f TMC pressure sensor
DTC-DFCC	0x00011E
DTC-DFCC Text	Integrity f TMC pressure sensor
DTC-TI	C107A01
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.332 Swa_lost_initialization

Object Identifier	Dia_Err_477
Object Text	Swa_lost_initialization
DTC-DFCC	0x000129
DTC-DFCC Text	Swa_lost_initialization
DTC-TI	B116816
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.333 Swa_tol_check_wl_event

Object Identifier	Dia_Err_476
Object Text	Swa_tol_check_wl_event
DTC-DFCC	0x00012A
DTC-DFCC Text	Swa_tol_check_wl_event
DTC-TI	B116807
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.334 Eol_test_active

Object Identifier	Dia_Err_475
Object Text	Eol_test_active
DTC-DFCC	0x000140
DTC-DFCC Text	Eol_test_active
DTC-TI	C101F00
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.335 Eol_test_timeout

Object Identifier	Dia_Err_474
Object Text	Eol_test_timeout
DTC-DFCC	0x000141
DTC-DFCC Text	Eol_test_timeout
DTC-TI	C102AF0
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.336 Eol_yaw_rate_adjust

Object Identifier	Dia_Err_472
Object Text	Eol_yaw_rate_adjust
DTC-DFCC	0x000143
DTC-DFCC Text	Eol_yaw_rate_adjust
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.337 Eol_yaw_rate_sensor

Object Identifier	Dia_Err_471
Object Text	Eol_yaw_rate_sensor
DTC-DFCC	0x000144
DTC-DFCC Text	Eol_yaw_rate_sensor
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.338 Eol_lat_acc_sensor

Object Identifier	Dia_Err_470
Object Text	Eol_lat_acc_sensor
DTC-DFCC	0x000145
DTC-DFCC Text	Eol_lat_acc_sensor
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.339 Eol_yr_la_exchanged

Object Identifier	Dia_Err_469
Object Text	Eol_yr_la_exchanged
DTC-DFCC	0x000146
DTC-DFCC Text	Eol_yr_la_exchanged
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.340 Eol_yaw_rate_mounting

Object Identifier	Dia_Err_468
Object Text	Eol_yaw_rate_mounting
DTC-DFCC	0x000147
DTC-DFCC Text	Eol_yaw_rate_mounting
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.341 Eol_lat_acc_mounting

Object Identifier	Dia_Err_467
Object Text	Eol_lat_acc_mounting
DTC-DFCC	0x000148
DTC-DFCC Text	Eol_lat_acc_mounting
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.342 Eol_swa_sensor

Object Identifier	Dia_Err_466
Object Text	Eol_swa_sensor
DTC-DFCC	0x000149
DTC-DFCC Text	Eol_swa_sensor
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.343 Eol_brake_light_switch

Object Identifier	Dia_Err_465
Object Text	Eol_brake_light_switch
DTC-DFCC	0x00014A
DTC-DFCC Text	Eol_brake_light_switch
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.344 Eol_front_wheel_sensors_swap_a

Object Identifier	Dia_Err_464
Object Text	Eol_front_wheel_sensors_swap_a
DTC-DFCC	0x00014B
DTC-DFCC Text	Eol_front_wheel_sensors_swap_a
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.345 Eol_front_wheel_sensors_swap_b

Object Identifier	Dia_Err_463
Object Text	Eol_front_wheel_sensors_swap_b
DTC-DFCC	0x00014C
DTC-DFCC Text	Eol_front_wheel_sensors_swap_b
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.346 Eol_rear_wheel_sensors_swap_a

Object Identifier	Dia_Err_462
Object Text	Eol_rear_wheel_sensors_swap_a
DTC-DFCC	0x00014D
DTC-DFCC Text	Eol_rear_wheel_sensors_swap_a
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.347 Eol_rear_wheel_sensors_swap_b

Object Identifier	Dia_Err_461
Object Text	Eol_rear_wheel_sensors_swap_b
DTC-DFCC	0x00014E
DTC-DFCC Text	Eol_rear_wheel_sensors_swap_b
DTC-TI	C102A29
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.348 Reifendruckwarnung

Object Identifier	Dia_Err_460
Object Text	Reifendruckwarnung
DTC-DFCC	0x00018D
DTC-DFCC Text	Reifendruckwarnung
DTC-TI	C114602
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.349 Reifenkontrollanzeige zur Zeit nicht verfügbar

Object Identifier	Dia_Err_459
Object Text	Reifenkontrollanzeige zur Zeit nicht verfügbar
DTC-DFCC	0x0001B0
DTC-DFCC Text	Reifenkontrollanzeige zur Zeit nicht verfügbar
DTC-TI	C1146F0
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.350 Raddurchmesser unplausibel

Object Identifier	Dia_Err_458
Object Text	Raddurchmesser unplausibel
DTC-DFCC	0x0001B1
DTC-DFCC Text	Raddurchmesser unplausibel
DTC-TI	C10A800
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.351 Unreliable_velo_filt

Object Identifier	Dia_Err_457
Object Text	Unreliable_velo_filt
DTC-DFCC	0x0001BB
DTC-DFCC Text	Unreliable_velo_filt
DTC-TI	U140000
Beschreibung	n/a
Priorität (Level)	tbd
ODX	n/a

1.2.352 Reifenkontrollanzeige nicht verfügbar

Object Identifier	Dia_Err_456
Object Text	Reifenkontrollanzeige nicht verfügbar
DTC-DFCC	0x0001BF
DTC-DFCC Text	Reifenkontrollanzeige nicht verfügbar
DTC-TI	C1146F0
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.353 VIN stored in Eeprom is not identical to VIN on BUS

Object Identifier	Dia_Err_455
Object Text	VIN stored in Eeprom is not identical to VIN on BUS
DTC-DFCC	0x001043
DTC-DFCC Text	VIN stored in Eeprom is not identical to VIN on BUS
DTC-TI	U10DA00
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.354 TMC pressure is higher than 15 bar but the BLS was inactive for more than 1 s

Object Identifier	Dia_Err_454
Object Text	TMC pressure is higher than 15 bar but the BLS was inactive for more than 1 s
DTC-DFCC	0x001078
DTC-DFCC Text	TMC pressure is higher than 15 bar but the BLS was inactive for more than 1 s
DTC-TI	B131329
Beschreibung	n/a
Priorität (Level)	3

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

ODX	n/a

1.2.355 Pump motor calibration is corrupt or non-restorable

Object Identifier	Dia_Err_453
Object Text	Pump motor calibration is corrupt or non-restorable
DTC-DFCC	0x001092
DTC-DFCC Text	Pump motor calibration is corrupt or non-restorable
DTC-TI	C107729
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.356 ACAN: MO1_Sta_Bremse signal failure value

Object Identifier	Dia_Err_452
Object Text	ACAN: MO1_Sta_Bremse signal failure value
DTC-DFCC	0x002014
DTC-DFCC Text	ACAN: MO1_Sta_Bremse signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.357 ACAN: MO1_Sta_MotMo signal failure value

Object Identifier	Dia_Err_451
Object Text	ACAN: MO1_Sta_MotMo signal failure value
DTC-DFCC	0x002015
DTC-DFCC Text	ACAN: MO1_Sta_MotMo signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.358 ACAN: mAllrad_1 frame DLC failure

Object Identifier	Dia_Err_504
Object Text	ACAN: mAllrad_1 frame DLC failure
DTC-DFCC	0x00204E
DTC-DFCC Text	ACAN: mAllrad_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Priorität (Level)	2
ODX	n/a

1.2.359 ACAN: mPLA_1 frame timeout

Object Identifier	Dia_Err_505
Object Text	ACAN: mPLA_1 frame timeout
DTC-DFCC	0x00206C
DTC-DFCC Text	ACAN: mPLA_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.360 FCAN: WWSs_01_alt veraltet bit is set

Object Identifier	Dia_Err_318
Object Text	FCAN: WWSs_01_alt veraltet bit is set
DTC-DFCC	0x002070
DTC-DFCC Text	FCAN: WWSs_01_alt veraltet bit is set
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.361 FCAN: Getriebe_12_alt veraltet bit is set /Hybrid vehicles/

Object Identifier	Dia_Err_319
Object Text	FCAN: Getriebe_12_alt veraltet bit is set /Hybrid vehicles/
DTC-DFCC	0x002071
DTC-DFCC Text	FCAN: Getriebe_12_alt veraltet bit is set /Hybrid vehicles/
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.362 FCAN: Unplausible VIN number

Object Identifier	Dia_Err_320
Object Text	FCAN: Unplausible VIN number
DTC-DFCC	0x002072
DTC-DFCC Text	FCAN: Unplausible VIN number
DTC-TI	U112100

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.363 FCAN: PLA_Status_PLA_ESP signal is invalid

Object Identifier	Dia_Err_321
Object Text	FCAN: PLA_Status_PLA_ESP signal is invalid
DTC-DFCC	0x002073
DTC-DFCC Text	FCAN: PLA_Status_PLA_ESP signal is invalid
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.364 FCAN: StartStop not coded but MO_StartStopp_Status not equal 0

Object Identifier	Dia_Err_322
Object Text	FCAN: StartStop not coded but MO_StartStopp_Status not equal 0
DTC-DFCC	0x002074
DTC-DFCC Text	FCAN: StartStop not coded but MO_StartStopp_Status not equal 0
DTC-TI	U112200
Beschreibung	SG nicht auf StartStopp kodiert, empfängt aber StartStopp Signale
Priorität (Level)	2
ODX	n/a

1.2.365 FCAN: TSK_Codierung signal is invalid

Object Identifier	Dia_Err_323
Object Text	FCAN: TSK_Codierung signal is invalid
DTC-DFCC	0x002075
DTC-DFCC Text	FCAN: TSK_Codierung signal is invalid
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.366 FCAN: Damper not coded but Fahrwerk_01 message received

Object Identifier	Dia_Err_324
Object Text	FCAN: Damper not coded but Fahrwerk_01 message received
DTC-DFCC	0x002077
DTC-DFCC Text	FCAN: Damper not coded but Fahrwerk_01 message received

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-TI	U101400
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.367 FCAN: Coding of ESP and TSK does not fit together

Object Identifier	Dia_Err_325
Object Text	FCAN: Coding of ESP and TSK does not fit together
DTC-DFCC	0x00207A
DTC-DFCC Text	FCAN: Coding of ESP and TSK does not fit together
DTC-TI	P164700
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.368 FCAN: Motor_20 message is received with invalid checksum

Object Identifier	Dia_Err_326
Object Text	FCAN: Motor_20 message is received with invalid checksum
DTC-DFCC	0x00207B
DTC-DFCC Text	FCAN: Motor_20 message is received with invalid checksum
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.369 FCAN: Motor_20 message is received with invalid counter

Object Identifier	Dia_Err_327
Object Text	FCAN: Motor_20 message is received with invalid counter
DTC-DFCC	0x00207C
DTC-DFCC Text	FCAN: Motor_20 message is received with invalid counter
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.370 FCAN: Allrad_03 message is received with invalid counter

Object Identifier	Dia_Err_328
Object Text	FCAN: Allrad_03 message is received with invalid counter
DTC-DFCC	0x00207D

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

DTC-DFCC Text	FCAN: Allrad_03 message is received with invalid counter
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.371 FCAN: Motor_11 message is received with invalid checksum

Object Identifier	Dia_Err_329
Object Text	FCAN: Motor_11 message is received with invalid checksum
DTC-DFCC	0x00207E
DTC-DFCC Text	FCAN: Motor_11 message is received with invalid checksum
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.372 FCAN: Motor_11 message is received with invalid counter

Object Identifier	Dia_Err_330
Object Text	FCAN: Motor_11 message is received with invalid counter
DTC-DFCC	0x00207F
DTC-DFCC Text	FCAN: Motor_11 message is received with invalid counter
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.373 FCAN: Motor_12 message is received with invalid checksum

Object Identifier	Dia_Err_331
Object Text	FCAN: Motor_12 message is received with invalid checksum
DTC-DFCC	0x002080
DTC-DFCC Text	FCAN: Motor_12 message is received with invalid checksum
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.374 FCAN: Motor_12 message is received with invalid counter

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

Object Identifier	Dia_Err_332
Object Text	FCAN: Motor_12 message is received with invalid counter
DTC-DFCC	0x002081
DTC-DFCC Text	FCAN: Motor_12 message is received with invalid counter
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.375 HiL_CCan_Sens_Clust1_Checksum

Object Identifier	Dia_Err_333
Object Text	HiL_CCan_Sens_Clust1_Checksum
DTC-DFCC	0x002082
DTC-DFCC Text	HiL_CCan_Sens_Clust1_Checksum
DTC-TI	U112200
Beschreibung	Fehler bezogen auf Nachbildung Sensorsignale am HiL-Prüfstand
Priorität (Level)	n/a
ODX	n/a

1.2.376 HiL_CCan_Sens_Clust1_Counter

Object Identifier	Dia_Err_334
Object Text	HiL_CCan_Sens_Clust1_Counter
DTC-DFCC	0x002083
DTC-DFCC Text	HiL_CCan_Sens_Clust1_Counter
DTC-TI	U112200
Beschreibung	Fehler bezogen auf Nachbildung Sensorsignale am HiL-Prüfstand
Priorität (Level)	n/a
ODX	n/a

1.2.377 HiL_CCan_Sens_Clust1_Timeout

Object Identifier	Dia_Err_335
Object Text	HiL_CCan_Sens_Clust1_Timeout
DTC-DFCC	0x002084
DTC-DFCC Text	HiL_CCan_Sens_Clust1_Timeout
DTC-TI	U112100
Beschreibung	Fehler bezogen auf Nachbildung Sensorsignale am HiL-Prüfstand
Priorität (Level)	n/a
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.378 HiL_CCan_Sens_Clust1_Length

Object Identifier	Dia_Err_336
Object Text	HiL_CCan_Sens_Clust1_Length
DTC-DFCC	0x002085
DTC-DFCC Text	HiL_CCan_Sens_Clust1_Length
DTC-TI	U112200
Beschreibung	Fehler bezogen auf Nachbildung Sensorsignale am HiL-Prüfstand
Priorität (Level)	n/a
ODX	n/a

1.2.379 HiL_CCan_Sens_Clust2_Checksum

Object Identifier	Dia_Err_337
Object Text	HiL_CCan_Sens_Clust2_Checksum
DTC-DFCC	0x002086
DTC-DFCC Text	HiL_CCan_Sens_Clust2_Checksum
DTC-TI	U112200
Beschreibung	Fehler bezogen auf Nachbildung Sensorsignale am HiL-Prüfstand
Priorität (Level)	n/a
ODX	n/a

1.2.380 HiL_CCan_Sens_Clust2_Counter

Object Identifier	Dia_Err_338
Object Text	HiL_CCan_Sens_Clust2_Counter
DTC-DFCC	0x002087
DTC-DFCC Text	HiL_CCan_Sens_Clust2_Counter
DTC-TI	U112200
Beschreibung	Fehler bezogen auf Nachbildung Sensorsignale am HiL-Prüfstand
Priorität (Level)	n/a
ODX	n/a

1.2.381 HiL_CCan_Sens_Clust2_Timeout

Object Identifier	Dia_Err_339
Object Text	HiL_CCan_Sens_Clust2_Timeout
DTC-DFCC	0x002088
DTC-DFCC Text	HiL_CCan_Sens_Clust2_Timeout
DTC-TI	U112100
Beschreibung	Fehler bezogen auf Nachbildung Sensorsignale am HiL-Prüfstand
Priorität (Level)	n/a
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.382 HiL_CCan_Sens_Clust2_Length

Object Identifier	Dia_Err_340
Object Text	HiL_CCan_Sens_Clust2_Length
DTC-DFCC	0x002089
DTC-DFCC Text	HiL_CCan_Sens_Clust2_Length
DTC-TI	U112200
Beschreibung	Fehler bezogen auf Nachbildung Sensorsignale am HiL-Prüfstand
Priorität (Level)	n/a
ODX	n/a

1.2.383 ACAN: MO_QBit_Fahrpedalrohwert signal is invalid

Object Identifier	Dia_Err_341
Object Text	ACAN: MO_QBit_Fahrpedalrohwert signal is invalid
DTC-DFCC	0x00208A
DTC-DFCC Text	ACAN: MO_QBit_Fahrpedalrohwert signal is invalid
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.384 steering wheel angle sensor transmits internal state Not Calibrated

Object Identifier	Dia_Err_509
Object Text	steering wheel angle sensor transmits internal state Not Calibrated
DTC-DFCC	0x000123
DTC-DFCC Text	steering wheel angle sensor transmits internal state Not Calibrated
DTC-TI	B116829
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.385 ACAN: LH2_Checksumme signal failure

Object Identifier	Dia_Err_688
Object Text	ACAN: LH2_Checksumme signal failure
DTC-DFCC	0x002000
DTC-DFCC Text	ACAN: LH2_Checksumme signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.386 ACAN: LH3_Sta_DSR signal failure value

Object Identifier	Dia_Err_687
Object Text	ACAN: LH3_Sta_DSR signal failure value
DTC-DFCC	0x002006
DTC-DFCC Text	ACAN: LH3_Sta_DSR signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.387 ACAN: AL1_Ist_Proz and RDL open failure

Object Identifier	Dia_Err_686
Object Text	ACAN: AL1_Ist_Proz and RDL open failure
DTC-DFCC	0x00200D
DTC-DFCC Text	ACAN: AL1_Ist_Proz and RDL open failure
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.388 ACAN: MO2_Mo_ZWR signal failure value

Object Identifier	Dia_Err_685
Object Text	ACAN: MO2_Mo_ZWR signal failure value
DTC-DFCC	0x002016
DTC-DFCC Text	ACAN: MO2_Mo_ZWR signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.389 ACAN: Airbag_03 frame timeout

Object Identifier	Dia_Err_684
Object Text	ACAN: Airbag_03 frame timeout
DTC-DFCC	0x002025
DTC-DFCC Text	ACAN: Airbag_03 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.390 ACAN: 4WD coding missmatch

Object Identifier	Dia_Err_683
Object Text	ACAN: 4WD coding missmatch
DTC-DFCC	0x002026
DTC-DFCC Text	ACAN: 4WD coding missmatch
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.391 ACAN: AL1_Ist_Proz is open failure

Object Identifier	Dia_Err_682
Object Text	ACAN: AL1_Ist_Proz is open failure
DTC-DFCC	0x002027
DTC-DFCC Text	ACAN: AL1_Ist_Proz is open failure
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.392 ACAN: AL1_Ist_Proz is closed failure

Object Identifier	Dia_Err_681
Object Text	ACAN: AL1_Ist_Proz is closed failure
DTC-DFCC	0x002028
DTC-DFCC Text	ACAN: AL1_Ist_Proz is closed failure
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.393 ACAN: AL1_Quersp_Sta signal failure value

Object Identifier	Dia_Err_680
Object Text	ACAN: AL1_Quersp_Sta signal failure value
DTC-DFCC	0x00202C
DTC-DFCC Text	ACAN: AL1_Quersp_Sta signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.394 ACAN: AL1_Zaehler failure

Object Identifier	Dia_Err_679
Object Text	ACAN: AL1_Zaehler failure
DTC-DFCC	0x00202D
DTC-DFCC Text	ACAN: AL1_Zaehler failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.395 ACAN: AL1_Zaehler failure 2

Object Identifier	Dia_Err_678
Object Text	ACAN: AL1_Zaehler failure 2
DTC-DFCC	0x00202E
DTC-DFCC Text	ACAN: AL1_Zaehler failure 2
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.396 ACAN: IDT_VIN signals wrong value

Object Identifier	Dia_Err_677
Object Text	ACAN: IDT_VIN signals wrong value
DTC-DFCC	0x002036
DTC-DFCC Text	ACAN: IDT_VIN signals wrong value
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.397 ACAN: VL1_ABS signal not set

Object Identifier	Dia_Err_676
Object Text	ACAN: VL1_ABS signal not set
DTC-DFCC	0x002037
DTC-DFCC Text	ACAN: VL1_ABS signal not set
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.398 ACAN: PL1_Checksumme signal failure

Object Identifier	Dia_Err_675
Object Text	ACAN: PL1_Checksumme signal failure
DTC-DFCC	0x002038
DTC-DFCC Text	ACAN: PL1_Checksumme signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.399 ACAN: PL1_Zaehler signal failure

Object Identifier	Dia_Err_674
Object Text	ACAN: PL1_Zaehler signal failure
DTC-DFCC	0x002039
DTC-DFCC Text	ACAN: PL1_Zaehler signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.400 ACAN: AWV_Zaehler signal failure

Object Identifier	Dia_Err_673
Object Text	ACAN: AWV_Zaehler signal failure
DTC-DFCC	0x00203E
DTC-DFCC Text	ACAN: AWV_Zaehler signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.401 ACAN: mMotor_2 frame timeout

Object Identifier	Dia_Err_672
Object Text	ACAN: mMotor_2 frame timeout
DTC-DFCC	0x002041
DTC-DFCC Text	ACAN: mMotor_2 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.402 ACAN: mMotor_2 frame DLC failure

Object Identifier	Dia_Err_671
Object Text	ACAN: mMotor_2 frame DLC failure
DTC-DFCC	0x002042
DTC-DFCC Text	ACAN: mMotor_2 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.403 ACAN: mMotor_3 frame timeout

Object Identifier	Dia_Err_670
Object Text	ACAN: mMotor_3 frame timeout
DTC-DFCC	0x002043
DTC-DFCC Text	ACAN: mMotor_3 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.404 ACAN: mMotor_7 frame timeout

Object Identifier	Dia_Err_669
Object Text	ACAN: mMotor_7 frame timeout
DTC-DFCC	0x002047
DTC-DFCC Text	ACAN: mMotor_7 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

1.2.405 ACAN: mAllrad_1 frame DLC failure 1

Object Identifier	Dia_Err_668
Object Text	ACAN: mAllrad_1 frame DLC failure 1
DTC-DFCC	0x002050
DTC-DFCC Text	ACAN: mAllrad_1 frame DLC failure 1
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.406 ACAN: mAllrad_1 frame timeout 2

Object Identifier	Dia_Err_667
Object Text	ACAN: mAllrad_1 frame timeout 2
DTC-DFCC	0x002051
DTC-DFCC Text	ACAN: mAllrad_1 frame timeout 2
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.407 ACAN: mAllrad_1 frame DLC failure 2

Object Identifier	Dia_Err_666
Object Text	ACAN: mAllrad_1 frame DLC failure 2
DTC-DFCC	0x002052
DTC-DFCC Text	ACAN: mAllrad_1 frame DLC failure 2
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.408 ACAN: mAllrad_1 frame timeout 3

Object Identifier	Dia_Err_665
Object Text	ACAN: mAllrad_1 frame timeout 3
DTC-DFCC	0x002053
DTC-DFCC Text	ACAN: mAllrad_1 frame timeout 3
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.409 ACAN: mKombi_2 frame timeout

Object Identifier	Dia_Err_664
Object Text	ACAN: mKombi_2 frame timeout
DTC-DFCC	0x002057
DTC-DFCC Text	ACAN: mKombi_2 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.410 BUS_FAILURE_RAM07.00

Object Identifier	Dia_Err_663
Object Text	BUS_FAILURE_RAM07.00
DTC-DFCC	0x002070
DTC-DFCC Text	BUS_FAILURE_RAM07.00
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.411 BUS_FAILURE_RAM07.01

Object Identifier	Dia_Err_662
Object Text	BUS_FAILURE_RAM07.01
DTC-DFCC	0x002071
DTC-DFCC Text	BUS_FAILURE_RAM07.01
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.412 BUS_FAILURE_RAM07.02

Object Identifier	Dia_Err_661
Object Text	BUS_FAILURE_RAM07.02
DTC-DFCC	0x002072
DTC-DFCC Text	BUS_FAILURE_RAM07.02
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.413 BUS_FAILURE_RAM07.03

Object Identifier	Dia_Err_660
Object Text	BUS_FAILURE_RAM07.03
DTC-DFCC	0x002073
DTC-DFCC Text	BUS_FAILURE_RAM07.03
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.414 BUS_FAILURE_RAM07.04

Object Identifier	Dia_Err_659
Object Text	BUS_FAILURE_RAM07.04
DTC-DFCC	0x002074
DTC-DFCC Text	BUS_FAILURE_RAM07.04
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.415 BUS_FAILURE_RAM07.05

Object Identifier	Dia_Err_658
Object Text	BUS_FAILURE_RAM07.05
DTC-DFCC	0x002075
DTC-DFCC Text	BUS_FAILURE_RAM07.05
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.416 BUS_FAILURE_RAM07.06

Object Identifier	Dia_Err_657
Object Text	BUS_FAILURE_RAM07.06
DTC-DFCC	0x002076
DTC-DFCC Text	BUS_FAILURE_RAM07.06
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.417 BUS_FAILURE_RAM07.07

Object Identifier	Dia_Err_656
Object Text	BUS_FAILURE_RAM07.07
DTC-DFCC	0x002077
DTC-DFCC Text	BUS_FAILURE_RAM07.07
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.418 BUS_FAILURE_RAM07.08

Object Identifier	Dia_Err_655
Object Text	BUS_FAILURE_RAM07.08
DTC-DFCC	0x002078
DTC-DFCC Text	BUS_FAILURE_RAM07.08
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.419 BUS_FAILURE_RAM07.09

Object Identifier	Dia_Err_654
Object Text	BUS_FAILURE_RAM07.09
DTC-DFCC	0x002079
DTC-DFCC Text	BUS_FAILURE_RAM07.09
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.420 BUS_FAILURE_RAM07.0A

Object Identifier	Dia_Err_653
Object Text	BUS_FAILURE_RAM07.0A
DTC-DFCC	0x00207A
DTC-DFCC Text	BUS_FAILURE_RAM07.0A
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.421 BUS_FAILURE_RAM07.0B

Object Identifier	Dia_Err_652
Object Text	BUS_FAILURE_RAM07.0B
DTC-DFCC	0x00207B
DTC-DFCC Text	BUS_FAILURE_RAM07.0B
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.422 ACAN: mLWR_Zustand frame timeout

Object Identifier	Dia_Err_651
Object Text	ACAN: mLWR_Zustand frame timeout
DTC-DFCC	0x00207C
DTC-DFCC Text	ACAN: mLWR_Zustand frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.423 ACAN: mLWR_Zustand frame DLC failure

Object Identifier	Dia_Err_650
Object Text	ACAN: mLWR_Zustand frame DLC failure
DTC-DFCC	0x00207D
DTC-DFCC Text	ACAN: mLWR_Zustand frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.424 ACAN: M10_rel_Saugrohrdruck signal failure value

Object Identifier	Dia_Err_649
Object Text	ACAN: M10_rel_Saugrohrdruck signal failure value
DTC-DFCC	0x00207E
DTC-DFCC Text	ACAN: M10_rel_Saugrohrdruck signal failure value
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.425 ACAN: mMotor_10 Start_Stop coding missmatch

Object Identifier	Dia_Err_648
Object Text	ACAN: mMotor_10 Start_Stop coding missmatch
DTC-DFCC	0x00207F
DTC-DFCC Text	ACAN: mMotor_10 Start_Stop coding missmatch
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.426 ACAN: mMotor_10 Start_Stop configuration failure

Object Identifier	Dia_Err_647
Object Text	ACAN: mMotor_10 Start_Stop configuration failure
DTC-DFCC	0x002080
DTC-DFCC Text	ACAN: mMotor_10 Start_Stop configuration failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.427 ACAN: mMotor_10 frame DLC failure

Object Identifier	Dia_Err_646
Object Text	ACAN: mMotor_10 frame DLC failure
DTC-DFCC	0x002081
DTC-DFCC Text	ACAN: mMotor_10 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.428 ACAN: mMotor_10 frame timeout

Object Identifier	Dia_Err_645
Object Text	ACAN: mMotor_10 frame timeout
DTC-DFCC	0x002082
DTC-DFCC Text	ACAN: mMotor_10 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.429 ACAN: LW1_CRC signal failure

Object Identifier	Dia_Err_644
Object Text	ACAN: LW1_CRC signal failure
DTC-DFCC	0x002083
DTC-DFCC Text	ACAN: LW1_CRC signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.430 ACAN: LW1_ID wrong value

Object Identifier	Dia_Err_643
Object Text	ACAN: LW1_ID wrong value
DTC-DFCC	0x002084
DTC-DFCC Text	ACAN: LW1_ID wrong value
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.431 ACAN: LW1_Zaehler signal failure

Object Identifier	Dia_Err_642
Object Text	ACAN: LW1_Zaehler signal failure
DTC-DFCC	0x002085
DTC-DFCC Text	ACAN: LW1_Zaehler signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.432 ACAN: mLW_1 frame DLC failure

Object Identifier	Dia_Err_641
Object Text	ACAN: mLW_1 frame DLC failure
DTC-DFCC	0x002086
DTC-DFCC Text	ACAN: mLW_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.433 ACAN: mLW_1 frame timeout

Object Identifier	Dia_Err_640
Object Text	ACAN: mLW_1 frame timeout
DTC-DFCC	0x002087
DTC-DFCC Text	ACAN: mLW_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.434 ACAN: Global CAN frame timeout

Object Identifier	Dia_Err_639
Object Text	ACAN: Global CAN frame timeout
DTC-DFCC	0x002088
DTC-DFCC Text	ACAN: Global CAN frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.435 ACAN: mKombi_1 frame timeout

Object Identifier	Dia_Err_638
Object Text	ACAN: mKombi_1 frame timeout
DTC-DFCC	0x002089
DTC-DFCC Text	ACAN: mKombi_1 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.436 ACAN: mKombi_1 frame DLC failure

Object Identifier	Dia_Err_637
Object Text	ACAN: mKombi_1 frame DLC failure
DTC-DFCC	0x00208A
DTC-DFCC Text	ACAN: mKombi_1 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.437 ACAN: RCTA_01_CHK signal failure

Object Identifier	Dia_Err_636
Object Text	ACAN: RCTA_01_CHK signal failure
DTC-DFCC	0x00208B
DTC-DFCC Text	ACAN: RCTA_01_CHK signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.438 ACAN: RCTA_01_BZ signal failure

Object Identifier	Dia_Err_635
Object Text	ACAN: RCTA_01_BZ signal failure
DTC-DFCC	0x00208C
DTC-DFCC Text	ACAN: RCTA_01_BZ signal failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.439 ACAN: RCTA_01 frame timeout

Object Identifier	Dia_Err_634
Object Text	ACAN: RCTA_01 frame timeout
DTC-DFCC	0x00208D
DTC-DFCC Text	ACAN: RCTA_01 frame timeout
DTC-TI	U112100
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.440 ACAN: RCTA_01 frame DLC failure

Object Identifier	Dia_Err_633
Object Text	ACAN: RCTA_01 frame DLC failure
DTC-DFCC	0x00208E
DTC-DFCC Text	ACAN: RCTA_01 frame DLC failure
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	3
ODX	n/a

1.2.441 ACAN: MO1_TiOut_Br signal is set

Object Identifier	Dia_Err_632
Object Text	ACAN: MO1_TiOut_Br signal is set
DTC-DFCC	0x00208F
DTC-DFCC Text	ACAN: MO1_TiOut_Br signal is set
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	1
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft

1.2.442 ACAN: AL1_Ist_Proz signal is set to not defined value

Object Identifier	Dia_Err_631
Object Text	ACAN: AL1_Ist_Proz signal is set to not defined value
DTC-DFCC	0x002090
DTC-DFCC Text	ACAN: AL1_Ist_Proz signal is set to not defined value
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.443 ACAN: AL1_Zaehler failure 4

Object Identifier	Dia_Err_630
Object Text	ACAN: AL1_Zaehler failure 4
DTC-DFCC	0x002091
DTC-DFCC Text	ACAN: AL1_Zaehler failure 4
DTC-TI	U112200
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.444 ACAN: MO1_Pedalwert

Object Identifier	Dia_Err_691
Object Text	ACAN: MO1_Pedalwert
DTC-DFCC	0x002092
DTC-DFCC Text	ACAN: MO1_Pedalwert
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

1.2.445 ACAN: GE1_Zielgang

Object Identifier	Dia_Err_692
Object Text	ACAN: GE1_Zielgang
DTC-DFCC	0x002093
DTC-DFCC Text	ACAN: GE1_Zielgang
DTC-TI	U112300
Beschreibung	n/a
Priorität (Level)	2
ODX	n/a

Vertraulich. Alle Rechte vorbehalten. Weitergabe oder Vervielfältigung ohne vorherige schriftliche Zustimmung des Fachbereiches der Volkswagen Aktiengesellschaft verboten. Vertragspartner erhalten dieses Dokument nur über die zuständige Beschaffungsabteilung.

© Volkswagen Aktiengesellschaft