

LANDLORD REPORT

Owner & Managing-Agent Report

What has been recorded, what it needs, what that costs and what remains unknown

PROPERTY

Two-bedroom house, City Bowl, Cape Town

REFERENCE

SAMPLE-B

INSPECTION DATE

20 July 2026

AREAS RECORDED

15



1 Where the property stands

A published AssetProof sample. A real, complete record with every identifying detail removed — no address, no owner or agent name, no contact details, and no image showing a street frontage, a neighbouring property or a vehicle registration.

The owner's and managing agent's report on the property. It says what has been recorded, what condition the property is in, what has to be done before a tenant moves in, what that costs, and what remains unknown. It is written to be acted on rather than filed.

2 At a glance

358

ITEMS ON THE
REGISTER

230

CONDITION FINDINGS

13

NEEDING ACTION FIRST

R1.46m

CONTENTS
REPLACEMENT

3 The three things to deal with this week

The three things to deal with this week

One — the pool. Severely green with sediment on the submerged steps. It is the first thing any viewer sees from the lounge and it must be cleared before a single photograph is taken. **Two — the exposed cabling at the alarm control box, and the fault light on the panel.** Both are electrical, both are quick, and a theft claim can turn on whether the alarm was working. **Three — the certificates.** No electrical or gas certificate of compliance is on file, and the gas certificate is a statutory requirement for the Smeg hob installation.

4 Property condition by area

AREA	STATUS	NOTES
Exterior & entrance	ATTENTION	Dark damp-like staining and moss/algae discolouration on unfinished concrete wall section; Patchy/thin lawn areas
Pool courtyard	ATTENTION	Pool water appears green/algae-affected, not clear; Pool water green/algae-tinted (visible in background)
Outdoor courtyard & braai	FAIR	Patchy/thin grass in lawn area; Weathered, discoloured/algae-stained wood on the step edging below the deck
Garage	FAIR	Crack/joint line across concrete floor near garage door threshold; Weathered/stained driveway paving
Laundry / utility & storage	ATTENTION	Exposed orange and black cabling around the alarm control box, not fully enclosed; Scattered small dark speckled marks (possible dirt or mould) on left interior panel
Kitchen	FAIR	Green/dark tarnish or residue build-up around bases of several control knobs on the right side; Wire rack tines appear bent/splayed out of alignment in places

AREA	STATUS	NOTES
Lounge	ATTENTION	Amber warning indicator illuminated on the alarm panel, indicating a fault or an unset zone; Heavy creasing and wrinkling across all leather cushions consistent with distressed-style leather or wear
Dining	GOOD	A round knot-like opening in one floorboard near the centre of the dining floor, possibly an old fixture hole; A visible seam/gap line running across the floorboards
Main bedroom suite	FAIR	One section of the venetian blind slats hangs unevenly/crookedly compared to the rest; Venetian blind slats hang unevenly/crookedly on the lower section of the window
Main en-suite bathroom	FAIR	Visible pale mineral/water staining on the tiled wall behind the basins; Visible seam/joint gap in wooden flooring near shower threshold
Bedroom 2	FAIR	Dark stain/knot mark near the front-left corner of the table top; Mattress has no bedding - fully bare, exposing printed ticking pattern
Second bathroom	GOOD	Cupboard interior appears empty apart from two towels - no visible damage to shelving; Small dark mark/residue spot near the drain area inside the basin
Guest powder room	GOOD	Inspected; no adverse finding recorded.
Additional bedroom – attribution not resolved	FAIR	Hairline seam/crack lines visible in ceiling bulkhead following the angled step pattern; Reflective glare patches to the left bedroom wall – paint sheen variation rather than a defect on the balance of what is visible
Additional bathroom – attribution not resolved	GOOD	Interior surface detail of this fitting not established; listed for closer inspection

5 Works schedule and spend

WORK	PRIORITY	INDICATIVE COST	STATUS
Pool treatment and clearance	HIGH	R4,000 – R9,000	Not started
Locate and inspect the pool plant	HIGH	R0 – R25,000	Not started
Enclose the exposed cabling; electrical certificate of compliance	HIGH	R2,500 – R6,000	Not started
Clear the alarm fault and walk-test every zone	HIGH	R1,500 – R4,000	Not started
Gas certificate of compliance for the hob installation	HIGH	R1,200 – R2,500	Not started
Smoke and carbon-monoxide detection	HIGH	R1,500 – R4,000	Not started
Investigate the damp-like staining on the concrete wall section	HIGH	R2,000 – R15,000	Not started
Replace the dishwasher door seal	MEDIUM	R600 – R1,500	Not started
Grounds: lawn, algae on steps and paving, driveway wash	MEDIUM	R6,000 – R14,000	Not started
Making good and painting the unfinished surfaces	MEDIUM	R5,000 – R12,000	Not started

WORK	PRIORITY	INDICATIVE COST	STATUS
Re-level the venetian blinds in both bedrooms	MEDIUM	R800 – R2,500	Not started
Clean the sectional chaise and outdoor cushions; decide on the leather two-seater	MEDIUM	R3,000 – R26,000	Decision needed
Cosmetic round across the house	LOW	R3,000 – R8,000	Not started
Indicative programme		R32,000 – R130,000	

6 Letting readiness

STEP	STATUS	WHAT IT TAKES
Condition baseline	COMPLETE	Fifteen areas, 118 surfaces and 358 items recorded, with 230 findings and a plate against each
Move-in report	READY TO SIGN	Issued with an acknowledgement block for tenant, agent and landlord
Contents schedule	COMPLETE	Fixtures separated from loose contents so a handover can be signed against it
Compliance certificates	OUTSTANDING	Electrical and gas certificates of compliance are not on file
Safety detection	OUTSTANDING	No smoke or carbon-monoxide detection observed
Pool	NOT USABLE	Must be cleared, re-tested and re-inspected before it is presented as available
Photography	HOLD	Do not photograph for a listing until the pool is clear and the grounds have had a round
Insurance record	PARTIAL	Contents are fully scheduled and valued; insurer, policy number and appliance serial plates are not on file

7 What remains unknown

OPEN MATTER
POOL – water is severely green and algae-affected with sediment on the submerged steps and floor. Treatment is required before any listing photography, viewing or tenancy
Pool pump and filtration equipment were never photographed – a short follow-up record is needed to complete the plant record
Confirm the function of the wall-mounted 'DRUID' control unit
Four images are indistinct or indeterminate and carry no inventory; re-inspect if those areas matter
Room attribution to confirm for one single-bed room, one empty wood-look-tiled room and one indistinct taupe-walled room – the photographs do not establish which bedroom they are
Appliance model and serial plates to be photographed close-up for the insurance record

OPEN MATTER

Insurer name and policy number

Principal owner name behind the managing agent

Geysers, roof and gutter/rainwater-harvesting installation not recorded

Electrical and gas compliance certificates

8 Recommendation

Deal with the seven high-priority items first — they are safety, compliance and presentation, they come to roughly R13,000 to R65,000 on the bands above, and the wide end of that is almost entirely the two unknowns (the pool plant and the damp). Get both inspected in one visit before committing to a budget. Hold the listing photography until the pool is clear and the grounds have had a round; photographs taken now would have to be redone, and a green pool in a listing gallery costs more in lost bookings than the treatment costs to do. Everything in Priority 2 and Priority 3 can run alongside a tenancy, and is already recorded as pre-existing, so it cannot later be charged to a tenant.

9 The evidence behind this report



Plate 019 Small octagonal plunge pool - shell, submerged steps and water



Plate 020 Small octagonal plunge pool - shell, submerged steps and water



Plate 021 Small octagonal plunge pool - shell, submerged steps and water



Plate 022 Small octagonal plunge pool - shell, submerged steps and water



Plate 023 Small octagonal plunge pool - shell, submerged steps and water



Plate 024 Small octagonal plunge pool - shell, submerged steps and water



Plate 025 Small octagonal plunge pool - shell, submerged steps and water



Plate 026 Artificial turf (astroturf) ground covering to the pool courtyard



Plate 027 Artificial turf (astroturf) ground covering to the pool courtyard



Plate 028 Artificial turf (astroturf) ground covering to the pool courtyard



Plate 029 Black wrought-iron lantern wall lights on the courtyard-facing house wall



Plate 030 Black wrought-iron lantern wall lights on the courtyard-facing house wall

Important. This is a photographic condition record made on a single date. It is not a structural, electrical, gas, damp or compliance survey; nothing was opened up, moved or tested, and no comment is offered on anything concealed. Severity is an assessment of the consequence of the observation, not of the cost of putting it right. Where an observation is described as cosmetic or as fair wear, that is an opinion offered to assist the parties and is not a determination of liability between landlord and tenant. AssetProof is not an insurer, loss adjuster, assessor, broker or certified valuer. Indicative cost bands are planning figures at South African rates and are not quotations. Replacement figures are opinions of value, not certified valuations.