



## Multiaxis configuration with 2 power-supplies



Projekt:	Produkt:	I:\Entwicklung\Steuerungen\SMC\SMCTEXTE\SMC_Pollux\Docu\HowToConnec diverse\Howtoconncet.dor	
	SMC-pollux	01.07.09	Page 1 of 3




## Multiaxis configuration with one power-supply



Projekt:	Produkt:	I:\Entwicklung\Steuerungen\SMC\SMCTEXTE\SMC_Pollux\Docu\HowToConnec diverse\Howtoconncet.dor	
	SMC-pollux	01.07.09	Page 2 of 3



## Multiaxis configuration with separated power-supply



Projekt:	Produkt:	I:\Entwicklung\Steuerungen\SMC\SMCTEXTE\SMC_Pollux\Docu\HowToConnect diverse\Howtoconncet.doc	
	SMC-pollux	01.07.09	Page 3 of 3