

Vehicle Ticket Report

Project: Nova-LF65-e40FT

Vehicle Number:

Client: TTC



Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-02-66014506bd2c1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 11:25:58 AM	ROOF	Roof	1- on roadside of the top rad compartment ; insulator missing around coolant pipe.		Remi		Closed	7/12/2024 4:15:48 PM	
LF65-02-6601e2ae6af51	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 11:25:58 AM	ROOF	Roof	2- on the roadside of the top rad compartment, coolant hose bad position too high and Cato clamp contact both hose and pipe.		Remi		Closed	7/12/2024 4:15:49 PM	
LF65-02-660176e8e5881	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 11:25:58 AM	ROOF	Roof	3- rear curbside top fairing damage (sharp edge).		Remi		Closed	7/12/2024 4:15:49 PM	
LF65-02-6601942a32a81	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 11:25:58 AM	ROOF	Roof	4- second curbside top cover, gap not even to fairing.		Remi		Closed	7/12/2024 4:15:50 PM	
LF65-02-66018c559d131	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 11:25:58 AM	ROOF	Roof	5- on second curbside top cover, latch too hard to use.		Remi		Closed	7/12/2024 4:15:50 PM	
LF65-02-66014869e3c01	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 11:25:58 AM	ROOF	Roof	6- on curbside mirror reflector unglued.		Remi		Closed	7/12/2024 4:15:50 PM	
LF65-02-66012a7bc9111	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 11:40:48 AM	ROOF	Roof	7- NCP2 missing on front roadside pantograph cable ground bolts		Remi		Closed	7/12/2024 4:15:51 PM	
LF65-02-6601846cc7e71	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 11:40:48	ROOF	Roof	8- rear roadside top fair contact frame.		Remi		Closed	7/12/2024 4:15:51	

Ticket #	Vehicle	Safety Critial	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
			AM								PM	
LF65-02-66012592302a1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:03:25 PM	EXTERIOR	Exterior	1- Screws not tight enough on both back up light		Remi		Closed	7/12/2024 4:15:51 PM	
LF65-02-66017f8c30941	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:03:25 PM	EXTERIOR	Exterior	2- two screws not tight enough on engine door.		Remi		Closed	7/12/2024 4:15:51 PM	
LF65-02-6601d7d7d4331	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:03:25 PM	EXTERIOR	Exterior	3- front curbside wheel house fender curved, bad installed.		Remi		Closed	7/12/2024 4:15:51 PM	
LF65-02-6601bbc038201	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:03:25 PM	EXTERIOR	Exterior	4- on the curbside engine flap door, please lub. it make noise.		Remi		Closed	7/12/2024 4:15:52 PM	
LF65-02-6601d00df31e1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:28:13 PM	ENGINE	Engine	1- fire suppression pipe contact frame.		Remi		Closed	7/12/2024 4:15:52 PM	
LF65-02-6601caad69ff1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:28:13 PM	ENGINE	Engine	2- roadside ground junction bloc fixation loose.		Remi		Closed	7/12/2024 4:15:52 PM	
LF65-02-6601be7ff2631	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:32:56 PM	INTERIOR	Interior	1- inside Rear EB , cable bad routing on communication line n/c.		Remi		Closed	7/12/2024 4:15:52 PM	
LF65-02-6601e47ce2e71	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:46:37 PM	INTERIOR	Interior	2- inside rear curbside base light compartment, harness contact camera frame.		Remi		Closed	7/12/2024 4:15:52 PM	
LF65-02-6601ef8521331	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:46:37 PM	INTERIOR	Interior	3- repositions all curtains behind base light.		Remi		Closed	7/12/2024 4:15:52 PM	
LF65-02-6601549d38e51	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 12:46:37 PM	INTERIOR	Interior	4- remove spray pain on the first curbside restraints retractor hook.		Remi		Closed	7/12/2024 4:15:52 PM	
LF65-02-66015edb054e1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:13:28 PM	INTERIOR	Interior	5- fist aid kit box scratched.		Remi		Closed	7/12/2024 4:15:53 PM	
LF65-02-66013ce050cf1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:13:28 PM	INTERIOR	Interior	6- driver's central mirror too hard to move + nut move.		Remi		Closed	7/12/2024 4:15:53 PM	
Ticket #	Vehicle	Safety Critial	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-02-6601bec0c9da1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:13:28 PM	INTERIOR	Interior	7- check for a green wire not connected inside curbside destination sign compartment		Remi		Closed		
LF65-02-660153f5a5ab1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:13:28 PM	INTERIOR	Interior	8- under dash compartment, Tyra's missing on tow hook fixation		Remi		Closed		
LF65-02-6601c9bc21981	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:13:28 PM	INTERIOR	Interior	9- driver's seat belt DCP not done		Remi		Closed		
LF65-02-66014faaea321	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:21:37 PM	INTERIOR	Interior	10- driver's seat wrong position not, 93 ml.		Remi		Closed		
LF65-02-6601fcf6102d1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:21:37 PM	INTERIOR	Interior	11- parking brake valve rod contact frame.		Remi		Closed		
LF65-02-66014e9fd18f1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:21:37 PM	INTERIOR	Interior	12- optional diagnostic plug harness not connected		Remi		Closed		
LF65-02-6601dc9c3c41	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 1:30:28 PM	INTERIOR	Interior	13- inside main panel; ; thr three connectors of the three light panel need to be fixed to stop this little rattle.		Remi		Closed		
LF65-02-6601742450041	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:08:11 PM	INTERIOR	Interior	14- driver's barrier window too hard to operate		Remi		Closed		
LF65-02-66016e8ed89e1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:08:11 PM	INTERIOR	Interior	15- driver's seat seems loose or bad assembly because made some noise ?		Remi		Closed		
LF65-02-6601a7139b491	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:08:11 PM	INTERIOR	Interior	16- on drivers partition panel; location legend wrong.		Remi		Closed		
LF65-02-660138d43dcf1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:27:40 PM	FUNCTION	Function	1- rear control ask for maintenance request.		Remi		Closed	7/12/2024 4:15:59 PM	
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-02-6601a4b3e24c1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:27:40 PM	FUNCTION	Function	2- fault code ABS communication error While maintenance test.		Remi		Closed	7/12/2024 4:15:59 PM	
LF65-02-660127ef1ec01	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:27:40 PM	FUNCTION	Function	3- roadside on dash, red emergency cut out switch loose.		Remi		Closed	7/12/2024 4:15:59 PM	
LF65-02-6601400c3c7f1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:27:40 PM	FUNCTION	Function	4- battery code on cluster yellow light.		Remi		Closed	7/12/2024 4:15:59 PM	
LF65-02-660186ba81751	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:27:40 PM	FUNCTION	Function	5- on cluster, auxiliary heater almost always on when A/C mode.		Remi		Closed	7/12/2024 4:15:59 PM	
LF65-02-66013f667e1e1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:39:40 PM	FUNCTION	Function	6- traction motor fault code yellow light on appears on the cluster.		Remi		Closed	7/12/2024 4:15:59 PM	
LF65-02-660178aa2f6c1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:54:36 PM	FUNCTION	Function	7- forced deleting process not working ?		Remi		Closed	7/12/2024 4:16:00 PM	
LF65-02-66013810a71a1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:54:36 PM	INTERIOR	Interior	17- on driver's partition, bolt is missing on floor fixation.		Remi		Closed	7/12/2024 4:16:00 PM	
LF65-02-660165879fe91	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:59:12 PM	UNDERCARRIAGE	UnderCarriage	1- rear central dust pan curved and hard to open because contact frame.		Remi		Closed	7/12/2024 4:16:00 PM	
LF65-02-660179691bc41	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 2:59:12 PM	UNDERCARRIAGE	UnderCarriage	2- rear central dust pan interfere with mud flap, hard to open.		Remi		Closed	7/12/2024 4:16:01 PM	
LF65-02-6601312c14711	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 3:37:57 PM	WATER	Water	No leak.		Remi		Closed	7/12/2024 4:16:01 PM	
LF65-02-66011b5b2a111	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 3:37:57 PM	ROAD TEST	Road Test	1- sound generator too quiet, difficult to hear it.		Remi		Closed	7/12/2024 4:16:01 PM	
LF65-02-6601bb4bb1fc1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 3:56:37 PM	UNDERCARRIAGE	UnderCarriage	3- front roadside air hose kinked.		Remi		Closed	7/12/2024 4:16:01 PM	
LF65-02-660136841bba1	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 3:56:37 PM	UNDERCARRIAGE	UnderCarriage	4- underneath driver's seat air fitting contact harness.		Remi		Closed	7/12/2024 4:16:01 PM	
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-02-6601dad457e41	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 3:56:37 PM	UNDERCARRIAGE	UnderCarriage	5- undercoating missing on front roadside brake chamber.		Remi		Closed	7/12/2024 4:16:01 PM	
LF65-02-660127d518b01	LF65-02-6601 / 2NVYL82M6R3754391	No	6/27/2024 3:56:37 PM	INTERIOR	Interior	18- fixation support wrong position inside top roadside driver's compartment. Injuries warning (sharp edge)		Remi		Closed	7/12/2024 4:16:01 PM	
LF65-02-6601afd910a71	LF65-02-6601 / 2NVYL82M6R3754391	No	7/10/2024 5:28:07 PM	EXTERIOR	Exterior	5- one sticker is missing on top of door #4		Remi		Closed	7/12/2024 4:16:02 PM	
LF65-02-6601ceb84a961	LF65-02-6601 / 2NVYL82M6R3754391	No	7/10/2024 5:28:07 PM	INTERIOR	Interior	19- two stickers missing on door #4		Remi		Closed	7/12/2024 4:16:02 PM	
LF65-02-66014f18b25e1	LF65-02-6601 / 2NVYL82M6R3754391	No	7/10/2024 5:28:07 PM	WATER	Water	Did another water test to check rear door after changing		Remi		Closed	7/12/2024 4:16:02 PM	
LF65-02-6601784deb371	LF65-02-6601 / 2NVYL82M6R3754391	No	7/10/2024 5:28:07 PM	FUNCTION	Function	8- battery yellow light on on Parker screen.		Remi		Closed	7/12/2024 4:16:02 PM	
LF65-02-66011e8d8ab81	LF65-02-6601 / 2NVYL82M6R3754391	No	7/10/2024 5:28:07 PM	EXTERIOR	Exterior	6- door #4 cratched need paint.		Remi		Closed	7/12/2024 4:16:02 PM	
LF65-02-66012b2ad3311	LF65-02-6601 / 2NVYL82M6R3754391	No	7/10/2024 5:28:07 PM	INTERIOR	Interior	20- first curbside yellow stanchon scratched.		Remi		Closed	7/12/2024 4:16:02 PM	
LF65-01-6600-6D358DE2	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#74 c/s base light #1 , harness to secured and tie rap to fix		Stephane		Closed	9/27/2025 2:47:16 PM	All done
LF65-01-6600-8BAB9200	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#68 c/s base light #3, bracket to fix		Stephane		Closed	9/27/2025 2:47:17 PM	All done
LF65-01-6600-6608C932	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#62 ceiling RF5, stain to clean		Stephane		Closed	9/27/2025 2:47:17 PM	All done
LF65-01-6600-03FEAD14	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#22 r/s in front the rear doors, the USB port block is loose		Stephane		Closed	9/27/2025 2:47:17 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-AC6B70EC	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#30 r/s first yellow stanchion to clean at the next stop button		Stephane		Closed	9/27/2025 2:47:17 PM	All done
LF65-01-6600-AAF54CCC	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#41 rear doors, torque seal missing at the bottom of #3 and #4 posts		Stephane		Closed	9/27/2025 2:47:17 PM	All done
LF65-01-6600-68DCF6E9	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#24 r/s and c/s at the middle two windows have bad installation of the frame		Stephane		Closed	9/27/2025 2:47:17 PM	All done
LF65-01-6600-8C418A0F	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#48 rear doors, two rods are not properly installed to grease it		Stephane		Closed	9/27/2025 2:47:18 PM	All done
LF65-01-6600-070F2E03	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#58 c/s 5th base light, ballast harness not properly installed		Stephane		Closed	9/27/2025 2:47:18 PM	All done
LF65-01-6600-43C4500C	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#34 r/s second flip up seat, yellow button is hard to operate and the seat stay clipped		Stephane		Closed	9/27/2025 2:47:18 PM	All done
LF65-01-6600-73FA4FC6	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#12 c/s rear part, lock screw not supposed to be there at the 4th window		Stephane		Closed	9/27/2025 2:47:18 PM	All done
LF65-01-6600-BAC19242	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:34 PM	INTERIOR	Interior	#64 r/s base light #3 and #4, many tie rap to cut		Stephane		Closed	9/27/2025 2:47:18 PM	All done
LF65-01-6600-B73BF8AF	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#9 rear part ceiling, chevron sticker not installed as usual		Stephane		Closed	9/27/2025 2:47:18 PM	All done
LF65-01-6600-535874BA	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#19 r/s rear part, stain to clean at the wall		Stephane		Closed	9/27/2025 2:47:18 PM	All done
LF65-01-6600-B8CA83D7	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#67 c/s base light #3, lots of harness to secured		Stephane		Closed	9/27/2025 2:47:19 PM	All done
LF65-01-6600-6AFB3E67	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35	INTERIOR	Interior	#20 c/s and r/s rear part, last yellow stanchion are		Stephane		Closed	9/27/2025 2:47:19	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
			PM			loose at the top					PM	
LF65-01-6600-B38FD33F	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#70 ceiling RF3 , tie rap to cut		Stephane		Closed	9/27/2025 2:47:19 PM	All done
LF65-01-6600-1DA85249	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#65 ceiling RF4, lot of harness to secured and attached in the panel		Stephane		Closed	9/27/2025 2:47:19 PM	All done
LF65-01-6600-034EDCF5	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#13 c/s and r/s rear part 2-seaters bench, harness not secured under the seats		Stephane		Closed	9/27/2025 2:47:19 PM	All done
LF65-01-6600-7CDF62D4	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#61 rear part 5-seaters bench, all seats are not the color as usual		Stephane		Closed	9/27/2025 2:47:19 PM	All done
LF65-01-6600-78BC4AAC	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#2 IB box, network connection too kinked		Stephane		Closed	9/27/2025 2:47:20 PM	All done
LF65-01-6600-907264E7	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#23 r/s front wheel arch, bad finish on yellow hand rail		Stephane		Closed	9/27/2025 2:47:20 PM	All done
LF65-01-6600-6D1EB963	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#11 c/s rear part cord bell box, wires are not secured and not connected properly		Stephane		Closed	9/27/2025 2:47:20 PM	All done
LF65-01-6600-8AAC71D4	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#28 c/s second flip up seat, stopper to adjust		Stephane		Closed	9/27/2025 2:47:20 PM	All done
LF65-01-6600-02243491	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#45 rear doors, harness to secured over door #4		Stephane		Closed	9/27/2025 2:47:20 PM	All done
LF65-01-6600-BB4264A6	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#52 rear doors, motor strap not enough tight		Stephane		Closed	9/27/2025 2:47:20 PM	All done
LF65-01-6600-3B96C886	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#66 ceiling RF4, camera mount is loose		Stephane		Closed	9/27/2025 2:47:20 PM	All done
LF65-01-6600-AAEE7329	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#39 first aid kit box to clean inside		Stephane		Closed	9/27/2025 2:47:21 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-93F31A79	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#8 rear part, many seats are scratched		Stephane		Closed	9/27/2025 2:47:22 PM	All done
LF65-01-6600-ACF185C1	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#18 r/s rear part, white light at the step not tight enough		Stephane		Closed	9/27/2025 2:47:22 PM	All done
LF65-01-6600-80FB44BA	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#33 r/s second flip up seat, black bushing missing at the bottom		Stephane		Closed	9/27/2025 2:47:22 PM	All done
LF65-01-6600-D3628864	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#72 r/s base light #2, duct to fix with tape		Stephane		Closed	9/27/2025 2:47:22 PM	All done
LF65-01-6600-3A5AB892	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#63 r/s base light #5 connector to secured		Stephane		Closed	9/27/2025 2:47:22 PM	All done
LF65-01-6600-FAE002C2	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#73 c/s base light # 2 harness to secured		Stephane		Closed	9/27/2025 2:47:22 PM	All done
LF65-01-6600-52EA3A04	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#17 rear doors, yellow stanchion not as usual		Stephane		Closed	9/27/2025 2:47:23 PM	All done
LF65-01-6600-3B74C1E7	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#35 r/s first 2-seater bench bad finish		Stephane		Closed	9/27/2025 2:47:23 PM	All done
LF65-01-6600-C1FDA988	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#57 c/s 5th base light, harness to secured		Stephane		Closed	9/27/2025 2:47:23 PM	All done
LF65-01-6600-9E3658BB	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#21 r/s and c/s, all screws of fixation bells cords are loose		Stephane		Closed	9/27/2025 2:47:23 PM	All done
LF65-01-6600-F1D53787	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#53 rear doors #3 yellow demand button, seal is outside		Stephane		Closed	9/27/2025 2:47:23 PM	All done
LF65-01-6600-53CB9798	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#6 rear part 5-seaters bench, the seats are scratched		Stephane		Closed	9/27/2025 2:47:23 PM	All done
LF65-01-6600-A827FB19	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#26 c/s first and second flip up seat, stain to clean on all seats		Stephane		Closed	9/27/2025 2:47:23 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-39840513	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#47 rear doors, harness contact with the bracket over the door #3		Stephane		Closed	9/27/2025 2:47:24 PM	All done
LF65-01-6600-F1140AF7	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#42 rear doors, tension to adjust		Stephane		Closed	9/27/2025 2:47:24 PM	All done
LF65-01-6600-4E5C10C0	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#75 c/s base light #1, insulation to fix		Stephane		Closed	9/27/2025 2:47:24 PM	All done
LF65-01-6600-B665ADAD	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#60 rear part 5-seater bench, black stoppers missing under the seats		Stephane		Closed	9/27/2025 2:47:24 PM	All done
LF65-01-6600-A1B09D01	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#71 r/s base light #2, harness to secured		Stephane		Closed	9/27/2025 2:47:24 PM	All done
LF65-01-6600-1C6F70D8	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#25 c/s next to rear door, USB port not properly installed to read it		Stephane		Closed	9/27/2025 2:47:24 PM	All done
LF65-01-6600-859A7165	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#69 r/s 5th window, supposed to be the sticker "please move back "		Stephane		Closed	9/27/2025 2:47:25 PM	All done
LF65-01-6600-65FCCD75	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#4 IB box, sticker at the wall is peeling		Stephane		Closed	9/27/2025 2:47:25 PM	All done
LF65-01-6600-DF29D42D	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#31 r/s between the flip up seat, the arms are squeaking and too hard to move		Stephane		Closed	9/27/2025 2:47:25 PM	All done
LF65-01-6600-D66C6BE5	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#38 first aid kit bad finish on white box		Stephane		Closed	9/27/2025 2:47:25 PM	All done
LF65-01-6600-5552F3B2	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#76 c/s base light #1, harness contact with the structure at two places		Stephane		Closed	9/27/2025 2:47:25 PM	All done
LF65-01-6600-329CACD2	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#27 c/s first flip up seat too high		Stephane		Closed	9/27/2025 2:47:25 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-D88D8063	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#15 c/s and r/s modesties panels, both glasses are not centered		Stephane		Closed	9/27/2025 2:47:25 PM	All done
LF65-01-6600-1E5F785F	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#43 rear doors harness loose at the middle and contact with the sliding guide		Stephane		Closed	9/27/2025 2:47:26 PM	All done
LF65-01-6600-142348C1	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#59 c/s 5th base light, air hose not properly installed		Stephane		Closed	9/27/2025 2:47:26 PM	All done
LF65-01-6600-0BC92B0F	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#44 rear doors, connectors and harness to secured at the middle		Stephane		Closed	9/27/2025 2:47:26 PM	All done
LF65-01-6600-C86A7D3D	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#56 c/s 5th base light, duct is loose and disconnected at the end		Stephane		Closed	9/27/2025 2:47:26 PM	All done
LF65-01-6600-C6D76BBC	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#29 c/s at the second position disabled chair, holes are present at the floor		Stephane		Closed	9/27/2025 2:47:26 PM	All done
LF65-01-6600-B6F4CD8A	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#1 IB box, somes harness to secured		Stephane		Closed	9/27/2025 2:47:53 PM	All done
LF65-01-6600-4992CD01	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:35 PM	INTERIOR	Interior	#5 IB box, black paint missing at the wall		Stephane		Closed	9/27/2025 2:47:54 PM	All done
LF65-01-6600-4C057424	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#16 r/s in front the rear doors, 2-seaters bench are too near the modesty panel		Stephane		Closed	9/27/2025 2:47:54 PM	All done
LF65-01-6600-1E949C6E	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#50 rear doors, connectors contact with green air hose over the door #4		Stephane		Closed	9/27/2025 2:47:54 PM	All done
LF65-01-6600-BD547477	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#54 rear doors compartment, harness contact with the duct some places		Stephane		Closed	9/27/2025 2:47:54 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-A5E783D3	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#37 first aid kit box, two belts and two straps are missing		Stephane		Closed	9/27/2025 2:47:54 PM	All done
LF65-01-6600-1FE3C3B1	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#51 rear doors compartment, drain too kinked over the door #3		Stephane		Closed	9/27/2025 2:47:55 PM	All done
LF65-01-6600-C670FFD1	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#49 rear doors, harness to secured at the wall over door #3		Stephane		Closed	9/27/2025 2:47:55 PM	All done
LF65-01-6600-C32FB835	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#46 rear doors, harness contact with the structure		Stephane		Closed	9/27/2025 2:47:55 PM	All done
LF65-01-6600-261BF834	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#14 rear part, USB ports not installed properly to read it		Stephane		Closed	9/27/2025 2:47:55 PM	All done
LF65-01-6600-4D3DE6BD	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#40 rear doors, black capping #4 is damaged		Stephane		Closed	9/27/2025 2:47:55 PM	All done
LF65-01-6600-AAC393F8	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#7 IB box, cap ends network connector missing		Stephane		Closed	9/27/2025 2:47:55 PM	All done
LF65-01-6600-4488DBCE	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#32 c/s second flip up seat, black bushing missing at the front part		Stephane		Closed	9/27/2025 2:47:56 PM	All done
LF65-01-6600-1F5D7F00	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#3 IB box, connector and harness not secured		Stephane		Closed	9/27/2025 2:47:56 PM	All done
LF65-01-6600-D6226E89	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#10 c/s rear part 2-seater bench, screw not tighten on backrest		Stephane		Closed	9/27/2025 2:47:56 PM	All done
LF65-01-6600-CE816CC9	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#36 r/s front wheel arch, sealant to clean at the bottom		Stephane		Closed	9/27/2025 2:47:56 PM	All done
LF65-01-6600-C4E79401	LF65-01-6600 / 2NVYL82M4R3754390	No	9/4/2025 6:20:36 PM	INTERIOR	Interior	#55 c/s last base light, harness to secured		Stephane		Closed	9/27/2025 2:47:56 PM	All done
LF65-01-6600-F4B24AA2	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#17 torque seal missing on c/s at the support of power train		Stephane		Closed	9/27/2025 2:47:56 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-EA4EE1F8	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#90 driver's backrest, information sticker not as usual		Stephane		Closed	9/27/2025 2:47:56 PM	All done
LF65-01-6600-D543404C	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	FUNCTION	Function	#4 driver's alarm not appearing in the dashboard when deactivated		Stephane		Closed	9/27/2025 2:47:57 PM	All done
LF65-01-6600-516C8836	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#81 ITS panel squeaking when opening		Stephane		Closed	9/27/2025 2:47:57 PM	All done
LF65-01-6600-3C9BA91F	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#12 yellow paint missing at the jacking plates		Stephane		Closed	9/27/2025 2:47:57 PM	All done
LF65-01-6600-F1208EA9	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#82 ITS latches too hard		Stephane		Closed	9/27/2025 2:47:57 PM	All done
LF65-01-6600-F7756174	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#7 r/s oil to clean on the dust pan		Stephane		Closed	9/27/2025 2:47:57 PM	All done
LF65-01-6600-CC564F45	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#104 driver's access door, lock and stopper to adjust		Stephane		Closed	9/27/2025 2:47:57 PM	All done
LF65-01-6600-A7CBB91D	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#78 c/s third window, red handle not on the good side of the window		Stephane		Closed	9/27/2025 2:48:02 PM	All done
LF65-01-6600-C7ACDF55	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#9 r/s bracket air brakes hose not installed as usual		Stephane		Closed	9/27/2025 2:48:02 PM	All done
LF65-01-6600-662E4952	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#112 front doors access panel, sticker warning is missing		Stephane		Closed	9/27/2025 2:48:03 PM	All done
LF65-01-6600-BEC4FC1B	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#3 r/s dust pan fixation is loose		Stephane		Closed	9/27/2025 2:48:03 PM	All done
LF65-01-6600-818DCA65	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#6 gray protection missing on all the fittings on hydraulic pump and steering box		Stephane		Closed	9/27/2025 2:48:03 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-831F9B10	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#18 undercoating missing c/s and r/s of the power train		Stephane		Closed	9/27/2025 2:48:03 PM	All done
LF65-01-6600-42560C90	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#84 c/s driver's mirror is loose and squeaky when adjust		Stephane		Closed	9/27/2025 2:48:03 PM	All done
LF65-01-6600-451FF705	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	FUNCTION	Function	#5 front doors alarm, tension to verify at the doors		Stephane		Closed	9/27/2025 2:48:03 PM	All done
LF65-01-6600-CC11472D	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#16 Oil to clean at the rear power train		Stephane		Closed	9/27/2025 2:48:04 PM	All done
LF65-01-6600-DF8E8FDE	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#11 r/s air hose brakes too kinked near the structure		Stephane		Closed	9/27/2025 2:48:04 PM	All done
LF65-01-6600-2C600197	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#85 front doors, harness to secured		Stephane		Closed	9/27/2025 2:48:04 PM	All done
LF65-01-6600-A080E8B2	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#95 driver's seat to clean		Stephane		Closed	9/27/2025 2:48:04 PM	All done
LF65-01-6600-5B17355D	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#92 driver's brakes pedal, rubber not properly fitted		Stephane		Closed	9/27/2025 2:48:04 PM	All done
LF65-01-6600-1824132A	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#2 undercoating missing at the front tow plates		Stephane		Closed	9/27/2025 2:48:04 PM	All done
LF65-01-6600-47D05107	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#15 presence of rust at rear axle		Stephane		Closed	9/27/2025 2:48:05 PM	All done
LF65-01-6600-D8B0B74E	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#109 front cone camera missing		Stephane		Closed	9/27/2025 2:48:05 PM	All done
LF65-01-6600-45628CDB	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#14 two harness not properly secured at the rear axle		Stephane		Closed	9/27/2025 2:48:05 PM	All done
LF65-01-6600-C53BA493	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#105 under dashboard, module not installed as usual		Stephane		Closed	9/27/2025 2:48:05 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-102F9F92	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#10 front suspension too higher		Stephane		Closed	9/27/2025 2:48:05 PM	All done
LF65-01-6600-92814BFD	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#88 cup holder is loose		Stephane		Closed	9/27/2025 2:48:05 PM	All done
LF65-01-6600-ED6ACCA8	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#8 black hydraulic hose contact with the structure		Stephane		Closed	9/27/2025 2:48:05 PM	All done
LF65-01-6600-3C483EF5	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#21 r/s rear corner, insulation supposed to be slot down		Stephane		Closed	9/27/2025 2:48:06 PM	All done
LF65-01-6600-EAC91E20	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#79 ITS compartment, lots of harness and connectors are not secured		Stephane		Closed	9/27/2025 2:48:06 PM	All done
LF65-01-6600-55C72618	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#91 driver's backrest, screws are not properly fix at the bottom		Stephane		Closed	9/27/2025 2:48:06 PM	All done
LF65-01-6600-DC3363E9	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#108 driver's backrest, 2 stickers are missing		Stephane		Closed	9/27/2025 2:48:06 PM	All done
LF65-01-6600-F643EBD1	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#94 r/s lower panel driver's, connector not connected behind		Stephane		Closed	9/27/2025 2:48:06 PM	All done
LF65-01-6600-EF47DDC6	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#100 ramp compartment, chevron stickers not properly installed		Stephane		Closed	9/27/2025 2:48:06 PM	All done
LF65-01-6600-411A4315	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#80 ITS compartment, harness contact together when panel is closed		Stephane		Closed	9/27/2025 2:48:06 PM	All done
LF65-01-6600-C8FFC020	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#107 driver's seat support not installed as usual		Stephane		Closed	9/27/2025 2:48:07 PM	All done
LF65-01-6600-04824CB8	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	FUNCTION	Function	#6 rear engine control box, maintenance required		Stephane		Closed	9/27/2025 2:48:07 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-44DDF222	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#96 ramp key missing in the gloves compartment		Stephane		Closed	9/27/2025 2:48:07 PM	All done
LF65-01-6600-B9F55A09	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#98 gloves compartment to clean		Stephane		Closed	9/27/2025 2:48:07 PM	All done
LF65-01-6600-D0A00B70	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	FUNCTION	Function	#2 clever devices keyboard doesn't work		Stephane		Closed	9/27/2025 2:48:07 PM	All done
LF65-01-6600-9F3BA2C6	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#86 r/s sun visor hard to operate		Stephane		Closed	9/27/2025 2:48:07 PM	All done
LF65-01-6600-F41FFE0E	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	INTERIOR	Interior	#99 panel ramp access, yellow paint is scratched		Stephane		Closed	9/27/2025 2:48:07 PM	All done
LF65-01-6600-EC7621C7	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#13 undercoating missing under rear doors		Stephane		Closed	9/27/2025 2:48:08 PM	All done
LF65-01-6600-A3E44C6E	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#19 auxiliary heater, valve contact with dust pan		Stephane		Closed	9/27/2025 2:48:08 PM	All done
LF65-01-6600-E809256B	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:44 PM	UNDERCARRIAGE	UnderCarriage	#5 fitting not as usual on the electric pump		Stephane		Closed	9/27/2025 2:48:08 PM	All done
LF65-01-6600-3B86890A	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#103 ramp stopper to adjust		Stephane		Closed	9/27/2025 2:48:08 PM	All done
LF65-01-6600-49FE2154	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	UNDERCARRIAGE	UnderCarriage	#20 torque seal missing at the support of auxiliary unit		Stephane		Closed	9/27/2025 2:48:08 PM	All done
LF65-01-6600-B7AE657B	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	UNDERCARRIAGE	UnderCarriage	#22 c/s rear corner, harness to secured		Stephane		Closed	9/27/2025 2:48:08 PM	All done
LF65-01-6600-524C98BC	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#110 front doors, yellow handrail loose at the bottom screws		Stephane		Closed	9/27/2025 2:48:09 PM	All done
LF65-01-6600-BD0FE993	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#87 driver's window too hard to operate		Stephane		Closed	9/27/2025 2:48:09 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-A5FFBAA1	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#89 driver's wall near window, to clean		Stephane		Closed	9/27/2025 2:48:09 PM	All done
LF65-01-6600-A598FE85	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	UNDERCARRIAGE	UnderCarriage	#4 presence of hydraulic fluid under the electrical pump		Stephane		Closed	9/27/2025 2:48:09 PM	All done
LF65-01-6600-D3C1C58B	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	FUNCTION	Function	#1 hydraulic fluid level to adjust		Stephane		Closed	9/27/2025 2:48:09 PM	All done
LF65-01-6600-OB3184AA	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	UNDERCARRIAGE	UnderCarriage	#1 under front doors, harness to secured		Stephane		Closed	9/27/2025 2:48:09 PM	All done
LF65-01-6600-A1EDBB99	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#77 c/s first bell cord box, wires contact with studs		Stephane		Closed	9/27/2025 2:48:09 PM	All done
LF65-01-6600-A104D73A	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	FUNCTION	Function	#3 batteries 12v light open in dashboard after few time		Stephane		Closed	9/27/2025 2:48:10 PM	All done
LF65-01-6600-3991A0AC	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#111 c/s front wheel arch, belt knock on the structure		Stephane		Closed	9/27/2025 2:48:10 PM	All done
LF65-01-6600-C1945BFB	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#83 driver's central mirror is loose		Stephane		Closed	9/27/2025 2:48:10 PM	All done
LF65-01-6600-8B12B50A	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#101 ramp compartment to clean		Stephane		Closed	9/27/2025 2:48:10 PM	All done
LF65-01-6600-A8CF60EA	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#93 driver's flashers box is loose		Stephane		Closed	9/27/2025 2:48:10 PM	All done
LF65-01-6600-8F631321	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#102 interior ramp compartment is scratched		Stephane		Closed	9/27/2025 2:48:10 PM	All done
LF65-01-6600-E5C8CCD4	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#106 under dashboard, driver's feet heater duct kinked		Stephane		Closed	9/27/2025 2:48:10 PM	All done
LF65-01-6600-3BA96F47	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:05:45 PM	INTERIOR	Interior	#97 popped valve missing in the gloves compartment		Stephane		Closed	9/27/2025 2:48:11 PM	All done
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment

Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
Ticket #	Vehicle	Safety Critical	Created Date	Defect Type	Defect Location	Description	Images	Assign To	Station	Status	Resolved Date	Resolved Comment
LF65-01-6600-3052C1E9	LF65-01-6600 / 2NVYL82M4R3754390	No	9/5/2025 3:08:01 PM	UNDERCARRIAGE	UnderCarriage	#23 r/s over battery #1, orange coolant hose contact with the battery		Stephane		Closed	9/27/2025 2:48:11 PM	All done