

USB4 2.0 ENGINEERING CHANGE NOTICE FORM

Title: Clarification for the Recovery flow in combination with the Enhanced Uni-Directional Time Sync Handshake
Applied to: USB4 Specification Version 2.0

Brief description of the functional changes:

This ECN provides clarification for a recovery flow that occurs during an operation with the Enhanced Uni-Directional Time Sync Handshake described in the specification, without introducing any functional behavior changes.
--

Benefits as a result of the changes:

Clarifies the spec description.

An assessment of the impact to the existing revision and systems that currently conform to the USB specification:
--

NA

An analysis of the hardware implications:
--

NA

An analysis of the software implications:
--

NA

An analysis of the compliance testing implications:
--

NA

USB4 2.0 ENGINEERING CHANGE NOTICE FORM

Actual Change

(a). Section 4.4.7 Gen 4 Link Recovery

To Text:

If Gen 4 Link Recovery was initiated while the TMU was in Inversed Bi-Directional Time Sync mode, restart Inversed Bi-Directional Time Sync handshakes and execute DirSwitchN number of handshakes before transitioning to Adaptive Uni-Directional handshakes.

Note: During the transition to CL0, DFP and UFP may not synchronize perfectly. Consequently, DFP handshakes initiated immediately after entering CL0 could time out if the UFP is still transitioning to CL0.