

USB4 2.0 ENGINEERING CHANGE NOTICE FORM

Title: Debug register (SB Register 6) Debug Capability ID default value is missing

Applied to: USB4 Specification Version 2.0

Brief description of the functional changes:

Debug register (SB Register 6) Debug Capability ID default value is missing. A null default is being added to the Capability ID table

Benefits as a result of the changes:

Spec clarification

An assessment of the impact to the existing revision and systems that currently conform to the USB specification:
--

NA

An analysis of the hardware implications:
--

NA

An analysis of the software implications:
--

NA

An analysis of the compliance testing implications:
--

NA

USB4 2.0 ENGINEERING CHANGE NOTICE FORM

Actual Change

(a). Section 4.4.7 Gen 4 Link Recovery

To Text:

Table 4-24. Debug Register Mapping

Debug Capability ID	Debug Capability Name	Debug Register Bytes 1-63 Mapping
<u>0</u>	<u>None</u>	<u>Reserved</u>
1	Scrambler Re-Sync	See Table 4-25 if ESRS is set to 01b. See Table 4-26 if ESRS is set to 10b.
2-127	Reserved	Reserved
128-255	Vendor Defined	Vendor Defined