

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00002	Policy	POL-60914956
Vehicle	2024 BMW 320i	VIN	JTTSDBYB5FLNDYX7W
Location	Shah Alam	Date	2026-05-07
Weather	Overcast	Road	Urban Road

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Right door, Rear bumper, Tail lamp, Hood. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 23 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 23,921.

Damage Area	Severity	Recommendation
Front bumper	Major	Repair
Hood	Minor	Repair
Left headlamp	Major	Replace
Rear bumper	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.