

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00006	Policy	POL-33480555
Vehicle	2021 Mazda CX-5	VIN	JT08WLMCF2VDGRTPM
Location	Shah Alam	Date	2026-05-01
Weather	Cloudy	Road	Dry Asphalt

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Rear bumper, Right door, Tail lamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 3 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 13 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 20,787.

Damage Area	Severity	Recommendation
Left fender	Minor	Repair
Tail lamp	Moderate	Repair
Front bumper	Minor	Replace
Rear bumper	Major	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.