

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00010	Policy	POL-72887192
Vehicle	2024 Mercedes-Benz GLC	VIN	JTBAT9VJ8D6JRH2FF
Location	Shah Alam	Date	2026-05-17
Weather	Clear	Road	Concrete

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Left fender, Right door, Hood. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 28 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 16,654.

Damage Area	Severity	Recommendation
Tail lamp	Moderate	Inspect
Rear bumper	Major	Inspect
Front bumper	Major	Inspect
Left fender	Minor	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.